

2007 Volvo FM MK2 6x4 Service Lube Truck ST03



Make	Volvo		Model	FM Service Truck		
Year		Hours		As at		
Mileage	250471		km	As at	29/08/2017	
Serial/VIN				Engine Serial		
Details	<p>2007 Volvo FM MK2 6x4 Service Lube Truck asset # ST03. Set up with G&G Fabrication service and lube body with Airman PDS185S compressor showing 1,965 hours, access steps and handrails, bull bar, chassis mounted REA FOPS canopy fitted 2011 and last inspected 6/2016. Last record in daily check log book 29/8/2017 at 250,471 kms and meter shows 6,837 hours while it is running to drive on to buyers transport. Sold un registered with registration plate removed. Buyers should review the site provided condition report to see details of the rust and driveline components as per the GES Equipment Report. This asset is offered for sale via Online Auction on an "As Is Where Is" basis ex Site Boddington Gold Mine, Western Australia.</p>					
Asking price	AUD	Under review - call for pricing				
Ex site	Australia, Western Australia, Boddington					

Service history

Last record in daily check log book 29/8/2017 at 250,471 kms and likely this unit has not been in service for more than 18 months

**For further details, to make an offer or book an inspection, contact
Global Equipment Solutions on Office: 08 9201 1142**













Carried out Servicability Audit B-ST03

Faults:

Airbag fault
Steering wheel buttons worn off
Steering wheel module electrical fault
Seat belt pretensioner electrical loop fault
A/C evaporator temp sensor fault
Main spotlights not working
Driver's door bent at check strap (requires door)
Front bull bar bent forwards
L/H front mudguard assy bent down
Mudguard rubber ripped
Driver's door step damaged & plastic surround
Driver's door trim broken
Module tool box door's corroded
Module frame corroded
Air tank bracket bent
Battery cover cracked
Air leaks (various)
All front cross members & cab support corroded to excess
Cab to engine harness requires attention
Top of chasis rail corroded
Module to chasis rubber strips missing in places
Gearbox retarder not working
Cracked chasis at rear
Chasis to module bracket support cracked
Module steps corroded to excess
Module rear back bar bent
Hose reel slide door missing
Diesel hose reel hose needs replacing
Driver's side of module has dent & crack in wheel guard
Driver's mudguard flap missing
Driver's cab door rubber split/broken
Waste oil suction not working
Passenger door (wheel mirror missing)
Front cab shock leaking
Cover missing off driver's mirror bracket
Hose reel (air) regulator broken
Water tank tap missing
Battery tray corroded through
3 way water valve lever seized
Fuel tank bracket clamp bent
Coolant hose reel will not retract
Rock oil hose reel will not retract
Various switches missing surrounds in cab

2 way speaker not attched (bracket gone)
Transmission retarder fault