

2013 Specialised Vehicle Solutions WR100 Charge Up Machine VCU4029



Make	SVS Specialised Vehicle Solutions		Model	WR100 Charge Up Machine	
Year	2013	Hours		As at	01/09/2019
Mileage			km	As at	01/09/2019
Serial/VIN	104		Engine Serial		
Details	<p>2013 Specialised Vehicle Solutions WR100 Charge Up Machine asset # VCU4029. Sale includes spare parts as noted in photos placed on machine that appear unused. This machine is based off the Caterpillar 525C log skidder with front chassis serial number CAT0525CA52501598 built after 2007. This SVS WR100 Charge up Truck was parked up in June 2019 and the work orders report can be found in the GES Equipment Report PDF on the auction page for this asset. This unit is being offered for sale via online auction and is sold on an "As Is" basis running to drive on to buyers transport ex Tanami Mine site, Northern Territory.</p>				
Asking price	AUD	Under review - call for pricing			
Ex site	Australia, Northern Territory, Tanami				

Service	Site maintenance team confirmed this unit was Running at time of decom.
----------------	---

history

**For further details, to make an offer or book an inspection, contact
Global Equipment Solutions on Office: 08 9201 1142**













Code	Date	Asset ID	Description	
40LH	30/08/2019	7:30:00 2060-10-20-02-VCU4029	MN 21397497 C/O Both Brake accumulators	
40LH	30/07/2019	7:30:00 2060-10-20-02-VCU4029	SG 11891649 12M NDT Crack Testing	
40LH	25/06/2019	7:30:00 2060-10-20-02-VCU4029	SG 12097113 1W Inspect SVS 525C VCU4029	
40LH	24/06/2019	7:30:00 2060-10-20-02-VCU4029	MN 21468056 Decommission	Y19W26
40LH	18/06/2019	7:30:00 2060-10-20-02-VCU4029	SG 12091212 1W Inspect SVS 525C VCU4029	
40LH	11/06/2019	7:30:00 2060-10-20-02-VCU4029	SG 12085309 1W Inspect SVS 525C VCU4029	
40LH	6/06/2019	7:30:00 2060-10-20-02-VCU4029	SG 12077791 1W Inspect SVS 525C VCU4029	
40LH	28/05/2019	7:30:00 2060-10-20-02-VCU4029	SG 12071246 1W Inspect SVS 525C VCU4029	Y19W22
40LH	25/05/2019	7:30:00 2060-10-20-02-VCU4029	SG 12065612 1W Inspect SVS 525C VCU4029	Y19W21
40LH	20/05/2019	7:30:00 2060-10-20-02-VCU4029-OPCB-ECSY	MI 21494283 No throttle Responce	
40LH	18/05/2019	19:30:00 2060-10-20-02-VCU4029	SG 12059758 1W Inspect SVS 525C VCU4029	Y19W20
40LH	7/05/2019	7:30:00 2060-10-20-02-VCU4029	SG 12052618 1W Inspect SVS 525C VCU4029	Y19W19
40LH	30/04/2019	19:30:00 2060-10-20-02-VCU4029	SG 12035002 250H Mech Svce Chargeup SVS 525C	Y19W18
40LH	30/04/2019	19:30:00 2060-10-20-02-VCU4029	SG 12046575 1W Inspect SVS 525C VCU4029	
40LH	23/04/2019	7:30:00 2060-10-20-02-VCU4029	SG 12040154 1W Inspect SVS 525C VCU4029	Y19W17
40LH	17/04/2019	7:30:00 2060-10-20-02-VCU4029-OPCB-ECSY	MI 21471150 C/O Faulty Batteries	
40LH	16/04/2019	7:30:00 2060-10-20-02-VCU4029	SG 12034095 1W Inspect SVS 525C VCU4029	Y19W16
40LH	9/04/2019	7:30:00 2060-10-20-02-VCU4029	SG 12027995 1W Inspect SVS 525C VCU4029	Y19W15
40LH	4/04/2019	7:30:00 2060-10-20-02-VCU4029	SG 12021467 1W Inspect SVS 525C VCU4029	Y19W14
40LH	1/04/2019	7:30:00 2060-10-20-02-VCU4029	MI 21458884 Repair start fault	
40LH	26/03/2019	7:30:00 2060-10-20-02-VCU4029	SG 12015300 1W Inspect SVS 525C VCU4029	Y19W13
40LH	19/03/2019	7:30:00 2060-10-20-02-VCU4029	SG 12008977 1W Inspect SVS 525C VCU4029	Y19W12
40LH	12/03/2019	7:30:00 2060-10-20-02-VCU4029	SG 12002746 1W Inspect SVS 525C VCU4029	Y19W11
40LH	12/03/2019	7:30:00 2060-10-20-02-VCU4029	MN 21389311 C/O Seat	Y19W11
40LH	5/03/2019	7:30:00 2060-10-20-02-VCU4029	SG 11996591 1W Inspect SVS 525C VCU4029	Y19W10
40LH	26/02/2019	7:30:00 2060-10-20-02-VCU4029	SG 11990250 1W Inspect SVS 525C VCU4029	Y19W09
40LH	19/02/2019	7:30:00 2060-10-20-02-VCU4029	SG 11984321 1W Inspect SVS 525C VCU4029	Y19W08
40LH	12/02/2019	7:30:00 2060-10-20-02-VCU4029-DRTR-AXA1-TYW2	MI 21424487 C/O Pos 2 Flat Tyre	
40LH	11/02/2019	19:30:00 2060-10-20-02-VCU4029	SG 11976354 1W Inspect SVS 525C VCU4029	Y19W07
40LH	11/02/2019	19:30:00 2060-10-20-02-VCU4029	MN 21389301 repair lh a/c blower box	Y19W14
40LH	5/02/2019	19:30:00 2060-10-20-02-VCU4029	SG 11971168 1W Inspect SVS 525C VCU4029	Y19W06
40LH	29/01/2019	7:30:00 2060-10-20-02-VCU4029	SG 11961570 1W Inspect SVS 525C VCU4029	
40LH	29/01/2019	7:30:00 2060-10-20-02-VCU4029	SG 11962220 500H Mech Svce Chargeup SVS 525C	Y19W05
40LH	22/01/2019	7:30:00 2060-10-20-02-VCU4029	SG 11957522 1W Inspect SVS 525C VCU4029	Y19W04
40LH	21/01/2019	7:30:00 2060-10-20-02-VCU4029-OPCB-ECSY	MI 21409052 Fix radio bracket Charge Cart 4029	
40LH	15/01/2019	7:30:00 2060-10-20-02-VCU4029	SG 11950884 1W Inspect SVS 525C VCU4029	Y19W03
40LH	8/01/2019	7:30:00 2060-10-20-02-VCU4029	SG 11946720 1W Inspect SVS 525C VCU4029	Y19W02
40LH	6/01/2019	7:30:00 2060-10-20-02-VCU4029-FSSY-ECSY	MI 21399013 Not starting battery flat	
20EL-TAD	4/01/2019	6:30:00 2060-10-20-02-VCU4029	MI 21398149 Basket control fault	
40LH	4/01/2019	7:30:00 2060-10-20-02-VCU4029-OPCB-ECSY	MI 21398018 Repair Orica emulsion electrical fault	
40LH	2/01/2019	19:30:00 2060-10-20-02-VCU4029	SG 11938059 1W Inspect SVS 525C VCU4029	Y19W01
40LH	25/12/2018	7:30:00 2060-10-20-02-VCU4029	SG 11934993 1W Inspect SVS 525C VCU4029	Y18W52
40LH	23/12/2018	7:30:00 2060-10-20-02-VCU4029-DRTR-AXA2-TYW3	MI 21391964 VCU4029 C/O P2 tyre	
40LH	18/12/2018	7:30:00 2060-10-20-02-VCU4029	SG 11926834 1W Inspect SVS 525C VCU4029	Y18W51
40LH	11/12/2018	7:30:00 2060-10-20-02-VCU4029	SG 11920977 1W Inspect SVS 525C VCU4029	Y18W50
40LH	4/12/2018	7:30:00 2060-10-20-02-VCU4029	SG 11915453 1W Inspect SVS 525C VCU4029	Y18W49
40LH	28/11/2018	7:30:00 2060-10-20-02-VCU4029-OPCB	MI 21374610 Repair AFFF Leak	
40LH	27/11/2018	7:30:00 2060-10-20-02-VCU4029	SG 11909571 1W Inspect SVS 525C VCU4029	Y18W48
40LH	27/11/2018	7:30:00 2060-10-20-02-VCU4029	MN 21342934 Fuel sender U/S	Y18W48
40LH	24/11/2018	19:30:00 2060-10-20-02-VCU4029	SG 11883105 250H Mech Svce Chargeup SVS 525C	Y18W47
40LH	20/11/2018	7:30:00 2060-10-20-02-VCU4029	SG 11903536 1W Inspect SVS 525C VCU4029	
40LH	13/11/2018	7:30:00 2060-10-20-02-VCU4029	SG 11897634 1W Inspect SVS 525C VCU4029	Y18W46
40LH	13/11/2018	7:30:00 2060-10-20-02-VCU4029-IMAT-BOOM	MI 21365201 C/O Boom Extension Pin On Adaptor	
40LH	6/11/2018	7:30:00 2060-10-20-02-VCU4029	SG 11891570 1W Inspect SVS 525C VCU4029	Y18W45
40LH	30/10/2018	7:30:00 2060-10-20-02-VCU4029	SG 11885804 1W Inspect SVS 525C VCU4029	Y18W44
40LH	23/10/2018	7:30:00 2060-10-20-02-VCU4029	SG 11879945 1W Inspect SVS 525C VCU4029	Y18W43
40LH	16/10/2018	19:30:00 2060-10-20-02-VCU4029	SG 11873989 1W Inspect SVS 525C VCU4029	Y18W42
40LH	9/10/2018	7:30:00 2060-10-20-02-VCU4029	SG 11868178 1W Inspect SVS 525C VCU4029	Y18W41
40LH	2/10/2018	7:30:00 2060-10-20-02-VCU4029	SG 11862474 1W Inspect SVS 525C VCU4029	Y18W40
40LH	29/09/2018	19:30:00 2060-10-20-02-VCU4029	SG 11856581 1W Inspect SVS 525C VCU4029	Y18W39
40LH	19/09/2018	19:30:00 2060-10-20-02-VCU4029	SG 11850985 1W Inspect SVS 525C VCU4029	Y18W38
40LH-TAI	13/09/2018	7:30:00 2060-10-20-02-VCU4029-HYSY	MI 21323813 Repair Hyds overheating	
40LH	13/09/2018	7:30:00 2060-10-20-02-VCU4029-OPCB	MN 21311691 Replace Damaged Eyewash Station	Y18W37
40LH	12/09/2018	19:30:00 2060-10-20-02-VCU4029	SG 11821830 2000H Mech Svce Chargeup SVS 525C	Y18W37
40LH	11/09/2018	19:30:00 2060-10-20-02-VCU4029	SG 11845172 1W Inspect SVS 525C VCU4029	
40LH	10/09/2018	7:30:00 2060-10-20-02-VCU4029-HYSY	MI 21321425 inspect repair slow boom movements	
40LH	4/09/2018	7:30:00 2060-10-20-02-VCU4029	SG 11838968 1W Inspect SVS 525C VCU4029	Y18W36

40LH	30/08/2018	7:30:00	2060-10-20-02-VCU4029-FRBO-ECSY	MI	21314182	I/R Emergency lowering n/w	
40LH	28/08/2018	7:30:00	2060-10-20-02-VCU4029	SG	11833184	1W Inspect SVS 525C VCU4029	Y18W35
40LH	22/08/2018	19:30:00	2060-10-20-02-VCU4029	SG	11826754	1W Inspect SVS 525C VCU4029	Y18W34
40LH	14/08/2018	7:30:00	2060-10-20-02-VCU4029	SG	11820501	1W Inspect SVS 525C VCU4029	Y18W33
40LH	14/08/2018	7:30:00	2060-10-20-02-VCU4029-IMAT-BOOM	MN	21297230	Change Valve in Boom	Y18W33
40LH	7/08/2018	7:30:00	2060-10-20-02-VCU4029	SG	11814468	1W Inspect SVS 525C VCU4029	Y18W32
40LH	1/08/2018	7:30:00	2060-10-20-02-VCU4029	SG	11808587	1W Inspect SVS 525C VCU4029	Y18W31
40LH	24/07/2018	7:30:00	2060-10-20-02-VCU4029	SG	11802625	1W Inspect SVS 525C VCU4029	Y18W30
40LH	17/07/2018	19:30:00	2060-10-20-02-VCU4029	SG	11796288	1W Inspect SVS 525C VCU4029	Y18W29
40LH	17/07/2018	19:30:00	2060-10-20-02-VCU4029-FRBO-ECSY	MN	21218382	VCU4029 Rpl P3 Jack Leg ProxiI Switch	Y18W29
40LH	13/07/2018	19:30:00	2060-10-20-02-VCU4029	SG	11790263	1W Inspect SVS 525C VCU4029	Y18W28
40LH	13/07/2018	19:30:00	2060-10-20-02-VCU4029-ENSY-IKSY	MN	21255939	C/O air filter housing Lid	Y18W28
20EL	4/07/2018	7:30:00	2060-10-20-02-VCU4029-OPCB-ECSY	MI	21274472	Prox fault CHarge Cart 4029	
40LH	3/07/2018	7:30:00	2060-10-20-02-VCU4029-IMAT-BOOM	MN	21215688	VCU4029 Replace Boom Assy	Y18W27
40LH	2/07/2018	19:30:00	2060-10-20-02-VCU4029	SG	11783639	1W Inspect SVS 525C VCU4029	Y18W27
40LH	27/06/2018	19:30:00	2060-10-20-02-VCU4029	SG	11777730	1W Inspect SVS 525C VCU4029	Y18W26
20EL	20/06/2018	7:30:00	2060-10-20-02-VCU4029-OPCB-ECSY	MI	21265320	Prox fault VCU029	
40LH	19/06/2018	19:30:00	2060-10-20-02-VCU4029	SG	11772689	1W Inspect SVS 525C VCU4029	Y18W25
40LH	12/06/2018	7:30:00	2060-10-20-02-VCU4029	SG	11751724	250H Mech Svce Chargeup SVS 525C	Y18W24
40LH	12/06/2018	7:30:00	2060-10-20-02-VCU4029	SG	11764931	1W Inspect SVS 525C VCU4029	
40LH	6/06/2018	19:30:00	2060-10-20-02-VCU4029-ALSY-HSVV	MN	21071146	re-hose boom *PCR	Y18W14
40LH	5/06/2018	7:30:00	2060-10-20-02-VCU4029	SG	11758594	1W Inspect SVS 525C VCU4029	Y18W23
40LH	5/06/2018	7:30:00	2060-10-20-02-VCU4029-FSSY	SG	11717606	12M Fire Suppression Inspection	Y18W23
40LH	5/06/2018	19:30:00	2060-10-20-02-VCU4029-OPCB-ECSY	MN	21086963	C/O boom basket harness	Y18W23
40LH	4/06/2018	7:30:00	2060-10-20-02-VCU4029-IMAT-BOOM	MI	21254683	Boom Function Fault	
40LH	29/05/2018	7:30:00	2060-10-20-02-VCU4029	SG	11752500	1W Inspect SVS 525C VCU4029	Y18W22
40LH	28/05/2018	7:30:00	2060-10-20-02-VCU4029-HYSY-HYCY	MI	21249149	Inspect boom movement	
40LH	20/05/2018	10:42:33	2060-10-20-02-VCU4029	SG	11745032	1W Inspect SVS 525C VCU4029	Y18W21
40LH	15/05/2018	7:30:00	2060-10-20-02-VCU4029	SG	11738751	1W Inspect SVS 525C VCU4029	Y18W20
40LH-TAI	14/05/2018	7:30:00	2060-10-20-02-VCU4029-HYSY	MI	21240786	VCU4029- Repair P3 Jack legs	
40LH	8/05/2018	19:30:00	2060-10-20-02-VCU4029	SG	11732928	1W Inspect SVS 525C VCU4029	Y18W19
40LH	5/05/2018	8:45:44	2060-10-20-02-VCU4029	SG	11726783	1W Inspect SVS 525C VCU4029	Y18W18
40LH	25/04/2018	19:30:00	2060-10-20-02-VCU4029	SG	11720845	1W Inspect SVS 525C VCU4029	Y18W17
40LH	19/04/2018	7:30:00	2060-10-20-02-VCU4029	SG	11714793	1W Inspect SVS 525C VCU4029	Y18W16
40LH	13/04/2018	7:30:00	2060-10-20-02-VCU4029-IMAT-BOOM	MI	21219253	Boom wont retract	
40LH	12/04/2018	7:30:00	2060-10-20-02-VCU4029	SG	11672871	500H Mech Svce Chargeup SVS 525C	Y18W15
40LH	12/04/2018	7:30:00	2060-10-20-02-VCU4029	MN	21063139	4000Hr PCR	Y18W15
40LH	9/04/2018	7:30:00	2060-10-20-02-VCU4029-OPCB-ECSY	MN	21071214	full a/c and electricl service*PCR	
40LH	8/04/2018	7:30:00	2060-10-20-02-VCU4029-ENSY-EXSY	MN	21189446	Modify exhaust guard to suit DPF probes	Y18W14
40LH	8/04/2018	12:35:51	2060-10-20-02-VCU4029-OPCB	MN	21070765	Replace door latch assy L/H and R/H *PCR	Y18W14
40LH	8/04/2018	12:37:23	2060-10-20-02-VCU4029-ENSY-COSY	MN	21071217	Remove/clean cooler pack*PCR	Y18W14
40LH	7/04/2018	7:30:00	2060-10-20-02-VCU4029-FRBO	MN	21206958	Weld Repairs to Boom	Y18W14
40LH	7/04/2018	7:30:00	2060-10-20-02-VCU4029-IMAT	MN	21070763	inspect/replace carrier/hitch hoses *PCR	Y18W14
40LH	7/04/2018	19:30:00	2060-10-20-02-VCU4029-OPCB-ECSY	MN	21070762	Replace work lights 4000hr pcr	Y18W14
40LH	3/04/2018	7:30:00	2060-10-20-02-VCU4029	SG	11708497	1W Inspect SVS 525C VCU4029	
40LH	27/03/2018	19:30:00	2060-10-20-02-VCU4029	SG	11701705	1W Inspect SVS 525C VCU4029	Y18W13
40LH	20/03/2018	7:30:00	2060-10-20-02-VCU4029	SG	11695621	1W Inspect SVS 525C VCU4029	Y18W12
40LH	18/03/2018	7:30:00	2060-10-20-02-VCU4029	SG	11689365	1W Inspect SVS 525C VCU4029	
40LH	16/03/2018	7:30:00	2060-10-20-02-VCU4029	SG	11706441	1W Inspect SVS 525C VCU4029	Y18W11
40LH	6/03/2018	7:30:00	2060-10-20-02-VCU4029	SG	11682116	1W Inspect SVS 525C VCU4029	Y18W10
40LH	28/02/2018	7:30:00	2060-10-20-02-VCU4029	SG	11576271	12M NDT Crack Testing	Y18W09
40LH	28/02/2018	7:30:00	2060-10-20-02-VCU4029	SG	11676014	1W Inspect SVS 525C VCU4029	Y18W09
40LH	20/02/2018	7:30:00	2060-10-20-02-VCU4029	SG	11670194	1W Inspect SVS 525C VCU4029	Y18W08
40LH	13/02/2018	7:30:00	2060-10-20-02-VCU4029-ENSY	MN	21123943	Replace turbo elbow on next service	Y18W07
40LH	13/02/2018	19:30:00	2060-10-20-02-VCU4029	SG	11664354	1W Inspect SVS 525C VCU4029	Y18W07
40LH	13/02/2018	19:30:00	2060-10-20-02-VCU4029	MN	21094860	C/O Bonnet supports LH and RH	
40LH	5/02/2018	19:30:00	2060-10-20-02-VCU4029	SG	11658235	1W Inspect SVS 525C VCU4029	Y18W06
40LH	1/02/2018	0:00:00	2060-10-20-02-VCU4029-OPCB	MI	21168847	no power to cab	
40LH	31/01/2018	0:00:00	2060-10-20-02-VCU4029	MN	21066320	Additional Tasks 4000H PCR	
40LH	30/01/2018	19:30:00	2060-10-20-02-VCU4029	SG	11652462	1W Inspect SVS 525C VCU4029	Y18W05
40LH	30/01/2018	19:30:00	2060-10-20-02-VCU4029-HYSY-HSVV	MI	21127169	c/o boom ext cyl and transfer pipe	Y18W05
40LH	23/01/2018	19:30:00	2060-10-20-02-VCU4029	SG	11646566	1W Inspect SVS 525C VCU4029	Y18W04
40LH	16/01/2018	19:30:00	2060-10-20-02-VCU4029	SG	11639409	1W Inspect SVS 525C VCU4029	Y18W03
40LH	16/01/2018	19:30:00	2060-10-20-02-VCU4029-FRBO	MI	21120018	c/o pos 3 jack leg switch	Y18W06
40LH	9/01/2018	7:30:00	2060-10-20-02-VCU4029	SG	11633356	1W Inspect SVS 525C VCU4029	Y18W02
40LH	2/01/2018	7:30:00	2060-10-20-02-VCU4029	SG	11592166	250H Mech Svce Chargeup SVS 525C	Y18W01
40LH	29/12/2017	7:30:00	2060-10-20-02-VCU4029-OPCB-ECSY	MI	21146281	Machine Will Not Start/ Machine went to I	
40LH	28/12/2017	7:30:00	2060-10-20-02-VCU4029-IMAT-BOOM-WOPL	MI	21145361	INSPECT BASKET DAMAGE	

40LH	27/12/2017	7:30:00	2060-10-20-02-VCU4029-FRBO	MI	21144604	c/o basket mount	
40LH	26/12/2017	7:30:00	2060-10-20-02-VCU4029	SG	11627323	1W Inspect SVS 525C VCU4029	Y17W52
40LH	24/12/2017	7:30:00	2060-10-20-02-VCU4029	SG	11615518	1W Inspect SVS 525C VCU4029	
40LH	19/12/2017	7:30:00	2060-10-20-02-VCU4029	SG	11621323	1W Inspect SVS 525C VCU4029	Y17W51
40LH	15/12/2017	7:30:00	2060-10-20-02-VCU4029-ALSY-HSVV	MN	21137861	c/o blown hyd hose	
40LH	13/12/2017	7:30:00	2060-10-20-02-VCU4029	SG	11609661	1W Inspect SVS 525C VCU4029	Y17W50
40LH	11/12/2017	7:30:00	2060-10-20-02-VCU4029	SG	11529297	250H Svce Chargeup SVS 525C VCU4029	
40LH	7/12/2017	19:30:00	2060-10-20-02-VCU4029	SG	11603822	1W Inspect SVS 525C VCU4029	Y17W49
40LH	2/12/2017	7:30:00	2060-10-20-02-VCU4029-ENSY-IKSY	MN	21109053	c/o air filter housing assy	
40LH	30/11/2017	7:30:00	2060-10-20-02-VCU4029	SG	11597992	1W Inspect SVS 525C VCU4029	Y17W48
40LH	30/11/2017	7:30:00	2060-10-20-02-VCU4029-FSSY	SG	11451313	6M Fire Suppression Inspection	Y17W48
40LH	27/11/2017	7:30:00	2060-10-20-02-VCU4029-IMAT	MI	21124368	Repair boom extension cyl pin/pipes	
40LH	25/11/2017	7:30:00	2060-10-20-02-VCU4029	SG	11592135	1W Inspect SVS 525C VCU4029	Y17W47
40LH	25/11/2017	7:30:00	2060-10-20-02-VCU4029-OPCB-ECSY	SG	11559887	Insp/Condition Monitor DPF	Y17W47
40LH	18/11/2017	7:30:00	2060-10-20-02-VCU4029	SG	11586271	1W Inspect SVS 525C VCU4029	Y17W46
40LH	18/11/2017	7:30:00	2060-10-20-02-VCU4029-HYSY	MI	21118798	i/r oil leak under cab	
40LH	15/11/2017	7:30:00	2060-10-20-02-VCU4029-ENSY-ECSY	MN	21116880	inspect/repair engine shutting down	
40LH	7/11/2017	7:30:00	2060-10-20-02-VCU4029	SG	11580342	1W Inspect SVS 525C VCU4029	Y17W45
40LH	7/11/2017	7:30:00	2060-10-20-02-VCU4029-DRTR-AXA1-WHR2	MN	21102256	C/O Pos 2 tyre	Y17W45
40LH	7/11/2017	19:30:00	2060-10-20-02-VCU4029-ENSY-EXSY	MN	21021502	c/o exhaust system to ceramic coated	Y17W45
40LH	31/10/2017	7:30:00	2060-10-20-02-VCU4029	SG	11574465	1W Inspect SVS 525C VCU4029	Y17W44
40LH	24/10/2017	7:30:00	2060-10-20-02-VCU4029	SG	11568420	1W Inspect SVS 525C VCU4029	Y17W43
40LH	17/10/2017	7:30:00	2060-10-20-02-VCU4029	SG	11562679	1W Inspect SVS 525C VCU4029	Y17W42
40LH	10/10/2017	7:30:00	2060-10-20-02-VCU4029	SG	11556761	1W Inspect SVS 525C VCU4029	Y17W41
40LH	6/10/2017	7:30:00	2060-10-20-02-VCU4029	SG	11551124	1W Inspect SVS 525C VCU4029	
40LH	6/10/2017	7:30:00	2060-10-20-02-VCU4029-IMAT	MN	21089347	repair pos 4 jack leg pin	
40LH	5/10/2017	7:30:00	2060-10-20-02-VCU4029-HYSY	MN	21088970	top up hyd oil level	
40LH	3/10/2017	7:30:00	2060-10-20-02-VCU4029	SG	11470013	1000H Svce Chargeup SVS 525C VCU4029	Y17W40
40LH	27/09/2017	7:30:00	2060-10-20-02-VCU4029-FRBO-ECSY	MI	21082205	Investigate shutdown/start fault	
40LH	27/09/2017	7:30:00	2060-10-20-02-VCU4029-FSSY-HOSE	MI	21082697	I/R Hyd leak under cab	
40LH	26/09/2017	7:30:00	2060-10-20-02-VCU4029	SG	11545055	1W Inspect SVS 525C VCU4029	Y17W39
40LH	23/09/2017	7:30:00	2060-10-20-02-VCU4029-OPCB-ECSY	SG	11559888	Insp/Condition Monitor DPF	
40LH	23/09/2017	7:30:00	2060-10-20-02-VCU4029-OPCB-ECSY	SG	11559889	Insp/Condition Monitor DPF	
40LH	23/09/2017	7:30:00	2060-10-20-02-VCU4029-OPCB-ECSY	SG	11559890	Insp/Condition Monitor DPF	
40LH	23/09/2017	7:30:00	2060-10-20-02-VCU4029-OPCB-ECSY	SG	11559891	Insp/Condition Monitor DPF	
40LH	19/09/2017	7:30:00	2060-10-20-02-VCU4029	SG	11539443	1W Inspect SVS 525C VCU4029	Y17W38
40LH	17/09/2017	7:30:00	2060-10-20-02-VCU4029	SG	11533379	1W Inspect SVS 525C VCU4029	
40LH	12/09/2017	9:14:00	2060-10-20-02-VCU4029	SG	11515960	1W Inspection SVS 525C VCU4029	Y17W37
40LH	5/09/2017	7:30:00	2060-10-20-02-VCU4029	SG	11527642	1W Inspect SVS 525C VCU4029	Y17W36
40LH	5/09/2017	7:30:00	2060-10-20-02-VCU4029	MN	21063124	Scope 4000Hr PCR Defects	Y17W36
40LH	5/09/2017	7:30:00	2060-10-20-02-VCU4029-FRBO-ECSY	MN	21061334	fit horn to the basket	Y17W36
40LH	31/08/2017	7:30:00	2060-10-20-02-VCU4029-IMAT-BOOM	MN	21063945	Repair leaking boom extension cyl	
40LH	28/08/2017	7:30:00	2060-10-20-02-VCU4029	SG	11521923	1W Inspect SVS 525C VCU4029	Y17W35
40LH	17/08/2017	7:30:00	2060-10-20-02-VCU4029-FRBO-ECSY	MI	21053392	Investigate shutdown fault	
40LH	16/08/2017	19:30:00	2060-10-20-02-VCU4029	SG	11509132	1W Inspection SVS 525C VCU4029	Y17W33
40LH	15/08/2017	7:30:00	2060-10-20-02-VCU4029-ENSY-ECSY	MI	21051765	Repair E stop fault	
40LH	13/08/2017	7:30:00	2060-10-20-02-VCU4029-DRTR-TRAN	MN	21002913	Up-grade park brake system	
40LH	9/08/2017	7:30:00	2060-10-20-02-VCU4029-DRTR-AXA1-TYW2	MN	21047532	Replace P2 Tyre	
40LH	8/08/2017	7:30:00	2060-10-20-02-VCU4029	SG	11503440	1W Inspection SVS 525C VCU4029	Y17W32
40LH	8/08/2017	7:30:00	2060-10-20-02-VCU4029-OPCB	MN	21020712	replace door Latch	Y17W32
40LH	8/08/2017	7:30:00	2060-10-20-02-VCU4029-OPCB-ECSY	MI	21047152	Repair basket lights/Picked up on weekly	
40LH	8/08/2017	19:30:00	2060-10-20-02-VCU4029-IMAT-BOOM	MN	20841740	ADJUST ZOOM TUBE	Y17W32
40LH	8/08/2017	19:30:00	2060-10-20-02-VCU4029-OPCB	MN	21015225	Install additional reverse camera	Y17W32
40LH	4/08/2017	0:00:00	2060-10-20-02-VCU4029-HYSY	MN	21005840	W/O - payment of invoice - control block	
40LH	2/08/2017	0:00:00	2060-10-20-02-VCU4029-DRTR	MI	21043209	C/O flat P tyre	
40LH	1/08/2017	7:30:00	2060-10-20-02-VCU4029	SG	11495673	1W Inspection SVS 525C VCU4029	Y17W31
40LH	26/07/2017	7:30:00	2060-10-20-02-VCU4029-DRTR	MI	21032171	c/o flat tyre	
40LH	25/07/2017	6:30:00	2060-10-20-02-VCU4029-OPCB-ECSY	MI	21037688	repair reverse camera	Y17W30
40LH	25/07/2017	7:30:00	2060-10-20-02-VCU4029	SG	11489210	1W Inspection SVS 525C VCU4029	Y17W30
40LH	23/07/2017	0:00:00	2060-10-20-02-VCU4029-OPCB	MI	21036386	c/o damaged P2 door strutt	
40LH-TAM	19/07/2017	7:30:00	2060-10-20-02-VCU4029-DRTR-AXA2-WHR4	MI	21033642	C/o P4 flat tyre	
40LH	17/07/2017	7:30:00	2060-10-20-02-VCU4029	SG	11483880	1W Inspection SVS 525C VCU4029	Y17W29
40LH	10/07/2017	7:30:00	2060-10-20-02-VCU4029	SG	11477948	1W Inspection SVS 525C VCU4029	Y17W28
40LH	8/07/2017	19:30:00	2060-10-20-02-VCU4029	SG	11472361	1W Inspection SVS 525C VCU4029	Y17W27
40LH	4/07/2017	7:30:00	2060-10-20-02-VCU4029-HYSY-HSVV	MI	21022280	Replaced failed suction hose	
40LH	30/06/2017	7:00:00	2060-10-20-02-VCU4029	SG	11467019	1W Inspection SVS 525C VCU4029	Y17W26
40LH	28/06/2017	7:30:00	2060-10-20-02-VCU4029-DRTR-AXA2-TYW3	MN	21018730	c/o punctured	
40LH	22/06/2017	6:30:00	2060-10-20-02-VCU4029	SG	11461689	1W Inspection SVS 525C VCU4029	NOT REQ

40LH	20/06/2017	3:44:21	2060-10-20-02-VCU4029	SG	11369614	250H PM Service SVS 525C Chargeup	Y17W25
40LH	15/06/2017	7:30:00	2060-10-20-02-VCU4029	SG	11456439	1W Inspection SVS 525C VCU4029	Y17W24
40LH	10/06/2017	7:30:00	2060-10-20-02-VCU4029	SG	11450675	1W Inspection SVS 525C VCU4029	Y17W23
40LH	29/05/2017	7:30:00	2060-10-20-02-VCU4029	SG	11445295	1W Inspection SVS 525C VCU4029	Y17W22
40LH	29/05/2017	7:30:00	2060-10-20-02-VCU4029-FRBO-ECSY	MN	20998844	Relocate reverse camera	Y17W22
40LH	27/05/2017	19:30:00	2060-10-20-02-VCU4029	SG	11439695	1W Inspection SVS 525C VCU4029	Y17W21
40LH	19/05/2017	6:30:00	2060-10-20-02-VCU4029-IMAT	MI	20994145	C/O leaking hyd hose on emulsion unit/	
40LH	19/05/2017	7:30:00	2060-10-20-02-VCU4029	SG	11434612	1W Inspection SVS 525C VCU4029	Y17W20
40LH	19/05/2017	7:30:00	2060-10-20-02-VCU4029-FSSY	SG	11430823	12M Fire Suppression Inspection	Y17W20
40LH	19/05/2017	7:30:00	2060-10-20-02-VCU4029-OPCB-ECSY	MN	20988808	Relocate Reverse cam	Y17W20
40LH	10/05/2017	7:30:00	2060-10-20-02-VCU4029	SG	11187224	12M NDT Crack Testing	Y17W19
40LH	10/05/2017	7:30:00	2060-10-20-02-VCU4029	SG	11283664	12M NDT Crack Testing	Y17W19
40LH	10/05/2017	7:30:00	2060-10-20-02-VCU4029	SG	11429329	1W Inspection SVS 525C VCU4029	Y17W19
40LH	10/05/2017	7:30:00	2060-10-20-02-VCU4029	MN	20928087	C/O FUEL SENDER UNIT U/S	Y17W19
40LH	2/05/2017	7:30:00	2060-10-20-02-VCU4029-ENSY-ECSY	MI	20969856	c/o batteries	
40LH	2/05/2017	7:30:00	2060-10-20-02-VCU4029-HYSY	MI	20970381	I/R oil leak under cab	
40LH	1/05/2017	19:30:00	2060-10-20-02-VCU4029	SG	11424032	1W Inspection SVS 525C VCU4029	Y17W18
40LH	29/04/2017	7:30:00	2060-10-20-02-VCU4029-HYSY-HSVV	MI	20980769	Replace u/s fitting on hyd pump	
40LH	28/04/2017	6:30:00	2060-10-20-02-VCU4029	SG	11413531	1W Inspection SVS 525C VCU4029	
40LH	28/04/2017	7:30:00	2060-10-20-02-VCU4029	SG	11407788	1W Inspection SVS 525C VCU4029	
40LH	27/04/2017	7:30:00	2060-10-20-02-VCU4029	SG	11418715	1W Inspection SVS 525C VCU4029	Y17W17
40LH	18/04/2017	7:30:00	2060-10-20-02-VCU4029	SG	11402553	1W Inspection SVS 525C VCU4029	Y17W16
40LH	17/04/2017	19:30:00	2060-10-20-02-VCU4029	SG	11332424	500H PM Service SVS 525C Chargeup	Y17W16
40LH	8/04/2017	7:30:00	2060-10-20-02-VCU4029-OPCB-ECSY	MN	20967820	inspect/repair reerse camera monitor	
40LH	6/04/2017	7:30:00	2060-10-20-02-VCU4029-ENSY-ECSY	MN	20966310	inspect/repair machine shut down fault	
40LH	31/03/2017	7:30:00	2060-10-20-02-VCU4029	SG	11392115	1W Inspection SVS 525C	
40LH	27/03/2017	0:00:00	2060-10-20-02-VCU4029-FSSY-ECSY	MN	20959428	fit camera	
40LH	25/03/2017	7:30:00	2060-10-20-02-VCU4029	SG	11397376	1W Inspection SVS 525C VCU4029	Y17W12
40LH	22/03/2017	7:30:00	2060-10-20-02-VCU4029-DRTR-TRAN	MN	20890091	Up-grade park brake system	Y17W12
Z4PD	19/03/2017	7:00:00	2060-10-20-02-VCU4029	SG	11386605	1W Inspection SVS 525C	
Z4PD	18/03/2017	7:30:00	2060-10-20-02-VCU4029	SG	11375782	1W Inspection SVS 525C	
Z4PD	16/03/2017	7:00:00	2060-10-20-02-VCU4029	SG	11370507	1W Inspection SVS 525C	
40LH	13/03/2017	7:30:00	2060-10-20-02-VCU4029-IMAT	MN	20914462	Labour Requirements for Emulsion Install	Y17W11
Z4PD	12/03/2017	7:00:00	2060-10-20-02-VCU4029	SG	11381194	1W Inspection SVS 525C	
40LH	8/03/2017	6:30:00	2060-10-20-02-VCU4029-HYSY-HSVV	MN	20926871	C/O PILOT CONTROL VALVE IN BASKET U/S	
Z4PD	6/03/2017	0:00:00	2060-10-20-02-VCU4029-ENSY	MI	20945404	idling too high	
Z4PD	2/03/2017	0:00:00	2060-10-20-02-VCU4029-HYSY-HSVV	MI	20943439	Replace A/Comp Filter	
Z4PD	2/03/2017	7:30:00	2060-10-20-02-VCU4029	SG	11353508	1W Inspection SVS 525C	Y17W09
Z4PD	2/03/2017	7:30:00	2060-10-20-02-VCU4029	SG	11364947	1W Inspection SVS 525C	Y17W09
Z4PD	10/02/2017	7:00:00	2060-10-20-02-VCU4029	SG	11359552	1W Inspection SVS 525C	Y17W06
Z4PD	3/02/2017	7:30:00	2060-10-20-02-VCU4029	SG	11347420	1W Inspection SVS 525C	Y17W05
Z4PD	1/02/2017	7:30:00	2060-10-20-02-VCU4029-OPCB	MN	20862720	i/r u/s fuel gauge	Y17W05
Z4PD	1/02/2017	19:30:00	2060-10-20-02-VCU4029	SG	11341999	1W Inspection SVS 525C	Y17W05
Z4PD	1/02/2017	19:30:00	2060-10-20-02-VCU4029-AISY	MN	20802534	c/o compressor inlet valve assy	Y17W05
Z4PD	24/01/2017	7:30:00	2060-10-20-02-VCU4029-OPCB	MI	20916313	C/O HIGH BEAM DIP SWITCH U/S	Y17W04
20EL	18/01/2017	7:00:00	2060-10-20-02-VCU4029	MI	20916759	Prox fault Charge Cart 4029	
Z4PD	14/01/2017	7:30:00	2060-10-20-02-VCU4029-FRBO-ECSY	MN	20905089	Install Proximity System	Y17W02
Z4PD	13/01/2017	19:30:00	2060-10-20-02-VCU4029	SG	11336631	1W Inspection SVS 525C	Y17W02
Z4PD	13/01/2017	19:30:00	2060-10-20-02-VCU4029-IMAT	MN	20851291	c/o pos 3 jack leg cylinder	Y17W02
20EL	6/01/2017	0:00:00	2060-10-20-02-VCU4029	MI	20909148	PROXIMITY REPAIR	
Z4PD	6/01/2017	19:30:00	2060-10-20-02-VCU4029	SG	11330923	1W Inspection SVS 525C	Y17W01
Z4PD	30/12/2016	7:30:00	2060-10-20-02-VCU4029	SG	11325451	1W Inspection SVS 525C	Y16W52
Z4PD	30/12/2016	7:30:00	2060-10-20-02-VCU4029-OPCB-SEAT	MN	20898705	c/o seat belt	Y16W52
Z4PD	29/12/2016	7:30:00	2060-10-20-02-VCU4029-OPCB-ECSY	MN	20866289	Replace ignition switch	Y16W52
Z4PD	27/12/2016	0:00:00	2060-10-20-02-VCU4029-HYSY	MI	20902562	I/R Hydraulic oil leak under compressor	
Z4PD	19/12/2016	7:30:00	2060-10-20-02-VCU4029	SG	11319665	1W Inspection SVS 525C	Y16W51
Z4PD	12/12/2016	7:30:00	2060-10-20-02-VCU4029	SG	11314208	1W Inspection SVS 525C	Y16W50
Z4PD	8/12/2016	7:30:00	2060-10-20-02-VCU4029	SG	11308765	1W Inspection SVS 525C	Y16W49
Z4PD	28/11/2016	7:30:00	2060-10-20-02-VCU4029	SG	11282096	250H PM Service SVS 525C Chargeup	Y16W48
Z4PD	28/11/2016	19:30:00	2060-10-20-02-VCU4029	SG	11303647	1W Inspection SVS 525C	Y16W48
Z4PD	21/11/2016	19:30:00	2060-10-20-02-VCU4029	SG	11298260	1W Inspection SVS 525C	Y16W47
Z4PD	19/11/2016	19:30:00	2060-10-20-02-VCU4029	SG	11292960	1W Inspection SVS 525C	Y16W46
Z4PD	12/11/2016	6:00:00	2060-10-20-02-VCU4029	SG	11287442	1W Inspection SVS 525C	Y16W45
Z4PD	10/11/2016	7:30:00	2060-10-20-02-VCU4029-HYSY-BRSY	MN	20871647	Parkbrake Not Holding	Y16W45
Z4PD	1/11/2016	7:30:00	2060-10-20-02-VCU4029	SG	11282136	1W Inspection SVS 525C	Y16W44
Z4PD	1/11/2016	7:30:00	2060-10-20-02-VCU4029-FSSY	SG	11289010	6M Fire Suppression Inspection	Y16W44
Z4PD	25/10/2016	19:30:00	2060-10-20-02-VCU4029	SG	11276901	1W Inspection SVS 525C	Y16W43
Z4PD	19/10/2016	19:30:00	2060-10-20-02-VCU4029	SG	11271022	1W Inspection SVS 525C	Y16W42

Z4PD	14/10/2016	19:30:00	2060-10-20-02-VCU4029	SG	11264587	1W Inspection SVS 525C	Y16W41
Z4PD	7/10/2016	19:30:00	2060-10-20-02-VCU4029	SG	11258788	1W Inspection SVS 525C	Y16W40
Z4PD	5/10/2016	6:00:00	2060-10-20-02-VCU4029-IMAT	MI	20851877	Compressor fault/Cutting out/	
Z4PD	2/10/2016	6:00:00	2060-10-20-02-VCU4029	SG	11253481	1W Inspection SVS 525C	Y16W39
Z4PD	29/09/2016	0:00:00	2060-10-20-02-VCU4029-IMAT	MI	20848696	Repair jack leg cylinder on pos 4	
Z4PD	26/09/2016	7:30:00	2060-10-20-02-VCU4029	SG	11108734	2000H PM Service SVS 525C Chargeup	Y16W39
Z4PD	26/09/2016	7:30:00	2060-10-20-02-VCU4029-IMAT	MN	20841814	boily repairs to zoom tube	Y16W39
Z4PD	25/09/2016	6:00:00	2060-10-20-02-VCU4029	SG	11248206	1W Inspection SVS 525C	Y16W38
Z4PD	25/09/2016	6:00:00	2060-10-20-02-VCU4029-OPCB-ECSY	MN	20845937	Repair Secondary Steer Fault	
Z4PD	19/09/2016	7:30:00	2060-10-20-02-VCU4029	SG	11236859	1W Inspection SVS 525C	Y16W38
Z4PD	9/09/2016	6:00:00	2060-10-20-02-VCU4029-HYSY-HSVV	MI	20836359	Hyd oil leak/Leaking hose on rear frame/	
Z4PD	9/09/2016	19:30:00	2060-10-20-02-VCU4029	SG	11231321	1W Inspection SVS 525C	Y16W36
Z4PD	2/09/2016	19:30:00	2060-10-20-02-VCU4029	SG	11226069	1W Inspection SVS 525C	Y16W35
Z4PD	22/08/2016	7:30:00	2060-10-20-02-VCU4029	SG	11220766	1W Inspection SVS 525C	Y16W34
Z4PD	19/08/2016	19:30:00	2060-10-20-02-VCU4029	SG	11215491	1W Inspection SVS 525C	Y16W33
Z4PD	11/08/2016	7:30:00	2060-10-20-02-VCU4029	SG	11210304	1W Inspection SVS 525C	Y16W32
Z4PD	11/08/2016	7:30:00	2060-10-20-02-VCU4029-DRTR-DRLN	MN	20800271	C/O worn centre driveshaft assembly	Y16W32
20EL	8/08/2016	7:00:00	2060-10-20-02-VCU4029	MI	20817141	Configure Prox screen	
Z4PD	6/08/2016	7:30:00	2060-10-20-02-VCU4029-HYSY	MN	20721288	jack leg fault- broken cylinder	Y16W31
Z4PD	5/08/2016	19:30:00	2060-10-20-02-VCU4029	SG	11205182	1W Inspection SVS 525C	Y16W31
Z4PD	5/08/2016	19:30:00	2060-10-20-02-VCU4029-FRBO	MI	20542498	REPLACE steering pins & bushes	Y16W31
Z4PD	31/07/2016	6:00:00	2060-10-20-02-VCU4029	SG	11200089	1W Inspection SVS 525C	
Z4PD	28/07/2016	19:30:00	2060-10-20-02-VCU4029	SG	11069854	250H PM Service SVS 525C Chargeup	Y16W30
Z4PD	22/07/2016	6:00:00	2060-10-20-02-VCU4029-AISY	MN	20799946	investigate compressor fault	Y16W29
Z4PD-TAC	22/07/2016	7:30:00	2060-10-20-02-VCU4029-AISY	MI	20579772	Inspect need for water trap in system	Y16W29
Z4PD	22/07/2016	19:30:00	2060-10-20-02-VCU4029-OPCB-SEAT	MN	20772216	Replace worn seat	Y16W29
Z4PD	21/07/2016	7:30:00	2060-10-20-02-VCU4029	SG	11194888	1W Inspection SVS 525C	Y16W29
Z4PD	21/07/2016	7:30:00	2060-10-20-02-VCU4029-FRBO	MI	20721225	replace P3 jack leg inner tube	
20EL	15/07/2016	6:00:00	2060-10-20-02-VCU4029	MI	20803464	VCU4029 prox fault	
Z4PD	14/07/2016	19:30:00	2060-10-20-02-VCU4029	SG	11189582	1W Inspection SVS 525C	Y16W28
20EL	8/07/2016	7:00:00	2060-10-20-02-VCU4029	MI	20799092	Proximity display screen change out	
Z4PD	7/07/2016	7:30:00	2060-10-20-02-VCU4029	SG	11184116	1W Inspection SVS 525C	Y16W27
Z4PD	1/07/2016	19:30:00	2060-10-20-02-VCU4029	SG	11178228	1W Inspection SVS 525C	Y16W26
Z4PD	1/07/2016	19:30:00	2060-10-20-02-VCU4029-IMAT	MN	20724528	C/Out Air Cleaner Ass	Y16W26
Z4PD	24/06/2016	7:30:00	2060-10-20-02-VCU4029	SG	11173004	1W Inspection SVS 525C	Y16W25
20EL	23/06/2016	6:00:00	2060-10-20-02-VCU4029	SG	11108735	1000H Proximity System Inspection	Y16W21
Z4PD	17/06/2016	19:30:00	2060-10-20-02-VCU4029	SG	11167710	1W Inspection SVS 525C	Y16W24
Z4PD	17/06/2016	19:30:00	2060-10-20-02-VCU4029-HYSY-TVRE	MI	20571622	C/O HYD TANK COVER	Y16W24
Z4PD	10/06/2016	19:30:00	2060-10-20-02-VCU4029	SG	11162379	1W Inspection SVS 525C	Y16W23
Z4PD	3/06/2016	7:30:00	2060-10-20-02-VCU4029	SG	11157103	1W Inspection SVS 525C	Y16W22
20EL	29/05/2016	6:00:00	2060-10-20-02-VCU4029	MI	20775776	Repair radio antenna	
Z4PD	28/05/2016	0:00:00	2060-10-20-02-VCU4029-DRTR-AXA1-TYW2	MI	20775391	C/O POS 2 TYRE	
Z4PD	28/05/2016	0:00:00	2060-10-20-02-VCU4029-ENSY-COSY-RADI	MI	20775606	INSP/REP OVERHEATING FAULT	
Z4PD	28/05/2016	19:30:00	2060-10-20-02-VCU4029	SG	11151492	1W Inspection SVS 525C	Y16W21
Z4PD	24/05/2016	19:30:00	2060-10-20-02-VCU4029-ENSY-COSY	MI	20761760	Overheating when tramming	Y16W21
Z4PD	22/05/2016	6:00:00	2060-10-20-02-VCU4029-IMAT-BOOM	MI	20771649	Boom lift cylinder pin broken/Found on s	
Z4PD	22/05/2016	6:00:00	2060-10-20-02-VCU4029-IMAT-BOOM	MN	20771749	Inspect/Replace broken boom lift pin	Y16W21
Z4PD	20/05/2016	19:30:00	2060-10-20-02-VCU4029	SG	11125612	1W Inspection SVS 525C	Y16W20
Z4PD	13/05/2016	19:30:00	2060-10-20-02-VCU4029	SG	11120415	1W Inspection SVS 525C	Y16W19
Z4PD	11/05/2016	0:00:00	2060-10-20-02-VCU4029-OPCB-ECSY	MI	20765088	repace rev cam system	
Z4PD	10/05/2016	7:00:00	2060-10-20-02-VCU4029-IMAT	MI	20763880	Repair damage to cage and boom	
Z4PD	7/05/2016	6:00:00	2060-10-20-02-VCU4029-ENSY-ECSY	MN	20763017	Electrical Shutdown Fault	
Z4PD	6/05/2016	6:00:00	2060-10-20-02-VCU4029-ENSY-COSY	MN	20762555	inspect cooling system	
Z4PD	6/05/2016	7:30:00	2060-10-20-02-VCU4029	SG	11029992	500H PM Service SVS 525C Chargeup	Y16W18
Z4PD	6/05/2016	7:30:00	2060-10-20-02-VCU4029-FSSY	SG	11098456	12M Fire Suppression Inspection	Y16W18
Z4PD	2/05/2016	7:30:00	2060-10-20-02-VCU4029-OPCB-ECSY	MI	20758968	REPAIR SHUT DOWN FAULT	Y16W18
Z4PD	1/05/2016	6:00:00	2060-10-20-02-VCU4029	SG	11110560	1W Inspection SVS 525C	
Z4PD	28/04/2016	6:00:00	2060-10-20-02-VCU4029	SG	11115319	1W Inspection SVS 525C	Y16W17
Z4PD	26/04/2016	7:00:00	2060-10-20-02-VCU4029-OPCB-ECSY	MI	20726185	Machine will not start	
Z4PD	26/04/2016	19:30:00	2060-10-20-02-VCU4029-ENSY-COSY-RADI	MN	20724526	Remove and clean cooler pack	Y16W17
Z4PD	22/04/2016	19:30:00	2060-10-20-02-VCU4029	SG	11105493	1W Inspection SVS 525C	Y16W16
Z4PD	17/04/2016	19:30:00	2060-10-20-02-VCU4029	SG	11100055	1W Inspection SVS 525C	Y16W15
Z4PD	16/04/2016	0:00:00	2060-10-20-02-VCU4029-HYSY	MI	20720719	jack leg fault- broken cylinder	
Z4PD	14/04/2016	6:00:00	2060-10-20-02-VCU4029-DRTR	MI	20719733	Retorque all wheels	
Z4PD	10/04/2016	0:00:00	2060-10-20-02-VCU4029-IMAT-BOOM-WOPL	MN	20716998	Repair Basket Step	
Z4PD	10/04/2016	6:00:00	2060-10-20-02-VCU4029	SG	11093828	1W Inspection SVS 525C	
Z4PD	10/04/2016	6:00:00	2060-10-20-02-VCU4029-IMAT-VPA1	MI	20717236	P1 kettle actuator fault	
Z4PD	4/04/2016	7:30:00	2060-10-20-02-VCU4029-DRTR-AXA2	MI	20680567	Repair Rear Axle Assembly	Y16W14

Z4PD	3/04/2016	6:00:00	2060-10-20-02-VCU4029	SG	11088704	1W Inspection SVS 525C	
20EL	30/03/2016	6:00:00	2060-10-20-02-VCU4029	MI	20711010	Replace radio antenna	
Z4PD	27/03/2016	6:00:00	2060-10-20-02-VCU4029	SG	11084385	1W Inspection SVS 525C	
Z4PD	20/03/2016	6:00:00	2060-10-20-02-VCU4029	SG	11078417	1W Inspection SVS 525C	
Z4PD	13/03/2016	6:00:00	2060-10-20-02-VCU4029	SG	11068274	1W Inspection SVS 525C	
Z4PD	6/03/2016	6:00:00	2060-10-20-02-VCU4029	SG	11063104	1W Inspection SVS 525C	
Z4PD	28/02/2016	6:00:00	2060-10-20-02-VCU4029	SG	11058116	1W Inspection SVS 525C	Y16W08
Z4PD	21/02/2016	7:30:00	2060-10-20-02-VCU4029	SG	11052662	1W Inspection SVS 525C	
Z4PD	14/02/2016	6:00:00	2060-10-20-02-VCU4029	SG	11047492	1W Inspection SVS 525C	
Z4PD	9/02/2016	0:00:00	2060-10-20-02-VCU4029-DRTR-AXA1	MI	20680098	remove front axle	DBS S6
Z4PD	9/02/2016	7:00:00	2060-10-20-02-VCU4029-IMAT-VPA1	MI	20607028	Fabricate new kettle grates	Y16W04
Z4PD	7/02/2016	6:00:00	2060-10-20-02-VCU4029	SG	11042116	1W Inspection SVS 525C	
Z4PD	29/01/2016	19:30:00	2060-10-20-02-VCU4029	SG	11037075	1W Inspection SVS 525C	Y16W04
Z4PD	25/01/2016	6:00:00	2060-10-20-02-VCU4029-DRTR-AXA2	MI	20672155	Repair rear axle locked up	
Z4PD	22/01/2016	19:30:00	2060-10-20-02-VCU4029	SG	11031988	1W Inspection SVS 525C	Y16W03
Z4PD	15/01/2016	6:00:00	2060-10-20-02-VCU4029-FSSY-ECSY	MN	20667126	C/O BATTERY	DBS S1
Z4PD	15/01/2016	19:30:00	2060-10-20-02-VCU4029	SG	11026365	1W Inspection SVS 525C	Y16W02
Z4PD	8/01/2016	19:30:00	2060-10-20-02-VCU4029	SG	11020981	1W Inspection SVS 525C	Y16W01
Z4PD	8/01/2016	19:30:00	2060-10-20-02-VCU4029-ENSY-IKSY	MI	20555242	repair air cleaner	Y16W01
Z4PD	4/01/2016	6:00:00	2060-10-20-02-VCU4029	SG	11010600	1W Inspection SVS 525C	
Z4PD	1/01/2016	19:30:00	2060-10-20-02-VCU4029	SG	11015894	1W Inspection SVS 525C	Y15W53
Z4PD	27/12/2015	0:00:00	2060-10-20-02-VCU4029-ENSY-FUSY-TVRE	MI	20656105	REPAIR WATER IN FUEL SYSTEM	
Z4PD	25/12/2015	7:00:00	2060-10-20-02-VCU4029	SG	10984139	250H PM Service SVS 525C Chargeup	Y15W52
Z4PD	18/12/2015	0:00:00	2060-10-20-02-VCU4029-IMAT-VPA1	MI	20652551	OUTLET PIPE BROKEN OFF	
Z4PD	18/12/2015	19:30:00	2060-10-20-02-VCU4029	SG	11005631	1W Inspection SVS 525C	Y15W51
Z4PD	16/12/2015	6:00:00	2060-10-20-02-VCU4029-HYSY-HSVV	MN	20650698	C/O Hydraulic Hose	
40LH	14/12/2015	7:00:00	2060-10-20-02-VCU4029-FRBO	MI	20579455	Repair P1 handrail - bent	DBS S5
Z4PD	12/12/2015	6:00:00	2060-10-20-02-VCU4029	SG	11000162	1W Inspection SVS 525C	Y15W50
Z4PD	6/12/2015	6:00:00	2060-10-20-02-VCU4029	SG	10994903	1W Inspection SVS 525C	Y15W49
Z4PD	30/11/2015	0:00:00	2060-10-20-02-VCU4029-FSSY	SG	10984660	6M Fire Suppression Inspection	DBSAFF15
Z4PD	30/11/2015	6:00:00	2060-10-20-02-VCU4029-IMAT	MI	20641411	C/out foot pedal in basket	DBS S5
Z4PD	30/11/2015	6:00:00	2060-10-20-02-VCU4029-IMAT	MI	20641412	Inspect/repair delayed anfo actuators	DBS S5
Z4PD	29/11/2015	6:00:00	2060-10-20-02-VCU4029	SG	10989673	1W Inspection SVS 525C	Y15W48
20EL	27/11/2015	7:00:00	2060-10-20-02-VCU4029	MI	20640388	Replace radio antenna base	
Z4PD	23/11/2015	6:00:00	2060-10-20-02-VCU4029-HYSY	MN	20637211	C/O Hydraulic Hose	
Z4PD	22/11/2015	6:00:00	2060-10-20-02-VCU4029	SG	10984158	1W Inspection SVS 525C	Y15W47
20EL	22/11/2015	7:00:00	2060-10-20-02-VCU4029	SG	10936440	1000H Proximity System Inspection	
Z4PD	13/11/2015	6:00:00	2060-10-20-02-VCU4029	SG	10978808	1W Inspection SVS 525C	Y15W46
Z4PD	8/11/2015	6:00:00	2060-10-20-02-VCU4029	SG	10973250	1W Inspection SVS 525C	Y15W45
Z4PD	1/11/2015	6:00:00	2060-10-20-02-VCU4029	SG	10967816	1W Inspection SVS 525C	
Z4PD	30/10/2015	6:00:00	2060-10-20-02-VCU4029	SG	10936419	1000H PM Service SVS 525C Chargeup	Y15W44
Z4PD	25/10/2015	6:00:00	2060-10-20-02-VCU4029	SG	10962480	1W Inspection SVS 525C	Y15W43
Z4PD-TAC	21/10/2015	6:00:00	2060-10-20-02-VCU4029-FRBO	MI	20584651	Replace steps under P1 door	DBS S2
Z4PD	19/10/2015	6:00:00	2060-10-20-02-VCU4029-IMAT-BOOM-WOPL	MI	20618957	CRACK IN BASKET TILT MOUNT	
Z4PD	16/10/2015	6:00:00	2060-10-20-02-VCU4029	SG	10957032	1W Inspection SVS 525C	Y15W42
Z4PD	14/10/2015	0:00:00	2060-10-20-02-VCU4029-OPCB-ECSY	MI	20616039	REPAIR SHUTDOWN FAULT	DBS S1
Z4PD	12/10/2015	6:00:00	2060-10-20-02-VCU4029-AISY	MI	20614554	Compressor not building up pressure	DBS S3
Z4PD	11/10/2015	6:00:00	2060-10-20-02-VCU4029-IMAT	MI	20614553	Repair damaged cage access step	
Z4PD	9/10/2015	6:00:00	2060-10-20-02-VCU4029	SG	10951670	1W Inspection SVS 525C	Y15W41
Z4PD	6/10/2015	6:00:00	2060-10-20-02-VCU4029-ENSY-COSY	MI	20611784	Inspect/repair overheating whilst tram	DBS S5
Z4PD	3/10/2015	6:00:00	2060-10-20-02-VCU4029-IMAT-BOOM-WOPL	MI	20610670	Inspect Basket Tilt Cyl Mount	
Z4PD	2/10/2015	6:00:00	2060-10-20-02-VCU4029	SG	10946176	1W Inspection SVS 525C	Y15W40
Z4PD	30/09/2015	6:00:00	2060-10-20-02-VCU4029-FRBO-ECSY	MI	20608530	Inspect/repair Fuel guage N/W	DBS S1
Z4PD	27/09/2015	6:00:00	2060-10-20-02-VCU4029	SG	10940342	1W Inspection SVS 525C	Y15W39
Z4PD	25/09/2015	6:00:00	2060-10-20-02-VCU4029-FRBO-AESY	MI	20554650	replace damaged pos2 door	Y15W39
Z4PD	20/09/2015	6:00:00	2060-10-20-02-VCU4029	SG	10934826	1W Inspection SVS 525C	
20EL	14/09/2015	6:00:00	2060-10-20-02-VCU4029	SG	10773993	1000H Proximity System Inspection	
Z4PD	13/09/2015	6:00:00	2060-10-20-02-VCU4029	SG	10929569	1W Inspection SVS 525C	Y15W37
Z4PD	13/09/2015	6:00:00	2060-10-20-02-VCU4029-IMAT-BOOM-WOPL	MI	20596030	REPAIR ACCIDENT DAMAGE TO BASKET	Y15W38
Z4PD	7/09/2015	0:00:00	2060-10-20-02-VCU4029	MN	20255567	AMMS Classified Plant Inspection #I02952	
Z4PD	7/09/2015	0:00:00	2060-10-20-02-VCU4029-IMAT-BOOM-WOPL	MI	20595986	BASKET MOUNTING PLATE DAMAGED	
Z4PD	7/09/2015	0:00:00	2060-10-20-02-VCU4029-OPCB	MI	20434539	Inspect/Repair windscreen wipers	DBS S1
Z4PD	7/09/2015	6:00:00	2060-10-20-02-VCU4029	MI	20488149	Repair air compressor	
Z4PD	7/09/2015	6:00:00	2060-10-20-02-VCU4029-AISY	MI	20487149	Replace compressor coupling	
Z4PD	7/09/2015	6:00:00	2060-10-20-02-VCU4029-IMAT-BOOM-WOPL	MI	20434919	Replace Basket floor	DBS S1
Z4PD	6/09/2015	6:00:00	2060-10-20-02-VCU4029	SG	10924245	1W Inspection SVS 525C	Y15W36
Z4PD	3/09/2015	0:00:00	2060-10-20-02-VCU4029-HYSY	MI	20593951	REPAIR HYD OIL LEAK	
Z4PD	30/08/2015	6:00:00	2060-10-20-02-VCU4029	SG	10919102	1W Inspection SVS 525C	Y15W35

Z4PD	23/08/2015	6:00:00	2060-10-20-02-VCU4029	SG	10913441	1W Inspection SVS 525C	
Z4PD	21/08/2015	6:00:00	2060-10-20-02-VCU4029	SG	10893899	250H PM Service SVS 525C Chargeup	Y15W34
Z4PD	16/08/2015	6:00:00	2060-10-20-02-VCU4029	SG	10908279	1W Inspection SVS 525C	Y15W33
Z4PD	9/08/2015	6:00:00	2060-10-20-02-VCU4029	SG	10903049	1W Inspection SVS 525C	Y15W32
Z4PD	31/07/2015	6:00:00	2060-10-20-02-VCU4029	SG	10896957	1W Inspection SVS 525C	Y15W31
Z4PD	31/07/2015	6:00:00	2060-10-20-02-VCU4029-AISY	MN	20568103	INVESTIGATE RPM INCREASE FAULT	DBS S5
Z4PD	26/07/2015	6:00:00	2060-10-20-02-VCU4029	SG	10891579	1W Inspection SVS 525C	Y15W30
Z4PD	25/07/2015	0:00:00	2060-10-20-02-VCU4029-HYSY-HSVV	MI	20571620	C/O HYD HOSE	DBS S3
Z4PD-TAC	21/07/2015	7:00:00	2060-10-20-02-VCU4029-HYSY	MI	20569256	REPLACE BASKET CONTROLE VALVE - SLOW BO	DBS S5
Z4PD	17/07/2015	6:00:00	2060-10-20-02-VCU4029	SG	10886021	1W Inspection SVS 525C	Y15W29
Z4PD	12/07/2015	6:00:00	2060-10-20-02-VCU4029	SG	10877524	1W Inspection SVS 525C	Y15W28
20EL	8/07/2015	6:00:00	2060-10-20-02-VCU4029	MI	20562471	Replace radio aerial & base	
Z4PD	5/07/2015	6:00:00	2060-10-20-02-VCU4029	SG	10872393	1W Inspection SVS 525C	Y15W27
Z4PD	2/07/2015	0:00:00	2060-10-20-02-VCU4029-IMAT-BOOM	MI	20559140	REPAIR DAMAGE ,CAGE TILT CYLINDER MOUNTS	
Z4PD	2/07/2015	6:00:00	2060-10-20-02-VCU4029-HYSY	MI	20556762	Reverse hydraulic levers in basket/	Y15W27
Z4PD	2/07/2015	7:00:00	2060-10-20-02-VCU4029-IMAT-BOOM-WOPL	MI	20559078	repair basket tilt cylinder mounts	DBS S3
Z4PD	28/06/2015	6:00:00	2060-10-20-02-VCU4029	SG	10866827	1W Inspection SVS 525C	Y15W26
Z4PD	27/06/2015	6:00:00	2060-10-20-02-VCU4029-OPCB	MI	20556450	REPLACE POS 1 DOOR STRUT	DBS S2
Z4PD	26/06/2015	6:00:00	2060-10-20-02-VCU4029	SG	10842852	500H PM Service SVS 525C Chargeup	Y15W26
Z4PD	25/06/2015	0:00:00	2060-10-20-02-VCU4029-ENSY-ECSY	MI	20555129	lost all power	
20EL	25/06/2015	6:00:00	2060-10-20-02-VCU4029	MI	20555186	Repair radio fault	
Z4PD	21/06/2015	6:00:00	2060-10-20-02-VCU4029	SG	10861199	1W Inspection SVS 525C	Y15W25
Z4PD	16/06/2015	6:00:00	2060-10-20-02-VCU4029-HYSY-ECSY	MN	20550517	C/O P3 JACK LEG PROXIMITY	DBS S2
Z4PD	15/06/2015	0:00:00	2060-10-20-02-VCU4029-OPCB-SEAT	MI	20549280	C/O SEAT BELT	DBS S1
Z4PD	13/06/2015	6:00:00	2060-10-20-02-VCU4029	SG	10855802	1W Inspection SVS 525C	Y15W24
Z4PD	10/06/2015	0:00:00	2060-10-20-02-VCU4029-ENSY-IKSY	MI	20547088	Replace air cleaner dust bowl	DBS S3
Z4PD	8/06/2015	7:00:00	2060-10-20-02-VCU4029-OPCB	MI	20542496	C/O Fuel level sender	DBS S2
Z4PD	7/06/2015	0:00:00	2060-10-20-02-VCU4029-ENSY-EXSY	MI	20545211	CLEAN CATALYTIC CONVERTER	DBS S1
Z4PD	7/06/2015	6:00:00	2060-10-20-02-VCU4029	SG	10850222	1W Inspection SVS 525C	Y15W23
Z4PD	6/06/2015	0:00:00	2060-10-20-02-VCU4029-FRBO-ECSY	MI	20544903	MODIFY LIGHTING FOR CAGE/HI BEAM	DBS S5
Z4PD	6/06/2015	6:00:00	2060-10-20-02-VCU4029-OPCB-ECSY	MN	20544946	LIGHT REPAIRS	DBS S5
Z4PD	3/06/2015	0:00:00	2060-10-20-02-VCU4029-AISY	MN	20543735	COMPRESSOR FAULT	DBS S5
Z4PD	3/06/2015	0:00:00	2060-10-20-02-VCU4029-ENSY-IKSY	MI	20543362	LOW POWER FAULT	DBS S5
Z4PD	2/06/2015	0:00:00	2060-10-20-02-VCU4029	MN	20538781	Purchase spare tyres	
Z4PD	1/06/2015	0:00:00	2060-10-20-02-VCU4029-FSSY	SG	10865556	12M Fire Suppression Inspection	DBSAFF15
Z4PD	30/05/2015	0:00:00	2060-10-20-02-VCU4029-FSSY	SG	10562910	6M Fire Suppression Inspection	DBSAFF14
Z4PD	29/05/2015	6:00:00	2060-10-20-02-VCU4029	SG	10844711	1W Inspection SVS 525C	Y15W22
Z4PD	29/05/2015	6:00:00	2060-10-20-02-VCU4029	MI	20540670	Inspect EWP post external incident/	
Z4PD	27/05/2015	0:00:00	2060-10-20-02-VCU4029-DRTR	MI	20539620	Fit tyres to rims as spare	
Z4PD	27/05/2015	6:00:00	2060-10-20-02-VCU4029-ENSY-FUSY	MI	20539310	Ran out of fuel	
Z4PD	26/05/2015	0:00:00	2060-10-20-02-VCU4029-IMAT-BOOM	MI	20538637	BOOM HYD LEAK	DBS S5
Z4PD	24/05/2015	6:00:00	2060-10-20-02-VCU4029	SG	10839131	1W Inspection SVS 525C	Y15W21
Z4PD	22/05/2015	0:00:00	2060-10-20-02-VCU4029-AISY	MI	20512849	Repair tank drain being blocked	Y15W21
Z4PD	15/05/2015	6:00:00	2060-10-20-02-VCU4029	SG	10833750	1W Inspection SVS 525C	Y15W20
Z4PD	12/05/2015	0:00:00	2060-10-20-02-VCU4029-DRTR-AXA1-TYW2	MI	20531641	Retorque P2 Wheel	
Z4PD	8/05/2015	6:00:00	2060-10-20-02-VCU4029	SG	10828325	1W Inspection SVS 525C	Y15W19
Z4PD	8/05/2015	6:00:00	2060-10-20-02-VCU4029-DRTR-AXA2-TYW3	MN	20529963	C/O POS THREE TYRE	DBS S5
Z4PD	3/05/2015	0:00:00	2060-10-20-02-VCU4029-DRTR-AXA1-TYW1	MI	20526723	c/o pos 1 flat tyre	
Z4PD	3/05/2015	0:00:00	2060-10-20-02-VCU4029-OPCB-ECSY	MI	20526823	Repair Air compressor fault	
Z4PD	2/05/2015	7:00:00	2060-10-20-02-VCU4029-IMAT-VPAR	MI	20526262	C/O Compressor Regulator	DBS S3
Z4PD	1/05/2015	6:00:00	2060-10-20-02-VCU4029	SG	10822552	1W Inspection SVS 525C	Y15W18
Z4PD	29/04/2015	0:00:00	2060-10-20-02-VCU4029-AISY	MI	20524824	COMPRESSOR FAULT	
Z4PD	26/04/2015	6:00:00	2060-10-20-02-VCU4029	SG	10817172	1W Inspection SVS 525C	
20EL	25/04/2015	0:00:00	2060-10-20-02-VCU4029	MI	20522855	Repair radio fault	
Z4PD	24/04/2015	6:00:00	2060-10-20-02-VCU4029	MN	20506108	C/O Compressor Reg Valve	Y15W17
Z4PD	23/04/2015	6:00:00	2060-10-20-02-VCU4029	SG	10813381	250H PM Service SVS 525C Chargeup	Y15W17
Z4PD	23/04/2015	6:00:00	2060-10-20-02-VCU4029-OPCB-ECSY	MI	20521439	Jackleg proxy fault	
Z4PD	17/04/2015	6:00:00	2060-10-20-02-VCU4029	SG	10811854	1W Inspection SVS 525C	Y15W16
Z4PD	11/04/2015	0:00:00	2060-10-20-02-VCU4029-HYSY	MI	20515621	Repair zoom creep	DBS S2
Z4PD	11/04/2015	6:00:00	2060-10-20-02-VCU4029-ENSY-FUSY	MN	20515814	LOW ENGINE POWER	DBS S5
Z4PD	10/04/2015	6:00:00	2060-10-20-02-VCU4029	SG	10806439	1W Inspection SVS 525C	Y15W15
Z4PD	9/04/2015	6:00:00	2060-10-20-02-VCU4029-FRBO-ECSY	MI	20479070	REPLACE EARTH STRAP	Y15W15
Z4PD	9/04/2015	6:00:00	2060-10-20-02-VCU4029-HYSY	MI	20351522	insp brake accum losing pressure/	Y15W15
Z4PD	9/04/2015	6:00:00	2060-10-20-02-VCU4029-OPCB-ECSY	MI	20312047	Change faulty fuel guage	Y15W15
Z4PD	8/04/2015	6:00:00	2060-10-20-02-VCU4029-IMAT-VPA1	MN	20514542	KETTLE PRESSURE SEAL FALLEN OFF	DBS S5
Z4PD	4/04/2015	0:00:00	2060-10-20-02-VCU4029-OPCB-ECSY	MI	20512297	C/O ignition barrel	
Z4PD	4/04/2015	7:00:00	2060-10-20-02-VCU4029-ENSY-COSY	MI	20511587	Radiator blocked/REMOVE AND CLEAN	DBS S2
Z4PD	3/04/2015	6:00:00	2060-10-20-02-VCU4029	SG	10800968	1W Inspection SVS 525C	Y15W14

Z4PD	30/03/2015	6:00:00	2060-10-20-02-VCU4029-DRTR-AXA2	MI	20490514	C/O Rear diff	DBS S3
Z4PD	26/03/2015	0:00:00	2060-10-20-02-VCU4029-FRBO-ECSY	MI	20508226	ELECTRICAL FAULT IN CAGE	DBS S5
Z4PD	26/03/2015	6:00:00	2060-10-20-02-VCU4029	SG	10794994	1W Inspection SVS 525C	Y15W13
Z4PD	23/03/2015	6:00:00	2060-10-20-02-VCU4029-IMAT-BOOM	MI	20505981	Replace missing boom ext cyl pin	
Z4PD	21/03/2015	6:00:00	2060-10-20-02-VCU4029	SG	10789202	1W Inspection SVS 525C	Y15W12
Z4PD	21/03/2015	6:00:00	2060-10-20-02-VCU4029-OPCB-ECSY	MI	20505214	Repair negative start fault	
Z4PD	21/03/2015	7:00:00	2060-10-20-02-VCU4029-FRBO	MI	20452774	Repair boom slides movement	Y15W21
Z4PD	15/03/2015	6:00:00	2060-10-20-02-VCU4029	SG	10783445	1W Inspection SVS 525C	
Z4PD	13/03/2015	0:00:00	2060-10-20-02-VCU4029-AISY	MI	20500978	REPLACE FOOT PEDAL	DBS S5
Z4PD	13/03/2015	6:00:00	2060-10-20-02-VCU4029	SG	10766922	1W Inspection SVS 525C	Y15W11
Z4PD	13/03/2015	6:00:00	2060-10-20-02-VCU4029-ALSY-HSVV	MN	20501222	HYD OIL LEAK	
Z4PD	7/03/2015	6:00:00	2060-10-20-02-VCU4029	SG	10777979	1W Inspection SVS 525C	Y15W10
Z4PD	1/03/2015	6:00:00	2060-10-20-02-VCU4029	SG	10772437	1W Inspection SVS 525C	Y15W09
Z4PD	20/02/2015	6:00:00	2060-10-20-02-VCU4029	SG	10773992	2000H PM Service SVS 525C Chargeup	Y15W08
Z4PD	14/02/2015	6:00:00	2060-10-20-02-VCU4029-IMAT-VPA1	MN	20486788	Kettles Not Shutting Off	
Z4PD	13/02/2015	6:00:00	2060-10-20-02-VCU4029	SG	10761546	1W Inspection SVS 525C	Y15W07
Z4PD	8/02/2015	6:00:00	2060-10-20-02-VCU4029	SG	10755951	1W Inspection SVS 525C	Y15W06
Z4PD	1/02/2015	6:00:00	2060-10-20-02-VCU4029	SG	10750531	1W Inspection SVS 525C	Y15W05
Z4PD	1/02/2015	6:00:00	2060-10-20-02-VCU4029-ENSY-COSY	MI	20479348	Repair coolant leak	
Z4PD	30/01/2015	7:00:00	2060-10-20-02-VCU4029-FRBO-AESY	MI	20478865	Repair damaged handrail on basket	
Z4PD	29/01/2015	6:00:00	2060-10-20-02-VCU4029-IMAT-BOOM-WOPL	MN	20478191	Repair Basket Step	
Z4PD	27/01/2015	6:00:00	2060-10-20-02-VCU4029-HYSY-BRSY	MI	20455816	Repair Brake fault	
Z4PD	25/01/2015	6:00:00	2060-10-20-02-VCU4029	SG	10745152	1W Inspection SVS 525C	Y15W04
Z4PD	23/01/2015	6:00:00	2060-10-20-02-VCU4029-IMAT-BOOM-WOPL	MI	20475309	Repair no basket controls	
Z4PD	19/01/2015	0:00:00	2060-10-20-02-VCU4029-IMAT	MI	20472093	REPAIR BOOM	Y15W04
Z4PD	18/01/2015	6:00:00	2060-10-20-02-VCU4029	SG	10740119	1W Inspection SVS 525C	Y15W03
Z4PD	17/01/2015	6:00:00	2060-10-20-02-VCU4029-IMAT-BOOM-WOPL	MN	20471472	Repair Platform	
Z4PD	17/01/2015	7:00:00	2060-10-20-02-VCU4029-FRBO	MI	20448824	Fit handrails to Pos 2 kettle access	Y15W04
20EL	11/01/2015	6:00:00	2060-10-20-02-VCU4029	MI	20468464	Proximity fault repair	
Z4PD	9/01/2015	0:00:00	2060-10-20-02-VCU4029-FSSY	MI	20467660	Repair AFFF system	
Z4PD	9/01/2015	6:00:00	2060-10-20-02-VCU4029	SG	10734719	1W Inspection SVS 525C	Y15W02
Z4PD	7/01/2015	6:00:00	2060-10-20-02-VCU4029-AISY	MI	20465469	Anfo kettle actuators not working	
Z4PD	2/01/2015	6:00:00	2060-10-20-02-VCU4029	SG	10729253	1W Inspection SVS 525C	Y15W01
Z4PD	28/12/2014	6:00:00	2060-10-20-02-VCU4029	SG	10723380	1W Inspection SVS 525C	Y14W52
Z4PD	27/12/2014	6:00:00	2060-10-20-02-VCU4029	SG	10725111	250H PM Service SVS 525C Chargeup	Y14W52
20EL	25/12/2014	6:00:00	2060-10-20-02-VCU4029	MI	20461054	Repair radio antenna/base	
Z4PD	22/12/2014	6:00:00	2060-10-20-02-VCU4029-OPCB-SEAT	MI	20433524	Repair torn seat	DBS S5
Z4PD	21/12/2014	6:00:00	2060-10-20-02-VCU4029	SG	10718081	1W Inspection SVS 525C	Y14W51
Z4PD	14/12/2014	6:00:00	2060-10-20-02-VCU4029	SG	10712740	1W Inspection SVS 525C	Y14W50
Z4PD	11/12/2014	6:00:00	2060-10-20-02-VCU4029-FRBO-ECSY	MI	20454218	Repair reverse camera	
Z4PD	9/12/2014	6:00:00	2060-10-20-02-VCU4029-OPCB-ROFO	MI	20453545	C/out rear wiper	
Z4PD	7/12/2014	6:00:00	2060-10-20-02-VCU4029	SG	10705870	1W Inspection SVS 525C	Y14W49
Z4PD	30/11/2014	0:00:00	2060-10-20-02-VCU4029-AISY	MI	20448447	Replace kettle relay valve	
Z4PD	30/11/2014	6:00:00	2060-10-20-02-VCU4029	SG	10702805	1W Inspection SVS 525C	Y14W48
20EL	29/11/2014	6:00:00	2060-10-20-02-VCU4029	MI	20448310	Replace damaged radio antenna	
Z4PD	29/11/2014	7:00:00	2060-10-20-02-VCU4029-IMAT-BOOM-WOPL	MI	20448402	Modify Basket handrails	
Z4PD	25/11/2014	6:00:00	2060-10-20-02-VCU4029-FRBO-ECSY	MI	20446558	Inspect/repair reverse camera N/W	DBS S1
Z4PD	22/11/2014	6:00:00	2060-10-20-02-VCU4029	SG	10693886	1W Inspection SVS 525C	Y14W47
Z4PD	15/11/2014	6:00:00	2060-10-20-02-VCU4029	SG	10683310	1W Inspection SVS 525C	Y14W46
Z4PD	13/11/2014	6:00:00	2060-10-20-02-VCU4029-HYSY-BRSY	MI	20440486	Repair parkbrake fault	
Z4PD	8/11/2014	0:00:00	2060-10-20-02-VCU4029-ENSY-ECSY	MI	20438342	C/O Compressor Cooling Fan	DBS S2
Z4PD	7/11/2014	6:00:00	2060-10-20-02-VCU4029	SG	10675916	1W Inspection SVS 525C	Y14W45
Z4PD	2/11/2014	6:00:00	2060-10-20-02-VCU4029	SG	10669671	1W Inspection SVS 525C	Y14W44
Z4PD	2/11/2014	6:00:00	2060-10-20-02-VCU4029-AISY	MI	20434987	Fab new anfo pedal	
Z4PD	2/11/2014	6:00:00	2060-10-20-02-VCU4029-FRBO-AESY	MI	20434984	Repair damaged bottom step	
Z4PD	31/10/2014	0:00:00	2060-10-20-02-VCU4029-IMAT-BOOM-WOPL	MI	20434560	Inspect/Repair cage hand rail	DBS S1
Z4PD	26/10/2014	0:00:00	2060-10-20-02-VCU4029-IMAT	MI	20431902	replace kettle seals	DBS S1
Z4PD	26/10/2014	6:00:00	2060-10-20-02-VCU4029	SG	10664343	1W Inspection SVS 525C	Y14W45
Z4PD	24/10/2014	6:00:00	2060-10-20-02-VCU4029	SG	10651263	500H PM Service SVS 525C Chargeup	Y14W43
Z4PD	19/10/2014	6:00:00	2060-10-20-02-VCU4029	SG	10658723	1W Inspection SVS 525C	Y14W42
Z4PD	18/10/2014	6:00:00	2060-10-20-02-VCU4029-ENSY-ECSY	MI	20427809	C/out ignition barrel	
Z4PD	12/10/2014	6:00:00	2060-10-20-02-VCU4029	SG	10653421	1W Inspection SVS 525C	Y14W41
Z4PD	10/10/2014	0:00:00	2060-10-20-02-VCU4029-FRBO-ECSY	MI	20424177	park brake press switch	DBS S1
Z4PD	5/10/2014	6:00:00	2060-10-20-02-VCU4029	SG	10647693	1W Inspection SVS 525C	Y14W40
Z4PD	26/09/2014	0:00:00	2060-10-20-02-VCU4029-FRBO-ECSY	MI	20417738	THERMO FAN FAULT	DBS S1
Z4PD	26/09/2014	6:00:00	2060-10-20-02-VCU4029	SG	10642139	1W Inspection SVS 525C	Y14W39
Z4PD	25/09/2014	6:00:00	2060-10-20-02-VCU4029-HYSY-HSVV	MI	20417326	Check max steering pump pressure/	
Z4PD	24/09/2014	6:00:00	2060-10-20-02-VCU4029-HYSY	MN	20416570	REPAIR BOOM HYD FAULT	

Z4PD	21/09/2014	6:00:00	2060-10-20-02-VCU4029	SG	10636439	1W Inspection SVS 525C	Y14W38
Z4PD	12/09/2014	6:00:00	2060-10-20-02-VCU4029	SG	10630199	1W Inspection SVS 525C	Y14W37
Z4PD	7/09/2014	6:00:00	2060-10-20-02-VCU4029	SG	10624786	1W Inspection SVS 525C	Y14W36
Z4PD	7/09/2014	6:00:00	2060-10-20-02-VCU4029-ENSY-ECSY	MI	20400829	Repair Electrical shutdown fault	Y14W37
Z4PD	29/08/2014	6:00:00	2060-10-20-02-VCU4029	SG	10619475	1W Inspection SVS 525C	Y14W35
Z4PD	28/08/2014	7:00:00	2060-10-20-02-VCU4029-FRBO-AESY	MI	20402933	Repair pos 2 access step hinges	
Z4PD	22/08/2014	6:00:00	2060-10-20-02-VCU4029	SG	10614001	1W Inspection SVS 525C	Y14W34
Z4PD	22/08/2014	7:00:00	2060-10-20-02-VCU4029-IMAT-BOOM-WOPL	MI	20335006	ANFO foot pedal needs gaurd fabricated a	Y14W34
Z4PD	16/08/2014	6:00:00	2060-10-20-02-VCU4029	SG	10608792	1W Inspection SVS 525C	Y14W33
Z4PD	14/08/2014	6:00:00	2060-10-20-02-VCU4029-ENSY-ECSY	MI	20396226	Intermittant low power fault	
Z4PD	10/08/2014	6:00:00	2060-10-20-02-VCU4029	SG	10603339	1W Inspection SVS 525C	Y14W32
Z4PD	9/08/2014	6:00:00	2060-10-20-02-VCU4029-OPCB-ECSY	MI	20393800	Install wiring and components into seal	
Z4PD	8/08/2014	6:00:00	2060-10-20-02-VCU4029-IMAT-VPA1	MI	20393053	Repair loose clamp to kettle actuator	
Z4PD	7/08/2014	6:00:00	2060-10-20-02-VCU4029-ENSY-ECSY	MI	20392386	Repair shutdown fault	
Z4PD	3/08/2014	6:00:00	2060-10-20-02-VCU4029	SG	10598068	1W Inspection SVS 525C	Y14W31
Z4PD	3/08/2014	6:00:00	2060-10-20-02-VCU4029-OPCB-ECSY	MI	20390492	Electrical shutdown fault	
Z4PD	2/08/2014	6:00:00	2060-10-20-02-VCU4029-IMAT-BOOM-WOPL	MN	20390040	REPAIR BASKET LOCK	
Z4PD	1/08/2014	6:00:00	2060-10-20-02-VCU4029	SG	10592966	250H PM Service SVS 525C Chargeup	Y14W31
20EL	31/07/2014	0:00:00	2060-10-20-02-VCU4029	MI	20389140	Repair radio & prox fault	
Z4PD	31/07/2014	6:00:00	2060-10-20-02-VCU4029-OPCB-ECSY	MI	20389281	C/O faulty batteries	
Z4PD	27/07/2014	6:00:00	2060-10-20-02-VCU4029	SG	10591964	1W Inspection SVS 525C	Y14W30
Z4PD	22/07/2014	6:00:00	2060-10-20-02-VCU4029	MI	20384726	Proximity fault	
Z4PD	21/07/2014	6:00:00	2060-10-20-02-VCU4029-IMAT-BOOM-WOPL	MN	20384146	WELD UP CRACK	
Z4PD	18/07/2014	6:00:00	2060-10-20-02-VCU4029	SG	10586401	1W Inspection SVS 525C	Y14W29
Z4PD	16/07/2014	6:00:00	2060-10-20-02-VCU4029-ENSY-ECSY	MI	20381855	REPAIR SHUT DOWN FAULT	
Z4PD	12/07/2014	6:00:00	2060-10-20-02-VCU4029	SG	10579139	1W Inspection SVS 525C	Y14W28
Z4PD	6/07/2014	6:00:00	2060-10-20-02-VCU4029	SG	10573135	1W Inspection SVS 525C	Y14W27
Z4PD	5/07/2014	6:00:00	2060-10-20-02-VCU4029	SG	10541850	1000H PM Service SVS 525C Chargeup	Y14W27
20EL	2/07/2014	6:00:00	2060-10-20-02-VCU4029	SG	10541851	1000H Proximity System Inspection	Y14W27
Z4PD	1/07/2014	6:00:00	2060-10-20-02-VCU4029-OPCB-ECSY	MI	20374482	inspect/repair aerial base	DBS S1
Z4PD	28/06/2014	6:00:00	2060-10-20-02-VCU4029-FRBO-ECSY	MI	20366290	re-wire basket lights	DBS S5
Z4PD	27/06/2014	6:00:00	2060-10-20-02-VCU4029	SG	10566941	1W Inspection SVS 525C	Y14W26
Z4PD	24/06/2014	0:00:00	2060-10-20-02-VCU4029-DRTR-TRAN	MI	20370891	c/o trans hose	DBS S2
Z4PD	22/06/2014	0:00:00	2060-10-20-02-VCU4029-ENSY-ECSY	MI	20369751	START FAULT	
Z4PD	22/06/2014	6:00:00	2060-10-20-02-VCU4029	SG	10561241	1W Inspection SVS 525C	Y14W25
Z4PD	21/06/2014	0:00:00	2060-10-20-02-VCU4029-FRBO-ECSY	MI	20369625	JACKLEG INDICATOR ON, PB WON'T RELEASE	
Z4PD	21/06/2014	6:00:00	2060-10-20-02-VCU4029-OPCB	MN	20369429	REPAIR A/C FAULT	
Z4PD	18/06/2014	0:00:00	2060-10-20-02-VCU4029-HYSY-ECSY	MI	20367317	COMPRESSOR THERMO FAN FAULT	
Z4PD	16/06/2014	0:00:00	2060-10-20-02-VCU4029-FRBO-ECSY	MI	20366293	no ignition power	
Z4PD	13/06/2014	6:00:00	2060-10-20-02-VCU4029	SG	10555062	1W Inspection SVS 525C	Y14W24
Z4PD	11/06/2014	0:00:00	2060-10-20-02-VCU4029-DRTR	MI	20345120	Repair p/brake dragging	Y14W19
Z4PD	8/06/2014	6:00:00	2060-10-20-02-VCU4029	SG	10548918	1W Inspection SVS 525C	Y14W23
Z4PD	5/06/2014	0:00:00	2060-10-20-02-VCU4029-FSSY	MN	20354507	12M Fire Suppression Inspection	Y14W25
Z4PD	1/06/2014	6:00:00	2060-10-20-02-VCU4029	SG	10543187	1W Inspection SVS 525C	Y14W22
Z4PD	26/05/2014	6:00:00	2060-10-20-02-VCU4029-OPCB-ECSY	MI	20356195	Jack leg proximity sensor fault	
Z4PD	25/05/2014	6:00:00	2060-10-20-02-VCU4029	SG	10537491	1W Inspection SVS 525C	Y14W21
Z4PD	25/05/2014	6:00:00	2060-10-20-02-VCU4029-OPCB-ECSY	MI	20355992	Repair cage lights	
Z4PD	16/05/2014	6:00:00	2060-10-20-02-VCU4029-FRBO-ECSY	MI	20351741	Repair emergency lowering fault	
Z4PD	15/05/2014	6:00:00	2060-10-20-02-VCU4029	SG	10531506	1W Inspection SVS 525C	Y14W20
Z4PD	14/05/2014	6:00:00	2060-10-20-02-VCU4029-FSSY	MI	20350470	Repair AFFF discharged	
Z4PD	13/05/2014	6:00:00	2060-10-20-02-VCU4029-AISY	MI	20343998	c/o compressor temp sensor	DBS S2
Z4PD	11/05/2014	6:00:00	2060-10-20-02-VCU4029	SG	10526318	1W Inspection SVS 525C	Y14W19
Z4PD	9/05/2014	6:00:00	2060-10-20-02-VCU4029-ENSY-IKSY	MI	20347898	C/O AIR FILTER	DBS S1
Z4PD	9/05/2014	6:00:00	2060-10-20-02-VCU4029-FRBO-AESY	MI	20347946	inspect/repair emerg lower function	DBS S1
Z4PD	4/05/2014	6:00:00	2060-10-20-02-VCU4029	SG	10519705	1W Inspection SVS 525C	Y14W18
Z4PD	1/05/2014	0:00:00	2060-10-20-02-VCU4029-ENSY-FUSY	MI	20343728	Ran out of fuel	
Z4PD	28/04/2014	6:00:00	2060-10-20-02-VCU4029-ENSY-FUSY	MI	20342063	LOW FUEL	
Z4PD	27/04/2014	6:00:00	2060-10-20-02-VCU4029	SG	10514058	1W Inspection SVS 525C	
Z4PD	23/04/2014	6:00:00	2060-10-20-02-VCU4029-HYSY-HSVV	MI	20339635	Oil leak at basket controls	
Z4PD	21/04/2014	6:00:00	2060-10-20-02-VCU4029	SG	10493253	250H PM Service SVS 525C Chargeup	Y14W17
Z4PD	19/04/2014	6:00:00	2060-10-20-02-VCU4029	SG	10508106	1W Inspection SVS 525C	Y14W16
Z4PD	18/04/2014	7:00:00	2060-10-20-02-VCU4029-FRBO-AESY	MI	20338270	inspect cage door latch	
Z4PD	14/04/2014	6:00:00	2060-10-20-02-VCU4029-ENSY	MN	20335539	WONT START	
Z4PD	13/04/2014	0:00:00	2060-10-20-02-VCU4029-AISY	MI	20335501	KETTLE PRESS FAULT	
Z4PD	13/04/2014	6:00:00	2060-10-20-02-VCU4029	SG	10502226	1W Inspection SVS 525C	Y14W15
Z4PD	9/04/2014	6:00:00	2060-10-20-02-VCU4029-ENSY-FUSY	MI	20333401	WONT START, NO FUEL	
Z4PD	31/03/2014	6:00:00	2060-10-20-02-VCU4029	SG	10495912	1W Inspection SVS 525C	Y14W14
Z4PD	24/03/2014	6:00:00	2060-10-20-02-VCU4029	SG	10490434	1W Inspection SVS 525C	Y14W13

Z4PD	23/03/2014	6:00:00	2060-10-20-02-VCU4029-HYSY-HSVV	MI	20324828	Repair oil leak at basket controls	
Z4PD	21/03/2014	6:00:00	2060-10-20-02-VCU4029	SG	10484260	1W Inspection SVS 525C	Y14W12
Z4PD	18/03/2014	6:00:00	2060-10-20-02-VCU4029-HYSY	MI	20322383	Repar oil leak at basket control levers	
Z4PD	10/03/2014	6:00:00	2060-10-20-02-VCU4029	SG	10477876	1W Inspection SVS 525C	Y14W11
Z4PD	8/03/2014	6:00:00	2060-10-20-02-VCU4029	SG	10473093	1W Inspection SVS 525C	Y14W10
Z4PD	1/03/2014	6:00:00	2060-10-20-02-VCU4029	SG	10466742	1W Inspection SVS 525C	Y14W09
Z4PD	26/02/2014	6:00:00	2060-10-20-02-VCU4029-ENSY-FUSY-TVRE	MI	20312045	Machine won,t start - out of fuel	
Z4PD	23/02/2014	6:00:00	2060-10-20-02-VCU4029	SG	10458394	1W Inspection SVS 525C	Y14W08
Z4PD	22/02/2014	0:00:00	2060-10-20-02-VCU4029-OPCB-ECSY	MI	20310436	Reposition air compressor switch in cab	
Z4PD	17/02/2014	6:00:00	2060-10-20-02-VCU4029-HYSY-BRSY	MN	20307300	INVESTIGATE P/B FAULT	
Z4PD	16/02/2014	6:00:00	2060-10-20-02-VCU4029	SG	10452510	1W Inspection SVS 525C	Y14W07
Z4PD	14/02/2014	0:00:00	2060-10-20-02-VCU4029-OPCB-ROFO	MI	20306658	DOOR STRUT FAULTY, P1	DBS S5
Z4PD	12/02/2014	6:00:00	2060-10-20-02-VCU4029-DRTR	MI	20304605	Repair parkbrake fault	
Z4PD	10/02/2014	6:00:00	2060-10-20-02-VCU4029-OPCB	MI	20304222	Replace door strut	
Z4PD	9/02/2014	6:00:00	2060-10-20-02-VCU4029	SG	10447155	1W Inspection SVS 525C	Y14W06
Z4PD	6/02/2014	6:00:00	2060-10-20-02-VCU4029-HYSY	MI	20302643	Boom function fault, control valve stick	
Z4PD	5/02/2014	6:00:00	2060-10-20-02-VCU4029-IMAT-BOOM	MI	20301845	Repair boom fault	
Z4PD	4/02/2014	6:00:00	2060-10-20-02-VCU4029-OPCB	MI	20301313	Replace door struts	DBS S5
Z4PD	2/02/2014	6:00:00	2060-10-20-02-VCU4029	SG	10441190	1W Inspection SVS 525C	
Z4PD	28/01/2014	0:00:00	2060-10-20-02-VCU4029-HYSY	MI	20297790	insp / repair slew creeping	
Z4PD	27/01/2014	6:00:00	2060-10-20-02-VCU4029	SG	10352101	500H PM Service SVS 525C Chargeup	Y14W05
Z4PD	27/01/2014	6:00:00	2060-10-20-02-VCU4029-HYSY	MI	20297444	Boom slow to the right	
Z4PD	25/01/2014	6:00:00	2060-10-20-02-VCU4029	SG	10435672	1W Inspection SVS 525C	Y14W04
Z4PD	22/01/2014	6:00:00	2060-10-20-02-VCU4029-OPCB-ECSY	MI	20295141	Engine keeps shutting down	
Z4PD	19/01/2014	6:00:00	2060-10-20-02-VCU4029	SG	10430249	1W Inspection SVS 525C	Y14W03
Z4PD	15/01/2014	6:00:00	2060-10-20-02-VCU4029-HYSY-HSVV	MI	20291436	inspect / repair hyd leak centre hitch	DBS S1
Z4PD	14/01/2014	7:00:00	2060-10-20-02-VCU4029-FRBO-AESY	MI	20290651	Repair damaged hand rail on basket	
Z4PD	10/01/2014	6:00:00	2060-10-20-02-VCU4029	SG	10424484	1W Inspection SVS 525C	Y14W02
Z4PD	6/01/2014	0:00:00	2060-10-20-02-VCU4029-HYSY	MI	20283511	repair slew not holding	DBS S3
Z4PD	3/01/2014	6:00:00	2060-10-20-02-VCU4029	SG	10418834	1W Inspection SVS 525C	Y14W01
Z4PD	30/12/2013	0:00:00	2060-10-20-02-VCU4029-HYSY	MI	20283659	c/o leaking hyd hose	
Z4PD	29/12/2013	0:00:00	2060-10-20-02-VCU4029-HYSY	MI	20283509	c/o basket controle lever boots	DBS S1
Z4PD	28/12/2013	0:00:00	2060-10-20-02-VCU4029-HYSY	MI	20282932	repair slow slew to one side	
Z4PD	27/12/2013	6:00:00	2060-10-20-02-VCU4029	SG	10413094	1W Inspection SVS 525C	Y13W52
Z4PD	20/12/2013	6:00:00	2060-10-20-02-VCU4029	SG	10406719	1W Inspection SVS 525C	Y13W51
Z4PD	15/12/2013	6:00:00	2060-10-20-02-VCU4029	SG	10401401	1W Inspection SVS 525C	Y13W50
20EL	14/12/2013	6:00:00	2060-10-20-02-VCU4029	MI	20277082	Replace 2 x prox antennas	
Z4PD	7/12/2013	6:00:00	2060-10-20-02-VCU4029	SG	10318470	250H PM Service SVS 525C Chargeup	Y13W49
Z4PD	6/12/2013	6:00:00	2060-10-20-02-VCU4029	SG	10395648	1W Inspection SVS 525C	Y13W49
Z4PD	6/12/2013	6:00:00	2060-10-20-02-VCU4029-OPCB	MI	20257441	Replace A/C filter	Y13W49
Z4PD	29/11/2013	6:00:00	2060-10-20-02-VCU4029	SG	10389912	1W Inspection SVS 525C	Y13W48
Z4PD	25/11/2013	0:00:00	2060-10-20-02-VCU4029-FSSY	SG	10337551	6M Fire Suppression Inspection Mobile	
Z4PD	23/11/2013	0:00:00	2060-10-20-02-VCU4029-FRBO-AESY	MN	20266864	FIT GRAB RAIL	
Z4PD	22/11/2013	6:00:00	2060-10-20-02-VCU4029	SG	10383933	1W Inspection SVS 525C	Y13W47
20EL	21/11/2013	6:00:00	2060-10-20-02-VCU4029	MI	20266225	Replace cracked touch screen	
Z4PD	21/11/2013	7:00:00	2060-10-20-02-VCU4029-IMAT-BOOM-WOPL	MI	20266084	Fit handrails to basket	
Z4PD	17/11/2013	6:00:00	2060-10-20-02-VCU4029	SG	10378287	1W Inspection SVS 525C	Y13W46
Z4PD	11/11/2013	6:00:00	2060-10-20-02-VCU4029-OPCB	MI	20260913	Inspect/repair a/c efficiency	
Z4PD	9/11/2013	6:00:00	2060-10-20-02-VCU4029	SG	10372886	1W Inspection SVS 525C	Y13W45
Z4PD	2/11/2013	6:00:00	2060-10-20-02-VCU4029	SG	10367552	1W Inspection SVS 525C	Y13W44
Z4PD	2/11/2013	6:00:00	2060-10-20-02-VCU4029-IMAT-BOOM-WOPL	MI	20257150	Inspect/repair bent step on basket	
Z4PD	31/10/2013	6:00:00	2060-10-20-02-VCU4029-AISY	MI	20256121	Inspect/repair anfo peddle sticking	DBS S1
Z4PD	31/10/2013	6:00:00	2060-10-20-02-VCU4029-OPCB-ECSY	MI	20255871	Low coolant alarm, engine wont turn off	
Z4PD	27/10/2013	6:00:00	2060-10-20-02-VCU4029-AISY	MI	20253840	Comp oil blowing back into air filter	DBS S3
Z4PD	26/10/2013	6:00:00	2060-10-20-02-VCU4029	SG	10361890	1W Inspection SVS 525C	Y13W43
Z4PD	20/10/2013	0:00:00	2060-10-20-02-VCU4029-DRTR-AXA1	MI	20250078	oil leak at P1 brake housing *warranty*	DBS S1
Z4PD	19/10/2013	6:00:00	2060-10-20-02-VCU4029	SG	10355279	1W Inspection SVS 525C	Y13W42
Z4PD	17/10/2013	6:00:00	2060-10-20-02-VCU4029-OPCB-ECSY	MI	20248560	repair A/C fan motor noise	DBS S2
Z4PD	13/10/2013	6:00:00	2060-10-20-02-VCU4029	SG	10355278	1W Inspection SVS 525C	Y13W41
Z4PD	6/10/2013	0:00:00	2060-10-20-02-VCU4029-ENSY-EXSY	MI	20243077	Modify exhaust and boom plates	
Z4PD	6/10/2013	6:00:00	2060-10-20-02-VCU4029	SG	10354922	1W Inspection SVS 525C	Y13W40
Z4PD	30/09/2013	6:00:00	2060-10-20-02-VCU4029-OPCB-ECSY	MI	20239879	Electrical fault with comp cooling fan	
40LH	27/09/2013	6:00:00	2060-10-20-02-VCU4029	MN	20210048	Daily Inspection VCU4029	DBSDAILY
Z4PD	21/09/2013	6:00:00	2060-10-20-02-VCU4029	MN	20232389	Weekly Inspection	Y13W39
Z4PD	18/09/2013	6:00:00	2060-10-20-02-VCU4029-HYSY-ECSY	MI	20233798	Repair hyd control fault/Check operation	
Z4PD	15/09/2013	6:00:00	2060-10-20-02-VCU4029-IMAT-BOOM-WOPL	MI	20232611	Rectify basket dead man switch fault	
Z4PD	14/09/2013	6:00:00	2060-10-20-02-VCU4029-OPCB-ECSY	MN	20232261	Relocate Reverse Camera	
Z4PD	12/09/2013	6:00:00	2060-10-20-02-VCU4029-IMAT-BOOM-WOPL	MN	20231518	Fit New Basket Lights	

Z4PD	6/09/2013	6:00:00	2060-10-20-02-VCU4029-OPCB-ECSY	MI	20228804	Install additional reverse lights	
Z4PD	2/09/2013	6:00:00	2060-10-20-02-VCU4029	MN	20219664	Commission SVS Charge Machine	Y13W35
Z4PD	2/09/2013	6:00:00	2060-10-20-02-VCU4029-OPCB-ECSY	MN	20226294	Fit blue revolving light	Y13W36
Z4PD	1/09/2013	0:00:00	2060-10-20-02-VCU4029-DRTR-AXA1-TYW1	MN	20226270	Purchase 2 Spare Rims from Acme & Fit ty	
20EL	30/08/2013	6:00:00	2060-10-20-02-VCU4029	MN	20225472	Install radio & prox system	