

2004 Toyota HZJ79R Landcruiser Ute



Make	Toyota		Model	HZJ79R Landcruiser Tray Back		
Year	2004	Hours		As at		
Mileage	195487		km	As at	03/09/2019	
Serial/VIN	JTELB71J707040652			Engine Serial	1HZ0453750	
Details	<p>2004 Toyota HZJ79R Landcruiser Ute. NB: Bonnet latch is faulty and requires repair prior to use and no spare tyre available for this vehicle. Fuel tanks swapped October 2018. WA vehicle registration expires 30/09/2019 and transfer at the time of sale must be to a WA street address Set up with bull bar with winch and side steps, spotlights, twin batteries with isolator, undertray twin tyre storage slot (no spare), Parkside UC20 3500 kg rated towbar (no tow ball adaptor), UHF Radio and internal roll bar. Please note: Collection is only available from Monday 23rd September. This asset is offered for sale via Online Auction on an "As Is Where Is" basis ex Site Welshpool, Western Australia.</p>					
Asking price	AUD	Under review - call for pricing				

Ex site	Australia, Western Australia, Welshpool
----------------	---

Service history	Please note: Bonnet latch is faulty and requires repair prior to use. 11/10/2018 - Fuel issue rectified with the fitting of 2 fuel tanks to replace rusted tanks with new fuel filters and new air filter. Drivers side door speaker removed
------------------------	--

**For further details, to make an offer or book an inspection, contact
Global Equipment Solutions on Office: 08 9201 1142**













[Accessibility / Contact us](#)A⁺A⁻

Vehicle Licence Expiry Date Enquiry

Vehicle licence expiry date request results

Plate Number 1ELW257
This vehicle licence expires 30/09/2019
on

Important note

The information provided is only current as at 03/09/2019 03:56 PM

Transport is not responsible for how this information is interpreted or used. It is the responsibility of the vehicle licence holder or driver to determine whether the vehicle should be driven.

[DoTDirect Home](#) / [Privacy](#) / [Disclaimer](#) / [Copyright](#) © 2019 Department of Transport

Tax Invoice



Invoice # 66175

Date: Thursday, October 11, 2018
R.O.: 66175

3 Kalgan Road, Welshpool
Western Australia 6106

Phone: 9358 1441
Fax: 9358 1440
Email: service@robsonbros4wd.com.au
www.robsonbros4wd.com.au

ABN 72 605 732 232

Newmont Asia Pacific
3 Bellows Street
Welshpool WA 6106

Rego: 1ELW267
Make / Model: TOYOTA HZJ79
Engine Number: 1HZ

Speedo:
Next Service Due: 11.Apr.2019 or 158,750km

Labour

LABOUR	\$1,200.00
<ul style="list-style-type: none">- Road tested vehicle for fault - Found engine starving for fuel and blue smoke.- Renewed air filter, dedusted and cleaned filter housing.- Removed both fuel filters and found badly clogged with rust and dirt. Renewed fuel filters, bled and primed system.- Removed both fuel tanks and found rust and dirt inside - Unable to clean out.- Fitted 2x second hand tanks, swapped over sender units as required and renewed solenoids.	

Parts

1.00	A1350	AIR FILTER	\$77.36
1.00	Z252X	FUEL FILTER	\$53.64
2.00	TO-2333268010	GASKET	\$13.40
1.00	TO-2333446010	PLATE, SPRING	\$2.85
1.00	TO-2333348012	ELEMENT	\$10.63
1.00	R2590P	FUEL FILTER	\$30.27
1.00	NPN03	FUEL TANKS	\$960.00
1.00	TO-7771060180	SOLENOID VALVE	\$285.55
1.00	TO-7771060160	VALVE, MAIN SOLENOID	\$315.00
1.00	NPN01	ENVIRONMENTAL DISPOSALS	\$13.64
1.00	NPN02	WORKSHOP CONSUMABLES	\$9.09

Subtotal	\$2,971.43
G.S.T.	\$297.15
Rounding	\$0.02
Total	\$3,268.60

Tax Invoice



Invoice # **60934**

Date: Wednesday, February 24, 2016
R.O.: 60934

3 Kalgan Road, Welshpool
Western Australia 6106

Phone: 9358 1441
Fax: 9358 1440
Email: service@robsonbros4wd.com.au
www.robsonbros4wd.com.au

ABN 86 165 193 771

Newmont Asia Pacific
3 Bellows Street
Welshpool WA 6106

Rego: 1ELW267
Make / Model: TOYOTA HZJ79
Engine Number: 1HZ

Speedo: 148749
Next Service Due: 24.Aug.2016 or 158,750km

Labour

150,000KM SERVICE

\$490.90

- Carried out service as required. Renewed engine oil and filter, greased all points and checked all levels.
- Drained cooling system and renewed coolant. Pressure tested cooling system. Checked for leaks.
- Renewed air filter, dedusted and cleaned filter housing.
- Inspected front and rear brakes and reported.
Front 10% worn, Rear 10% worn.
- Renewed fuel filter x2, bled and primed system.
- Drained brake fluid, removed and cleaned reservoir. Refilled and bled system. Topped up the reservoir.
- Drained clutch fluid. Refilled and bled system. Topped up the reservoir.
- Renewed transfer case oil.
- Tightened rear diff breather fitting - No charge.

Sublet Repairs

AUTO ELECTRICS

\$397.00

- Tested aircon and serviced system. Changed dryer and regas as required. Located no air from centre vents. Fitted vent cable as required. Tested. OK.

WHEEL ALIGNMENT, TYRES, TUBE

\$705.00

- Triangle 750R16 14ply x 2.
- Tube x 4.
- Rust band x 4.
- Wheel alignment.
- Heat to free up draglinks/nuts.

MAKE UP BROWN CANOPY

\$1,500.00

- Make up brown canopy with 6 zips, rope pull downs, windows front and rear with

Paul
21/3/16