

2010 Atlas Copco S7D Simba PD04



Make	Atlas Copco		Model	S7D Simba		
Year	2010	Hours	2135		As at	01/09/2018
Mileage				km	As at	
Serial/VIN	AVO10A190, 8991845700			Engine Serial		
Details	2010 Atlas Copco S7D Simba PD04. YOM 2010 Serial no AVO10A190, 8991845700. Engine Hours estimated at 2135. Hour Meters as per photos: Pump hours showing 18265 hours, impact hours showing 73 hours and must be a changed meter. Work orders report in GES Equipment Report. Lot 0373 offered running to drive on to buyers transport. Sold via Online Auction ex Kambalda Western Australia.					
Asking price	AUD	Under review - call for pricing				
Ex site	Australia, Western Australia, Kambalda					

Service history	Fair
------------------------	------

**For further details, to make an offer or book an inspection, contact
Global Equipment Solutions on Office: 08 9201 1142**











Plant No	Date	Work Order	W/Ord Description	Work Type	History Notes	SMU Readings
PD04	4/11/2015	209305	\$ Cylinder - Stinger Changeout on condition	Component Change out		215 HR, 6667 LP
PD04	14/01/2016	214195	Rail LH Changeout (On Condition)	Component Change out		259 HR, 6929 LP
PD04	15/01/2016	214652	Cylinder - Feed Thrust Changeout on condition	Component Change out		
PD04	15/01/2016	214651	Replace Top Hat & Feed cradle	Component Change out		
PD04	5/05/2016	217055	Cylinder - Feed Thrust Changeout on condition	Component Change out		311 HR, 7251 LP
PD04	22/09/2016	225881	Cylinder - Stinger Changeout on condition	Component Change out		371 HR, 7624 LP
PD04	31/10/2016	226420	Cylinder - Feed Thrust Changeout on condition	Component Change out		
PD04	18/12/2016	227525	c/o failed pos 2 tyreold tyre s/n zz00056v1a new	Component Change out		7765 LP
PD04	26/01/2018	235595	Cylinder - Rod Handler Arms Changeout on condition	Component Change out	Replaced Both Rod Handlers worn out !	592 HR, 8549 LP
PD04	22/04/2018	237248	c/o feed rope c/o pitto jaw bolts	Component Change out		
PD04	2/05/2018	237579	Cylinder - Feed Thrust Changeout on condition	Component Change out		
PD04	11/05/2018	237739	Cylinder - Stinger Changeout on condition	Component Change out		
PD04	16/05/2018	237856	Cylinder - Stinger Changeout on condition	Component Change out		
PD04	21/05/2018	237903	Cylinder - Feed Thrust Changeout on condition	Component Change out		640 HR, 63 LP

Plant No	Date	Work Order	W/Ord Description	Work Type	History Notes	SMU Readings
PD04	23/03/2015	202464	Replaced blown hose	Breakdown		
PD04	24/03/2015	202471	No HV pilot core (Batteries u/s)Replaced batteries	Breakdown		
PD04	30/03/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	31/03/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	87 HR, 6109 LP
PD04	31/03/2015	202593	Threading fault (Adjustment & tests)	Preventative Maintenance		87 HR, 6109 LP
PD04	31/03/2015	202583	Threading u/s (Checked electricaly All OK)	Breakdown		87 HR, 6109 LP
PD04	2/04/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	87 HR, 6116 LP
PD04	2/04/2015	202670	Tap out LH lift cylinder fitting (bspt)	Breakdown		87 HR, 6116 LP
PD04	3/04/2015	202681	Adjust-Align Rod Handler	Breakdown		6117 LP
PD04	3/04/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	6117 LP
PD04	3/04/2015	202600	Record Drifter serial #	Non Maintenance		6117 LP
PD04	3/04/2015	202678	Replace CT18 valve and adjust	Preventative Maintenance		6117 LP
PD04	4/04/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	4/04/2015	202692	Shutting down on high hyd oil temp	Breakdown		
PD04	5/04/2015	202612	2 Weekly Service - Atlas 1257MEMS PM TASK 374	Preventative Maintenance		
PD04	5/04/2015	202711	Modify rear stinger end to suit k9 extension rods.	Modification		
PD04	6/04/2015	202725	Helicoil stripped clamp for rear stinger	Breakdown		89 HR, 6123 LP
PD04	6/04/2015	202720	Set up threading & put MUX back together	Breakdown		89 HR, 6123 LP
PD04	7/04/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	7/04/2015	202728	Threading fault still replace & set releif 31773092	Preventative Maintenance		
PD04	8/04/2015	202839	Replace coupling between hyd pump & elect mot	Breakdown		93 HR, 6127 LP
PD04	13/04/2015	202888	C/O blown carrier hose	Breakdown		
PD04	14/04/2015	202894	Changed out -6 blown hose in loom , rewrap and	Breakdown		96 HR, 6129 LP
PD04	14/04/2015	202896	Changed out blown -6 boom lift hose, air/ water	Breakdown		96 HR, 6129 LP
PD04	14/04/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	96 HR, 6129 LP
PD04	15/04/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	96 HR, 6129 LP
PD04	16/04/2015	202772	3 Monthly Service - ATLAS 1257MEMS PM TASK 4	Preventative Maintenance		97 HR, 6131 LP
PD04	23/04/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	98 HR, 6132 LP
PD04	24/04/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	101 HR, 6132 LP
PD04	25/04/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	101 HR, 6135 LP
PD04	25/04/2015	203061	Weld stinger sub thread,weld hose tree boltsCanc	Breakdown		101 HR, 6135 LP
PD04	26/04/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	102 HR, 6139 LP
PD04	26/04/2015	203063	No percussion from drifter	Breakdown	C/O drifter as no percussion	102 HR, 6139 LP
PD04	30/04/2015	203010	2 Weekly Service - Atlas SimbaMEMS PM TASK 37	Preventative Maintenance		106 HR, 6139 LP
PD04	1/05/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	1/05/2015	203225	Wrap hosesRepair leaks	Preventative Maintenance		
PD04	2/05/2015	203247	Blown HoseReplace rear stinger fitting co burred	Breakdown		
PD04	2/05/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	3/05/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	4/05/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	108 HR, 6150 LP
PD04	5/05/2015	203277	Blown hose with rods up the hole	Breakdown		108 HR, 6156 LP
PD04	5/05/2015	203282	Removed pito cylinder to replace u/s bolt	Breakdown		108 HR, 6156 LP
PD04	5/05/2015	203278	Replaced blown hose	Breakdown		108 HR, 6156 LP
PD04	6/05/2015	203290	Replaced blown hose & Feed faultRock jammed u	Breakdown		109 HR, 6161 LP
PD04	7/05/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	109 HR, 6162 LP
PD04	7/05/2015	203366	Replace feed rope	Breakdown		109 HR, 6162 LP
PD04	8/05/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	109 HR, 6166 LP
PD04	8/05/2015	203365	Rod Handler IssuesRemoved broken bolt Replace	Breakdown		109 HR, 6166 LP
PD04	9/05/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	109 HR, 6172 LP
PD04	10/05/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	109 HR, 6178 LP
PD04	10/05/2015	203394	Drifter jammed (Bolt fell out & jammed)Replaced	Breakdown		109 HR, 6178 LP
PD04	11/05/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	109 HR, 6180 LP
PD04	11/05/2015	203404	Jack leg not moving & cable reel faultReplaced Di	Breakdown		109 HR, 6180 LP
PD04	11/05/2015	203397	Repaired cable reel fault (DCV sticking)Replaced f	Breakdown		109 HR, 6180 LP
PD04	12/05/2015	203415	Machine shutting down (Hyd sensor u/s) Bypass	Breakdown		110 HR, 6182 LP
PD04	12/05/2015	203418	Replaced blown hose	Breakdown		110 HR, 6182 LP
PD04	13/05/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	111 HR, 6183 LP
PD04	13/05/2015	203426	Refitted feed ropeChecked on temp sensor for hy	Breakdown		111 HR, 6183 LP
PD04	13/05/2015	203431	Water DCV stickingOutriggers DCV not operating	Breakdown		111 HR, 6183 LP
PD04	14/05/2015	203179	2 Weekly Service - Atlas SimbaMEMS PM TASK 37	Preventative Maintenance	Fitted modified hose tree Squirty Fitted air wate	112 HR, 6187 LP
PD04	14/05/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	112 HR, 6187 LP
PD04	15/05/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	15/05/2015	203505	Rear stinger sheared off (Welded back on)Swopp	Breakdown		
PD04	15/05/2015	203530	Refitted rod handler pin & return rope, freed up s	Breakdown		
PD04	15/05/2015	203532	Replaced blown hosereplaced missing drifter mou	Breakdown		
PD04	16/05/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	17/05/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	17/05/2015	203541	Tighten lose slides & Chase faults (Jack legs)	Breakdown		
PD04	18/05/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	117 HR, 6203 LP
PD04	18/05/2015	203546	Fitted filter cart (Cleaning water out of hydraulic t	Corrective Maintenance		117 HR, 6203 LP
PD04	19/05/2015	203571	Freed up water reel spoolAdjusted front & rear ro	Breakdown		118 HR, 6207 LP

PD04	19/05/2015	203567	Replaced water flushing valveFeed kept kicking oi	Breakdown		118 HR, 6207 LF
PD04	20/05/2015	203585	Remonted hose reel & tightened loose fittings	Breakdown		118 HR, 6211 LF
PD04	21/05/2015	203650	Replaced leaking trans cooler	Breakdown		119 HR, 6215 LF
PD04	21/05/2015	203588	Tramming hydraulic cooler splitHas been bypassed	Breakdown	Replaced tramming cooler with secondhand uni	119 HR, 6215 LF
PD04	22/05/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	119 HR, 6218 LF
PD04	22/05/2015	203647	Replace water flushing seals	Preventative Maintenance	C/O flushing head assy	119 HR, 6218 LF
PD04	23/05/2015	203666	C/O shank water jacket	Breakdown	Stripped thread in jacket housing	120 HR, 6220 LF
PD04	23/05/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	120 HR, 6220 LF
PD04	23/05/2015	203672	Drill out broken inlet manifold bolts	Breakdown		120 HR, 6220 LF
PD04	23/05/2015	203667	Front stinger leaking fitting	Breakdown	Threads stripped in cyl -so C/O stinger cyl	120 HR, 6220 LF
PD04	24/05/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	121 HR, 6223 LF
PD04	24/05/2015	203682	Replaced u/s carrier hose	Breakdown		121 HR, 6223 LF
PD04	25/05/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	121 HR, 6227 LF
PD04	25/05/2015	203680	Replaced oring on percussion fitting	Breakdown		121 HR, 6227 LF
PD04	26/05/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	122 HR, 6229 LF
PD04	27/05/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	123 HR, 6230 LF
PD04	9/07/2015	205621	Loose terminal on oil pressure sender	Breakdown		
PD04	11/07/2015	205624	percussion not working correctly	Breakdown		
PD04	12/07/2015	205668	Adjust carosel cover, to stop rods falling out	Breakdown		
PD04	12/07/2015	205669	Carosel spinning in wrong direction	Breakdown		
PD04	14/07/2015	205682	drifter leaking oil	Breakdown	Resealed back hammer piston seals	
PD04	14/07/2015	205689	inspect stinger valves and coils	Breakdown		
PD04	14/07/2015	205688	Strip+clean water flushing valve	Breakdown		
PD04	15/07/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	132 HR, 6238 LF
PD04	15/07/2015	205720	Replace return rope	Breakdown		132 HR, 6238 LF
PD04	16/07/2015	205723	Calibrate clino	Breakdown		132 HR, 6242 LF
PD04	16/07/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	132 HR, 6242 LF
PD04	16/07/2015	205713	Replace broken return rope	Breakdown		132 HR, 6242 LF
PD04	17/07/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	132 HR, 6244 LF
PD04	17/07/2015	205730	Repair rear stinger (Thread broken off)	Damage		132 HR, 6244 LF
PD04	18/07/2015	205759	blocked water hose at drifter	Breakdown		134 HR, 6245 LF
PD04	18/07/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	134 HR, 6245 LF
PD04	18/07/2015	205749	Recalibrate Clyno.	Corrective Maintenance		134 HR, 6245 LF
PD04	18/07/2015	205756	Replace blown oring on rotation motor	Breakdown		134 HR, 6245 LF
PD04	18/07/2015	205755	Replace broken strapping bolt	Breakdown		134 HR, 6245 LF
PD04	18/07/2015	205754	Water flushing wont turn off	Breakdown	Stripped & cleaned flushing valve.	134 HR, 6245 LF
PD04	19/07/2015	205779	Replaced Mex head sealsFitted spot light	Breakdown		135 HR, 6249 LF
PD04	19/07/2015	205781	Replaced rod arm cylinder	Breakdown		135 HR, 6249 LF
PD04	20/07/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	135 HR, 6251 LF
PD04	21/07/2015	205577	2 Weekly Service - Atlas SimbaMEMS PM TASK 37	Preventative Maintenance		136 HR, 6256 LF
PD04	22/07/2015	205955	Filled fuel & bleedLost power / low hyd oil	Breakdown		
PD04	23/07/2015	205970	c/o dash hose	Breakdown		137 HR, 6258 LF
PD04	23/07/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	137 HR, 6258 LF
PD04	23/07/2015	205996	rotation fault	Breakdown		137 HR, 6258 LF
PD04	23/07/2015	205978	Water presssure issueReplaced flushing seals Tes	Breakdown		137 HR, 6258 LF
PD04	24/07/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	137 HR, 6259 LF
PD04	24/07/2015	205993	Test water output efficiency. Bypass all electric cc	Corrective Maintenance		137 HR, 6259 LF
PD04	25/07/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	26/07/2015	206040	Broken return rope bolt	Breakdown		
PD04	27/07/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	140 HR, 6275 LF
PD04	27/07/2015	206072	pilot fault on sliprings-pilot core came off in slipr	Breakdown		140 HR, 6275 LF
PD04	27/07/2015	206042	Replace broken rod handler stopper bolt	Breakdown		140 HR, 6275 LF
PD04	28/07/2015	206183	C/O flushing seals	Breakdown		
PD04	28/07/2015	206077	Check out water pressure problemsFound damp f	Breakdown		
PD04	29/07/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	144 HR, 6280 LF
PD04	29/07/2015	206176	Grundfos Water Pump Changeout on conditionPos	Breakdown		144 HR, 6280 LF
PD04	30/07/2015	206234	c/o blow drifter hose	Breakdown		146 HR, 6283 LF
PD04	30/07/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	146 HR, 6283 LF
PD04	31/07/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	148 HR, 6293 LF
PD04	1/08/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	1/08/2015	206259	Inspect faulty percussion hour meter.	Corrective Maintenance		
PD04	1/08/2015	206258	Replace mex head seals.	Corrective Maintenance		
PD04	2/08/2015	206271	C/o rotation hose -8x2.6m.	Breakdown		
PD04	2/08/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	2/08/2015	206280	Replace 2 missing pito jaw bolts	Breakdown		
PD04	3/08/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	151 HR, 6302 LF
PD04	4/08/2015	205815	6 Monthly Service - Atlas SimbaMEMS PM TASK 4	Preventative Maintenance		153 HR, 6306 LF
PD04	4/08/2015	206347	Fit engine cover	Breakdown		153 HR, 6306 LF
PD04	4/08/2015	206366	No full percussion, no dampening.	Breakdown		153 HR, 6306 LF
PD04	4/08/2015	206380	rod alignment	Breakdown		153 HR, 6306 LF
PD04	5/08/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	5/08/2015	206367	No dampening or full percussion pressure.	Breakdown		
PD04	6/08/2015	206405	Dampening very erratic 38 to 130 barBypassed flc	Corrective Maintenance		
PD04	7/08/2015	206492	Blown hyd hose.	Breakdown		156 HR, 6308 LF

PD04	7/08/2015	206502	co 2 blown -6 hoses	Breakdown		156 HR, 6308 LP
PD04	7/08/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	156 HR, 6308 LP
PD04	7/08/2015	206505	rotation motor leaking oil	Breakdown		156 HR, 6308 LP
PD04	7/08/2015	206456	Water wheel not retracting.	Corrective Maintenance		156 HR, 6308 LP
PD04	8/08/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	9/08/2015	206517	2x Broken hose ends. Re-wrap loom without clyn	Breakdown		157 HR, 6317 LP
PD04	9/08/2015	206522	C/O 2x -6 hoses + 3 broken fittings	Breakdown		157 HR, 6317 LP
PD04	9/08/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	157 HR, 6317 LP
PD04	10/08/2015	206566	compressor not unloading	Breakdown		
PD04	10/08/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	10/08/2015	206571	Return rope come off sheave wheel	Breakdown		
PD04	11/08/2015	206664	calibrate all sensors	Breakdown		158 HR, 6323 LP
PD04	11/08/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	158 HR, 6323 LP
PD04	11/08/2015	206574	Help op remove broken shank and C/O flushing s	Breakdown		158 HR, 6323 LP
PD04	11/08/2015	206657	tighten loose pito and rod handler bolts	Breakdown		158 HR, 6323 LP
PD04	12/08/2015	206677	C/o broken rotation fitting -12 elbow.	Breakdown		
PD04	12/08/2015	206692	C/o Drifter hose 2.3m -12.	Breakdown		
PD04	12/08/2015	206665	C/O rotation motor fittings x2	Breakdown		
PD04	12/08/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	12/08/2015	206702	Return rope fell off	Breakdown		
PD04	13/08/2015	206717	No threading or unthreading	Breakdown		159 HR, 6338 LP
PD04	13/08/2015	206709	repair broken drifter mount	Breakdown		159 HR, 6338 LP
PD04	13/08/2015	206711	repair rotation motor alignment	Breakdown		159 HR, 6338 LP
PD04	14/08/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	15/08/2015	206752	adjust dampening pressure.	Breakdown	Reset dampening pressure to 40 bar.	162 HR, 6350 LP
PD04	15/08/2015	207000	Cylinder - Feed Thrust Changeout on condition	Breakdown		162 HR, 6350 LP
PD04	15/08/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	162 HR, 6350 LP
PD04	15/08/2015	206746	Repair carousel not turning	Breakdown	Carousel not turning - Adj flow restrictor.	162 HR, 6350 LP
PD04	16/08/2015	206763	Change out 3 front straping bolts	Breakdown		162 HR, 6357 LP
PD04	16/08/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	162 HR, 6357 LP
PD04	17/08/2015	206843	hydraulics over heating	Breakdown		162 HR, 6360 LP
PD04	17/08/2015	206861	Re-gas accumulators and run up for lube.	Corrective Maintenance		162 HR, 6360 LP
PD04	17/08/2015	206862	Swap over rotation hoses.	Breakdown		162 HR, 6360 LP
PD04	18/08/2015	206930	High oil temp light onReplaced blown fuse	Breakdown		164 HR, 6363 LP
PD04	18/08/2015	206929	No water faultReplaced blocked hose	Breakdown		164 HR, 6363 LP
PD04	18/08/2015	206922	Simba wouldn't start on power pack and hydraulic	Breakdown		164 HR, 6363 LP
PD04	19/08/2015	206530	2 Weekly Service - Atlas SimbaMEMS PM TASK 37	Preventative Maintenance		164 HR, 6365 LP
PD04	20/08/2015	206982	Adjust rod alignment.Inspect drifter timing. Tight	Corrective Maintenance		167 HR, 6366 LP
PD04	20/08/2015	206954	c/o broken return rope	Breakdown		167 HR, 6366 LP
PD04	20/08/2015	206983	C/O feed rope.	Breakdown		167 HR, 6366 LP
PD04	20/08/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	167 HR, 6366 LP
PD04	21/08/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	167 HR, 6369 LP
PD04	22/08/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	23/08/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	23/08/2015	207039	Inspect outrigger faultGrease drifter. Fit -4 air ho	Corrective Maintenance		
PD04	24/08/2015	207049	Blown -8 hose.	Breakdown		169 HR, 6382 LP
PD04	25/08/2015	207064	Adjust rod alignment	Breakdown		
PD04	25/08/2015	207152	check drifter faults.	Breakdown		
PD04	25/08/2015	207057	Drain Tarnsfer case & F/R Final Drive at start of s	Corrective Maintenance		
PD04	25/08/2015	207063	Put return rope back on wheel	Breakdown		
PD04	25/08/2015	207151	remove bit from guide tube.	Breakdown		
PD04	25/08/2015	207061	Threading fault	Breakdown		
PD04	26/08/2015	207164	Bolt sensor bracket back on boom	Corrective Maintenance		171 HR, 6399 LP
PD04	26/08/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	171 HR, 6399 LP
PD04	26/08/2015	207186	Make up new hose for water tap	Corrective Maintenance		171 HR, 6399 LP
PD04	28/08/2015	207228	1x blown drifter hoses + 2x u/s hoses	Breakdown		172 HR, 6406 LP
PD04	28/08/2015	207213	blown -8 hose +replaced damaged double check	Breakdown		172 HR, 6406 LP
PD04	28/08/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	172 HR, 6406 LP
PD04	29/08/2015	207230	2x blown drifter hoses+c/o L/P & H.P acumulator	Breakdown	Adj threading,C/O HP &LP accumulators & 2X	172 HR, 6409 LP
PD04	29/08/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	172 HR, 6409 LP
PD04	29/08/2015	207231	Recalibrate clino	Breakdown		172 HR, 6409 LP
PD04	30/08/2015	207234	change out blown "12 hyd hose	Breakdown		173 HR, 6419 LP
PD04	30/08/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	173 HR, 6419 LP
PD04	31/08/2015	207275	change hose.	Breakdown		174 HR, 6424 LP
PD04	31/08/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	174 HR, 6424 LP
PD04	31/08/2015	207276	rod handlers loose on rail	Breakdown		174 HR, 6424 LP
PD04	1/09/2015	206910	2 Weekly Service - Atlas SimbaMEMS PM TASK 37	Preventative Maintenance		175 HR, 6429 LP
PD04	1/09/2015	207385	no power to clino	Breakdown		175 HR, 6429 LP
PD04	2/09/2015	207398	Clino sensor faultReplaced 9106219203 x 2 Repl	Breakdown		176 HR, 6430 LP
PD04	2/09/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	176 HR, 6430 LP
PD04	2/09/2015	207386	secure loose front work light bracket	Breakdown		176 HR, 6430 LP
PD04	3/09/2015	207427	C/O -8 rotation hose.	Breakdown		176 HR, 6435 LP
PD04	4/09/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	4/09/2015	207446	Fit Return rope + new grease drum	Breakdown		

PD04	5/09/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	177 HR, 6441 LF
PD04	5/09/2015	207470	fit new bush to mux hed	Breakdown		177 HR, 6441 LF
PD04	5/09/2015	207471	water fault	Breakdown		177 HR, 6441 LF
PD04	6/09/2015	207488	Replace rod arm jaw role pin.C/O -12 hose.	Breakdown		177 HR, 6445 LF
PD04	8/09/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	9/09/2015	207745	c/o drifter hoses	Breakdown		178 HR, 6457 LF
PD04	9/09/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	178 HR, 6457 LF
PD04	9/09/2015	207697	No boosted water pressure. Water pump not o	Breakdown		178 HR, 6457 LF
PD04	10/09/2015	207770	C/O -8 hose	Breakdown		178 HR, 6464 LF
PD04	10/09/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	178 HR, 6464 LF
PD04	11/09/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	12/09/2015	207800	replace broken drifter bolt	Breakdown		180 HR, 6474 LF
PD04	13/09/2015	207803	change hose	Breakdown		181 HR, 6479 LF
PD04	13/09/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	181 HR, 6479 LF
PD04	13/09/2015	207806	Replace mux head seals.	Breakdown		181 HR, 6479 LF
PD04	14/09/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	181 HR, 6487 LF
PD04	14/09/2015	207818	Remount RH pito jaw.Drill out snapped bolt.	Breakdown		181 HR, 6487 LF
PD04	15/09/2015	207812	c/o blown hyd ""12 hose	Breakdown		181 HR, 6494 LF
PD04	15/09/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	181 HR, 6494 LF
PD04	15/09/2015	207958	Fit 3x missing bolts for pito jaws. (LHS)	Breakdown		181 HR, 6494 LF
PD04	15/09/2015	207959	Re-build dampening accumulator.	Breakdown		181 HR, 6494 LF
PD04	15/09/2015	207960	Replace percussion hose.	Breakdown		181 HR, 6494 LF
PD04	16/09/2015	207739	2 Weekly Service - Atlas SimbaMEMS PM TASK 37	Preventative Maintenance		181 HR, 6497 LF
PD04	16/09/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	181 HR, 6497 LF
PD04	16/09/2015	207999	Replaced Rod Handler Pads	Breakdown		181 HR, 6497 LF
PD04	17/09/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	17/09/2015	208005	No canopy movementreplaced u/s d.c.v	Breakdown		
PD04	18/09/2015	208014	Blown -8 hose.	Breakdown		183 HR, 6509 LF
PD04	18/09/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	183 HR, 6509 LF
PD04	18/09/2015	208015	Poor holding power from pitto assembly.	Breakdown		183 HR, 6509 LF
PD04	19/09/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	185 HR, 6511 LF
PD04	20/09/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	185 HR, 6516 LF
PD04	20/09/2015	208013	Full percussion erratic.	Corrective Maintenance	Charged Accumulators to 90 & 22 bar	185 HR, 6516 LF
PD04	21/09/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	186 HR, 6521 LF
PD04	22/09/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	186 HR, 6528 LF
PD04	22/09/2015	208089	Replace flushing seals.Drill out M12 snapped bolt.	Breakdown		186 HR, 6528 LF
PD04	23/09/2015	208119	repair rear stinger not coming out	Breakdown		186 HR, 6530 LF
PD04	24/09/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	186 HR, 6533 LF
PD04	24/09/2015	208129	replace loose pitto jaw bolts	Breakdown		186 HR, 6533 LF
PD04	25/09/2015	208138	c/o flushing head U-cup seals - no seal kits at 15L	Corrective Maintenance		188 HR, 6539 LF
PD04	25/09/2015	208142	Canopy up and down fault	Breakdown		188 HR, 6539 LF
PD04	25/09/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	188 HR, 6539 LF
PD04	25/09/2015	208148	Pitto jaw bolts u/s	Breakdown		188 HR, 6539 LF
PD04	26/09/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	188 HR, 6540 LF
PD04	26/09/2015	208179	Tighten loose fitting under rig	Breakdown		188 HR, 6540 LF
PD04	27/09/2015	208181	repair compressor	Breakdown		189 HR, 6547 LF
PD04	28/09/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	189 HR, 6554 LF
PD04	29/09/2015	208198	Bleed off canopy cylinders to lower canopy.Servic	Breakdown		190 HR, 6559 LF
PD04	29/09/2015	208337	c/o -4 hose under dash	Breakdown		190 HR, 6559 LF
PD04	29/09/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	190 HR, 6559 LF
PD04	29/09/2015	208330	rotation fault	Breakdown	C/O drill - threading C/O valves X2	190 HR, 6559 LF
PD04	30/09/2015	207918	2 Weekly Service - Atlas SimbaMEMS PM TASK 37	Preventative Maintenance		190 HR, 6560 LF
PD04	30/09/2015	208339	C/O u/s pitto jaw bolts	Breakdown		190 HR, 6560 LF
PD04	30/09/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	190 HR, 6560 LF
PD04	1/10/2015	208419	C/o return rope	Breakdown		192 HR, 6565 LF
PD04	1/10/2015	208399	Canopy not working	Breakdown		192 HR, 6565 LF
PD04	1/10/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	192 HR, 6565 LF
PD04	1/10/2015	208400	No hydraulics on diesel	Breakdown		192 HR, 6565 LF
PD04	1/10/2015	208401	Remount front spotlight	Breakdown		192 HR, 6565 LF
PD04	1/10/2015	208392	Stingers not working?	Breakdown		192 HR, 6565 LF
PD04	2/10/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	192 HR, 6568 LF
PD04	2/10/2015	208446	Remove and replace snaped front stinger bolts	Corrective Maintenance		192 HR, 6568 LF
PD04	2/10/2015	208420	Simba in 649 had no pilot, found it had a bad con	Breakdown		192 HR, 6568 LF
PD04	3/10/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	193 HR, 6572 LF
PD04	3/10/2015	208460	Reseal flushing head	Breakdown		193 HR, 6572 LF
PD04	4/10/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	193 HR, 6572 LF
PD04	5/10/2015	208486	broken return rope bolt	Breakdown		195 HR, 6577 LF
PD04	5/10/2015	208495	C/O -12 hose	Corrective Maintenance		195 HR, 6577 LF
PD04	5/10/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	195 HR, 6577 LF
PD04	5/10/2015	208467	leaver kick out fault	Corrective Maintenance		195 HR, 6577 LF
PD04	6/10/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	195 HR, 6583 LF
PD04	6/10/2015	208475	levers kicking out	Breakdown		195 HR, 6583 LF
PD04	7/10/2015	208515	C/O air mist check valve.	Breakdown		
PD04	7/10/2015	208506	c/o flushing head seals	Breakdown		

PD04	7/10/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	7/10/2015	208518	Replace hydraulic oil filters and sample oil.	Preventative Maintenance		
PD04	7/10/2015	208507	reseal shuttel vavle	Breakdown		
PD04	7/10/2015	208502	rotation fault	Breakdown		
PD04	7/10/2015	208503	stinger fault	Breakdown		
PD04	7/10/2015	208514	Strugled to go uphill.Top up hyd oil and allow rig	Breakdown		
PD04	7/10/2015	208513	Tighten loose rotation motor bolts.	Corrective Maintenance		
PD04	8/10/2015	208526	Canopy DCV sticking, free up spool	Breakdown		197 HR, 6587 LF
PD04	8/10/2015	208527	Clino Resolver Module Error - Check X1 + X2/X3 c	Breakdown		197 HR, 6587 LF
PD04	8/10/2015	208517	Test voltage at rear and front stinger DCV's.(26v)	Breakdown		197 HR, 6587 LF
PD04	8/10/2015	208516	Tighten loose plug on DCV for canopy.	Breakdown		197 HR, 6587 LF
PD04	9/10/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	9/10/2015	208529	Refit front bumper with new bolts	Breakdown		
PD04	9/10/2015	208546	Retime Drifter forward	Breakdown		
PD04	10/10/2015	208558	C/O -6 Pito jaw hose	Breakdown		198 HR, 6590 LF
PD04	10/10/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	198 HR, 6590 LF
PD04	11/10/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	199 HR, 6597 LF
PD04	12/10/2015	208577	C/O blown -8 hose.	Breakdown		199 HR, 6601 LF
PD04	12/10/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	199 HR, 6601 LF
PD04	12/10/2015	208578	Refit mux and flushing head.	Breakdown		199 HR, 6601 LF
PD04	13/10/2015	208485	canopy and out rigger fault	Breakdown		199 HR, 6604 LF
PD04	13/10/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	199 HR, 6604 LF
PD04	14/10/2015	208324	2 Weekly Service - Atlas Simba - DayshiftMEMS P	Preventative Maintenance		200 HR, 6607 LF
PD04	14/10/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	200 HR, 6607 LF
PD04	15/10/2015	208780	Cylinder - Rod Handler Arms Changeout on condit	Breakdown	Replaced Both Rod Handlers worn out !	201 HR, 6609 LF
PD04	15/10/2015	208765	Remove snapped strapping bolt	Breakdown		201 HR, 6609 LF
PD04	16/10/2015	208795	C/O -8 hose.	Breakdown		201 HR, 6613 LF
PD04	16/10/2015	208784	change two blown hoses	Breakdown		201 HR, 6613 LF
PD04	16/10/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	201 HR, 6613 LF
PD04	16/10/2015	208779	Replaced blown hose	Breakdown		201 HR, 6613 LF
PD04	17/10/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	202 HR, 6615 LF
PD04	18/10/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	203 HR, 6619 LF
PD04	19/10/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	203 HR, 6621 LF
PD04	20/10/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	204 HR, 6625 LF
PD04	20/10/2015	208818	Lazer Fault (Fault find & order part)3127995209 €	Breakdown		204 HR, 6625 LF
PD04	22/10/2015	208981	C/O -6 hose x6.	Breakdown		207 HR, 6629 LF
PD04	22/10/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	207 HR, 6629 LF
PD04	22/10/2015	208843	Fit filter cart to hyd return oil supply.	Corrective Maintenance		207 HR, 6629 LF
PD04	22/10/2015	208974	fit new rod stopper and straighten rod guid arm	Breakdown		207 HR, 6629 LF
PD04	22/10/2015	208972	hyd over temp fualt	Breakdown		207 HR, 6629 LF
PD04	22/10/2015	208965	Shutting down on hyd oil temp	Breakdown		207 HR, 6629 LF
PD04	24/10/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	208 HR, 6632 LF
PD04	24/10/2015	208997	U/S pull rope.	Breakdown		208 HR, 6632 LF
PD04	25/10/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	209 HR, 6634 LF
PD04	26/10/2015	209057	Simba fault- tripped sub on E/L, found mud in bak	Breakdown		209 HR, 6635 LF
PD04	27/10/2015	208918	3 Monthly Service - ATLAS Simba - DayshiftMEMS	Preventative Maintenance		210 HR, 6639 LF
PD04	28/10/2015	209165	Regas low and high pressure accumaltors	Breakdown		210 HR, 6639 LF
PD04	28/10/2015	209161	Replace u/s Carrier Hose.	Breakdown		210 HR, 6639 LF
PD04	29/10/2015	209196	C/o Blown Percussion hose.	Breakdown		
PD04	29/10/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	29/10/2015	209182	fix leaks, fix light,change valve, adjust lazer.	Breakdown		
PD04	29/10/2015	209164	Remount rod handler bracket	Breakdown		
PD04	29/10/2015	209195	Replace Faulty Lazer (Warranty).	Corrective Maintenance		
PD04	29/10/2015	209178	Replace X8 Clyno Cable.Lost CAN communication?	Breakdown		
PD04	29/10/2015	209185	when pressing the start button the rig would start	Breakdown		
PD04	30/10/2015	209197	C/o Blown Pilot Hose 4m -4.	Breakdown		212 HR, 6651 LF
PD04	30/10/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	212 HR, 6651 LF
PD04	30/10/2015	209183	replace clino cable	Breakdown		212 HR, 6651 LF
PD04	31/10/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	212 HR, 6657 LF
PD04	1/11/2015	209226	C/O return rope.	Breakdown		212 HR, 6662 LF
PD04	1/11/2015	209249	Test port under power pack leaking.	Preventative Maintenance		212 HR, 6662 LF
PD04	2/11/2015	209263	c/o blown hose	Breakdown		213 HR, 6665 LF
PD04	2/11/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	213 HR, 6665 LF
PD04	2/11/2015	209275	Tighten loose fitting under dash.	Breakdown		213 HR, 6665 LF
PD04	3/11/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	213 HR, 6666 LF
PD04	4/11/2015	209305	\$ Cylinder - Stinger Changeout on condition	Component Change out		215 HR, 6667 LF
PD04	4/11/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	215 HR, 6667 LF
PD04	4/11/2015	209427	Fix oil leak dripping on exhaust cause it to smoke	Breakdown		215 HR, 6667 LF
PD04	5/11/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	217 HR, 6668 LF
PD04	5/11/2015	209447	Replace U/s return rope	Breakdown		217 HR, 6668 LF
PD04	5/11/2015	209439	Return rope came loose and came off againbolts	Breakdown		217 HR, 6668 LF
PD04	5/11/2015	209438	Return rope fell off rear pulley, remount rope& ch	Breakdown		217 HR, 6668 LF
PD04	6/11/2015	209449	Adjust rod handlers	Breakdown		217 HR, 6668 LF
PD04	6/11/2015	209470	C/O LP Accumulator and blown hose	Breakdown		217 HR, 6668 LF

PD04	6/11/2015	209465	C/O Twisted Return Rope and blown -08 rollover	Breakdown		217 HR, 6668 LF
PD04	6/11/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	217 HR, 6668 LF
PD04	6/11/2015	209448	Fab up new return guide	Breakdown		217 HR, 6668 LF
PD04	6/11/2015	209461	Fire Alarm light was on, unplugged pressure switc	Breakdown		217 HR, 6668 LF
PD04	7/11/2015	209485	c/o blown -6 rollover hose rewrap loom	Breakdown		218 HR, 6673 LF
PD04	7/11/2015	209488	Clino Fault - Clean X1 and X2/3 Plugs - Came goo	Breakdown		218 HR, 6673 LF
PD04	7/11/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	218 HR, 6673 LF
PD04	7/11/2015	209475	Replace leaking test fitting on CT block.	Corrective Maintenance		218 HR, 6673 LF
PD04	8/11/2015	209491	40L hyd oil	Breakdown		219 HR, 6676 LF
PD04	8/11/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	219 HR, 6676 LF
PD04	9/11/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	219 HR, 6682 LF
PD04	10/11/2015	209127	2 Weekly Service - Atlas Simba - DayshiftMEMS P	Preventative Maintenance		220 HR, 6685 LF
PD04	10/11/2015	209514	change hose, wash for service day	Breakdown		220 HR, 6685 LF
PD04	10/11/2015	209527	make j bar, perc fault, fix spot light.	Breakdown		220 HR, 6685 LF
PD04	11/11/2015	209641	c/o blown carrier hose	Breakdown		222 HR, 6687 LF
PD04	11/11/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	222 HR, 6687 LF
PD04	12/11/2015	209647	Adjust rod arm alignment. (both)Free up accelera	Corrective Maintenance		
PD04	12/11/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	12/11/2015	209656	Repaired oil leak	Breakdown		
PD04	13/11/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	224 HR, 6705 LF
PD04	13/11/2015	209675	Repair spot light & C/O LH shuttle o-ring.	Corrective Maintenance		224 HR, 6705 LF
PD04	14/11/2015	209694	C/O DCV o-rings.	Corrective Maintenance		
PD04	14/11/2015	209669	clino electrical fault	Breakdown		
PD04	14/11/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	15/11/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	224 HR, 6710 LF
PD04	16/11/2015	209709	Canopy fault.	Breakdown		
PD04	16/11/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	17/11/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	225 HR, 6712 LF
PD04	18/11/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	19/11/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	226 HR, 6719 LF
PD04	20/11/2015	209726	clino fault	Breakdown		228 HR, 6723 LF
PD04	20/11/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	228 HR, 6723 LF
PD04	20/11/2015	209836	Replace Resolver cable3176001772	Corrective Maintenance		228 HR, 6723 LF
PD04	21/11/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	229 HR, 6732 LF
PD04	21/11/2015	209881	Feed Rope pulled Lug out of Table. Modify.	Breakdown		229 HR, 6732 LF
PD04	22/11/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	229 HR, 6735 LF
PD04	23/11/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	229 HR, 6737 LF
PD04	24/11/2015	209606	2 Weekly Service - Atlas Simba - DayshiftMEMS P	Preventative Maintenance		230 HR, 6742 LF
PD04	24/11/2015	209918	Blown hose on carrier.	Breakdown		230 HR, 6742 LF
PD04	24/11/2015	209958	Engine stalls under load.	Corrective Maintenance		230 HR, 6742 LF
PD04	24/11/2015	209702	Replace seat	Corrective Maintenance		230 HR, 6742 LF
PD04	25/11/2015	209960	replace sheared bolt on drifter	Breakdown		
PD04	25/11/2015	209957	Very poor boring.	Corrective Maintenance		
PD04	26/11/2015	209978	c/o both acumalators	Corrective Maintenance		232 HR, 6747 LF
PD04	26/11/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	232 HR, 6747 LF
PD04	26/11/2015	210030	rod handler stopper broke off	Breakdown		232 HR, 6747 LF
PD04	27/11/2015	210045	\$replace flushing head seals	Breakdown		235 HR, 6755 LF
PD04	27/11/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	235 HR, 6755 LF
PD04	28/11/2015	210049	change 4 broken hose fittings	Breakdown		237 HR, 6759 LF
PD04	28/11/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	237 HR, 6759 LF
PD04	28/11/2015	210054	fix broken bolt in flushing head and reseal	Breakdown		237 HR, 6759 LF
PD04	29/11/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	237 HR, 6766 LF
PD04	30/11/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	238 HR, 6771 LF
PD04	1/12/2015	210094	C/o Return Rope.	Breakdown		238 HR, 6775 LF
PD04	1/12/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	238 HR, 6775 LF
PD04	1/12/2015	210086	repair broken cylinder fittings	Breakdown		238 HR, 6775 LF
PD04	2/12/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	240 HR, 6785 LF
PD04	2/12/2015	210181	repair oil leak on rod arms and stop them from hi	Corrective Maintenance		240 HR, 6785 LF
PD04	3/12/2015	210195	C/O Blown -06 Hose	Breakdown		
PD04	3/12/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	3/12/2015	210197	Replace blown -8 hose	Breakdown		
PD04	4/12/2015	210210	C/O U/S Drifter Fitting	Breakdown		240 HR, 6789 LF
PD04	4/12/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	240 HR, 6789 LF
PD04	5/12/2015	210228	Adjust alignment.	Corrective Maintenance		242 HR, 6792 LF
PD04	5/12/2015	210215	C/O grease hose at handle.	Corrective Maintenance		242 HR, 6792 LF
PD04	5/12/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	242 HR, 6792 LF
PD04	5/12/2015	210216	Replace mux head.	Corrective Maintenance		242 HR, 6792 LF
PD04	6/12/2015	210232	C/O u/s perc hose.	Breakdown		243 HR, 6795 LF
PD04	6/12/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	243 HR, 6795 LF
PD04	7/12/2015	210248	C/o u/s hose	Breakdown		243 HR, 6802 LF
PD04	7/12/2015	210249	Repair leaking rotation block.	Corrective Maintenance		243 HR, 6802 LF
PD04	7/12/2015	210252	Repair u/s flushing head.	Corrective Maintenance		243 HR, 6802 LF
PD04	8/12/2015	210140	2 Weekly Service - Atlas Simba - DayshiftMEMS P	Preventative Maintenance		244 HR, 6807 LF
PD04	9/12/2015	210353	C/o bearing in rear idler pulley.	Corrective Maintenance		245 HR, 6809 LF

PD04	9/12/2015	210352	C/o snapped pull rope.	Breakdown		245 HR, 6809 LF
PD04	9/12/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	245 HR, 6809 LF
PD04	9/12/2015	210361	replace x6 hoesighten feed rope	Breakdown		245 HR, 6809 LF
PD04	10/12/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	246 HR, 6815 LF
PD04	10/12/2015	210380	refit feed rope	Breakdown		246 HR, 6815 LF
PD04	10/12/2015	210379	remount hose reel	Corrective Maintenance		246 HR, 6815 LF
PD04	11/12/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	247 HR, 6821 LF
PD04	12/12/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	12/12/2015	210412	Remove damaged Pito Jaw Pad Bolt. Replace/Ret	Breakdown		
PD04	13/12/2015	210424	c/o u/s pitto jaw bolts	Breakdown		
PD04	13/12/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	13/12/2015	210414	oil leaking from boom fitting	Breakdown		
PD04	14/12/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	249 HR, 6837 LF
PD04	15/12/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	249 HR, 6845 LF
PD04	15/12/2015	210458	Remount return rope pulley	Breakdown		249 HR, 6845 LF
PD04	16/12/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	16/12/2015	210666	remove pito jaw, take to w/shop /cut bolt out ret	Breakdown		
PD04	17/12/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	251 HR, 6852 LF
PD04	17/12/2015	214010	rod arm adjustment, water leak, flushing seals	Breakdown		251 HR, 6852 LF
PD04	18/12/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	392 HR, 6859 LF
PD04	18/12/2015	214025	Move Feed Rope Ladder Pin To Adjust Drifter Tim	Breakdown		392 HR, 6859 LF
PD04	18/12/2015	214034	repair rod handlers	Breakdown		392 HR, 6859 LF
PD04	19/12/2015	208612	Alternator siezed during Daily, C/O AlternatorRefit	Breakdown		251 HR, 6862 LF
PD04	19/12/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	251 HR, 6862 LF
PD04	20/12/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	251 HR, 6862 LF
PD04	21/12/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	253 HR, 6862 LF
PD04	22/12/2015	210549	2 Weekly Service - Atlas Simba - DayshiftMEMS P	Preventative Maintenance		254 HR, 6867 LF
PD04	22/12/2015	214084	C/o damaged hyd fittings.	Breakdown		254 HR, 6867 LF
PD04	23/12/2015	214093	c/o return rope, re seal mux head, c/o broken fitt	Breakdown		254 HR, 6869 LF
PD04	23/12/2015	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	254 HR, 6869 LF
PD04	2/01/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	255 HR, 6873 LF
PD04	3/01/2016	214118	Cable reel switch not holding on retraction.	Corrective Maintenance		
PD04	3/01/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	3/01/2016	214122	Replace governor on compressor.	Corrective Maintenance		
PD04	3/01/2016	214114	Threading timing requires adjustment.	Corrective Maintenance		
PD04	4/01/2016	214125	Boom sensors not reliable for drill plan.	Breakdown		255 HR, 6877 LF
PD04	4/01/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	255 HR, 6877 LF
PD04	5/01/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	256 HR, 6882 LF
PD04	5/01/2016	214173	End centraliser bolts stripped from rail.	Corrective Maintenance		256 HR, 6882 LF
PD04	5/01/2016	214112	Feed extends whilst tramming.	Corrective Maintenance		256 HR, 6882 LF
PD04	5/01/2016	214182	Poor boring. Percussion pressure down.	Corrective Maintenance		256 HR, 6882 LF
PD04	6/01/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	256 HR, 6888 LF
PD04	6/01/2016	214212	replace dash 6 hose	Breakdown		256 HR, 6888 LF
PD04	7/01/2016	214229	C/O Blown -06 hose	Breakdown		256 HR, 6895 LF
PD04	7/01/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	256 HR, 6895 LF
PD04	8/01/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	9/01/2016	214239	Clino Fault	Breakdown		257 HR, 6908 LF
PD04	9/01/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	257 HR, 6908 LF
PD04	11/01/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	258 HR, 6914 LF
PD04	12/01/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	258 HR, 6920 LF
PD04	12/01/2016	214306	Water screen damaged. Make new hose to bypas	Breakdown		258 HR, 6920 LF
PD04	13/01/2016	214322	c/o blown hose	Breakdown		258 HR, 6925 LF
PD04	13/01/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	258 HR, 6925 LF
PD04	14/01/2016	214177	2 Weekly Electrical Service - Drills 23-105001-01	Preventative Maintenance		259 HR, 6929 LF
PD04	14/01/2016	214325	2 Weekly Service - Atlas Simba - DayshiftMEMS P	Preventative Maintenance		259 HR, 6929 LF
PD04	14/01/2016	214195	Rail LH Changeout (On Condition)	Component Change out		259 HR, 6929 LF
PD04	15/01/2016	214652	Cylinder - Feed Thrust Changeout on condition	Component Change out		
PD04	15/01/2016	214651	Replace Top Hat & Feed cradle	Component Change out		
PD04	18/01/2016	214496	Adjust rod arms and drifter slides.Tighten loose fi	Corrective Maintenance		
PD04	18/01/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	19/01/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	261 HR, 6935 LF
PD04	19/01/2016	214514	Tension loose drifter shoes.	Breakdown		261 HR, 6935 LF
PD04	20/01/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	262 HR, 6943 LF
PD04	21/01/2016	214548	\$C/O -6 hose.	Breakdown		262 HR, 6945 LF
PD04	21/01/2016	214536	c/o top l/h clip on	Breakdown		262 HR, 6945 LF
PD04	21/01/2016	214626	Change green death switch for clino monitor.	Breakdown		262 HR, 6945 LF
PD04	21/01/2016	214631	clino repairs	Breakdown		262 HR, 6945 LF
PD04	21/01/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	262 HR, 6945 LF
PD04	21/01/2016	214620	Grease pump air inlet blocked, clean out and test	Corrective Maintenance		262 HR, 6945 LF
PD04	21/01/2016	214623	repair clino	Breakdown		262 HR, 6945 LF
PD04	22/01/2016	214664	C/O top RH clip on.	Breakdown		263 HR, 6951 LF
PD04	22/01/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	263 HR, 6951 LF
PD04	25/01/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	263 HR, 6951 LF
PD04	25/01/2016	214665	Hydro oil filler fault.	Corrective Maintenance		263 HR, 6951 LF

PD04	26/01/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	263 HR, 6957 LF
PD04	27/01/2016	214751	compressor not working	Breakdown		264 HR, 6968 LF
PD04	27/01/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	264 HR, 6968 LF
PD04	28/01/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	264 HR, 6975 LF
PD04	28/01/2016	214763	Lost Pilot Circit.R/H E-stop full of water. Gland on	Breakdown		264 HR, 6975 LF
PD04	28/01/2016	214762	Lost water Pressure then Flow.	Breakdown		264 HR, 6975 LF
PD04	29/01/2016	214600	6 Monthly Service - Atlas Simba - DayshiftMEMS F	Preventative Maintenance		265 HR, 6982 LF
PD04	1/02/2016	214861	c/o broken fitting in hyd water cooler	Breakdown		
PD04	1/02/2016	214858	Clino fault.	Breakdown		
PD04	1/02/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	1/02/2016	214853	Drill fault?Rotation vs Feed.	Corrective Maintenance		
PD04	1/02/2016	214854	Intermittant Shut down fault.Repair wiring to run s	Breakdown		
PD04	1/02/2016	214860	recalibrate clino	Breakdown		
PD04	1/02/2016	214862	Start fault	Breakdown		
PD04	2/02/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	267 HR, 6986 LF
PD04	2/02/2016	214867	simba cutting in and out fault	Breakdown		267 HR, 6986 LF
PD04	3/02/2016	214880	c/o blown main loom hose rewrap	Breakdown		
PD04	3/02/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	3/02/2016	214888	replace return ropestraighten rope guide	Breakdown		
PD04	4/02/2016	208631	\$Repair & weld female thread to rear stinger.	Corrective Maintenance		269 HR, 6994 LF
PD04	4/02/2016	V00012	Cat pump not energising?	Breakdown		269 HR, 6994 LF
PD04	4/02/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	269 HR, 6994 LF
PD04	4/02/2016	214977	Rebuild Pito Jaws.Hammerd to bits?	Damage		269 HR, 6994 LF
PD04	5/02/2016	215008	\$Inspect air mist switch.(will need to be looked at	Corrective Maintenance		
PD04	5/02/2016	215000	\$Re-seal MUX flushing head and fit.	Corrective Maintenance		
PD04	8/02/2016	214943	2 Weekly Service - Atlas Simba - DayshiftMEMS P	Preventative Maintenance		
PD04	8/02/2016	215035	c/o -12 hose	Breakdown		
PD04	8/02/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	8/02/2016	215079	Replace 3m-6 hose for rod handlers.	Breakdown		
PD04	9/02/2016	215094	remove muirhead off pd03 and fit to pd04	Breakdown		
PD04	9/02/2016	215093	Water and percussion fault	Breakdown		
PD04	10/02/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	271 HR, 7008 LF
PD04	10/02/2016	215082	Replace -8x2.6m Feed hose through Hell hole unc	Breakdown		271 HR, 7008 LF
PD04	11/02/2016	215124	c/o -6 pitto hose	Breakdown		
PD04	11/02/2016	215115	C/O blown outrigger hose.	Breakdown		
PD04	11/02/2016	215125	c/o leaking rollover steel pipe with ryco hose	Breakdown		
PD04	11/02/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	12/02/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	274 HR, 7010 LF
PD04	14/02/2016	215214	problem with reeming bit mode.	Breakdown		
PD04	14/02/2016	215213	repair air on/off fault	Breakdown		
PD04	14/02/2016	215228	reseal and fit water flushing jacket	Breakdown		
PD04	14/02/2016	215215	reseal flushing head	Breakdown		
PD04	15/02/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	16/02/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	275 HR, 7019 LF
PD04	16/02/2016	215260	Large hole reaming mode not working?Free up sp	Breakdown		275 HR, 7019 LF
PD04	17/02/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	276 HR, 7021 LF
PD04	18/02/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	18/02/2016	215375	Re-seal MUX head and fit.	Corrective Maintenance		
PD04	18/02/2016	215373	Start fault on diesel.	Breakdown		
PD04	18/02/2016	215374	Start fault on electrics.	Breakdown		
PD04	19/02/2016	215380	simba start faultlatching contactor playing up, wil	Breakdown		276 HR, 7021 LF
PD04	21/02/2016	215397	C/O 2x percussion hoses on drifter.	Breakdown		
PD04	22/02/2016	215391	Called to simba having trouble starting up, found	Breakdown		
PD04	22/02/2016	215396	LH joystick not threading out.	Breakdown		
PD04	23/02/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	277 HR, 7030 LF
PD04	24/02/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	278 HR, 7038 LF
PD04	24/02/2016	215432	Rear Stinger stuck out?Free up spool (junk in it).	Breakdown		278 HR, 7038 LF
PD04	24/02/2016	215430	Replace water flushing Jacket.	Breakdown		278 HR, 7038 LF
PD04	24/02/2016	215431	Tighten loose fitting on Oil cooler.	Breakdown		278 HR, 7038 LF
PD04	25/02/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	278 HR, 7047 LF
PD04	26/02/2016	215331	2 Weekly Service - Atlas Simba - DayshiftMEMS P	Preventative Maintenance		278 HR, 7056 LF
PD04	28/02/2016	215517	Machine Shutting down hyd temp switch u/s3217	Breakdown		
PD04	29/02/2016	215522	Adjust feed speed to suit threading in/out.	Breakdown		
PD04	29/02/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	29/02/2016	215529	isolator faultrepair wirring	Breakdown		
PD04	29/02/2016	215419	Monthly Drill Rigs Load Checks 23-105002-01.prr	Preventative Maintenance		
PD04	29/02/2016	215530	Pilot fault -e stop wire broken and contact corrodi	Breakdown		
PD04	29/02/2016	215511	Replace air regulator water trapAW40-04BDG-A	Corrective Maintenance		
PD04	29/02/2016	215528	Threading out faultk9 relay	Breakdown		
PD04	1/03/2016	215608	C/o blown hose	Breakdown		280 HR, 7060 LF
PD04	1/03/2016	215616	clino fault, come good	Breakdown		280 HR, 7060 LF
PD04	1/03/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	280 HR, 7060 LF
PD04	1/03/2016	215614	set threading speed	Breakdown		280 HR, 7060 LF
PD04	1/03/2016	215609	uncoupling speed adjustment.	Breakdown		280 HR, 7060 LF

PD04	3/03/2016	215639	Air/water faults.	Breakdown		281 HR, 7072 LF
PD04	3/03/2016	215658	Clino calibration.	Breakdown		281 HR, 7072 LF
PD04	3/03/2016	215657	Tighten front rod handler mounting bolts and align	Breakdown		281 HR, 7072 LF
PD04	6/03/2016	215663	Clino fault, C/O x8 clino cable	Breakdown		
PD04	7/03/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	8/03/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	281 HR, 7084 LF
PD04	9/03/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	282 HR, 7085 LF
PD04	10/03/2016	215806	C/O -6 hose.	Breakdown		
PD04	10/03/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	10/03/2016	215802	X10 fault. Check all wiring. C/O U/S sensor & cali	Breakdown		
PD04	13/03/2016	215829	Airmist fault/repair wiring to contacts clean out gc	Breakdown		
PD04	13/03/2016	215827	Wouldnt start on powerpack C/o u/s shut down sv	Breakdown		
PD04	14/03/2016	215839	Air Flush fault. Fit Check Valve.Cable-tie contacts	Breakdown		
PD04	14/03/2016	215915	c/o -4 hose under dash	Breakdown		
PD04	14/03/2016	215830	Called to simba in 648 having start up fault, found	Breakdown		
PD04	14/03/2016	215826	Clino Fault	Corrective Maintenance		
PD04	14/03/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	14/03/2016	215911	Threading Relay stuck on?Harness internal short?	Breakdown		
PD04	15/03/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	286 HR, 7093 LF
PD04	15/03/2016	215838	Found broken wire Un-threading Fault.Run exterr	Breakdown		286 HR, 7093 LF
PD04	15/03/2016	215834	no dampening fault	Breakdown		286 HR, 7093 LF
PD04	15/03/2016	215913	Replace back hammer hose. Opp broke fitting.	Damage		286 HR, 7093 LF
PD04	16/03/2016	215927	boom creeping.	Breakdown		
PD04	16/03/2016	215938	c/o loom hose	Breakdown		
PD04	16/03/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	16/03/2016	215936	water not turning off	Breakdown		
PD04	17/03/2016	215963	c/o snapped mux strapping bolt	Breakdown		
PD04	17/03/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	17/03/2016	215952	Make up Tempirary Harness for A92 to A93.	Breakdown		
PD04	18/03/2016	215981	Lost Air Flush.Cleaned N/O Contact and cover in e	Breakdown		288 HR, 7103 LF
PD04	18/03/2016	215979	Water flush/ Air flush Blocked.Over crimped hose	Breakdown		288 HR, 7103 LF
PD04	20/03/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	21/03/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	22/03/2016	215411	Replace start stop buttons3217001227 & 321700	Corrective Maintenance		
PD04	22/03/2016	216012	service day faults	Breakdown		
PD04	23/03/2016	216102	Strip & Repair Seat swivel Locking Mechanisum.	Corrective Maintenance		291 HR, 7105 LF
PD04	24/03/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	24/03/2016	216105	Replace broken Pito Jaw Cyl Fitting.	Breakdown		
PD04	25/03/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	26/03/2016	215933	Electrical repairs	Corrective Maintenance		
PD04	28/03/2016	216151	Clino fault.	Breakdown		
PD04	28/03/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	29/03/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	293 HR, 7123 LF
PD04	30/03/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	294 HR, 7126 LF
PD04	31/03/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	4/04/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	5/04/2016	216338	calibrate clino, out by 2 degrees	Breakdown		296 HR, 7130 LF
PD04	5/04/2016	216346	change broken feed rope	Breakdown		296 HR, 7130 LF
PD04	5/04/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	296 HR, 7130 LF
PD04	6/04/2016	216436	c/o -8 hose	Breakdown		296 HR, 7137 LF
PD04	6/04/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	296 HR, 7137 LF
PD04	7/04/2016	216445	C/O -8 hose.	Breakdown		
PD04	7/04/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	8/04/2016	216459	c/o broken return rope and replace snapped bolt	Breakdown		297 HR, 7152 LF
PD04	8/04/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	297 HR, 7152 LF
PD04	11/04/2016	216475	C/O -6 hose and 45 degree fitting.	Breakdown		
PD04	11/04/2016	216474	C/O -6 hose.	Breakdown		
PD04	11/04/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	12/04/2016	216554	clino fault	Breakdown		299 HR, 7156 LF
PD04	12/04/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	299 HR, 7156 LF
PD04	12/04/2016	216095	Replace or check if needed to replacing Joystick H	Corrective Maintenance		299 HR, 7156 LF
PD04	13/04/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	13/04/2016	216555	shutdown on decline, faulty e-stop switch	Breakdown		
PD04	13/04/2016	216574	x 10 clino fault c/o damaged cable	Breakdown		
PD04	14/04/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	301 HR, 7160 LF
PD04	15/04/2016	216572	Simba fault with strating circuit. Circuit not latchi	Breakdown		302 HR, 7170 LF
PD04	18/04/2016	216758	Cylinder - Feed Thrust Changeout on condition	Breakdown		
PD04	18/04/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	18/04/2016	216627	drilling badly.	Breakdown		
PD04	19/04/2016	216717	adjust low dampering pressure	Corrective Maintenance		303 HR, 7183 LF
PD04	19/04/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	303 HR, 7183 LF
PD04	20/04/2016	216737	clino cable	Breakdown		
PD04	20/04/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	21/04/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	304 HR, 7195 LF

PD04	25/04/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	26/04/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	307 HR, 7205 LF
PD04	27/04/2016	216883	c/o -6 hose	Breakdown		308 HR, 7212 LF
PD04	27/04/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	308 HR, 7212 LF
PD04	28/04/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	308 HR, 7218 LF
PD04	2/05/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	3/05/2016	217019	c/o leaking pitto jaw hyd fittingsrock damage	Breakdown		309 HR, 7239 LF
PD04	3/05/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	309 HR, 7239 LF
PD04	3/05/2016	217022	Replace flushing head seals.	Corrective Maintenance		309 HR, 7239 LF
PD04	4/05/2016	217032	c/o - 6 hose	Breakdown		310 HR, 7244 LF
PD04	4/05/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	310 HR, 7244 LF
PD04	4/05/2016	217036	Feed Fault?Bypass test Feed Cyl. Adjust slides.	Breakdown		310 HR, 7244 LF
PD04	5/05/2016	216842	2 Weekly Service - Atlas Simba - DayshiftMEMS P	Preventative Maintenance		311 HR, 7251 LF
PD04	5/05/2016	217055	Cylinder - Feed Thrust Changeout on condition	Component Change out		311 HR, 7251 LF
PD04	5/05/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	311 HR, 7251 LF
PD04	5/05/2016	217058	Drill Fault?	Breakdown		311 HR, 7251 LF
PD04	5/05/2016	217043	Refit Return Rope skipped off rear pully.	Breakdown		311 HR, 7251 LF
PD04	5/05/2016	217057	Start Fault.N/C Contact behind P-Brake switch U/	Breakdown		311 HR, 7251 LF
PD04	9/05/2016	217105	Cylinder - Feed Thrust Changeout on conditionRe	Breakdown		
PD04	9/05/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	9/05/2016	217076	Replace X8, X9 Clyno sensors.	Breakdown		
PD04	9/05/2016	217106	Threading fault, Rotation DCV seals and clean out	Breakdown		
PD04	10/05/2016	217102	Adjust threading	Breakdown		312 HR, 7262 LF
PD04	10/05/2016	217098	C/O -12 hose.	Breakdown		312 HR, 7262 LF
PD04	10/05/2016	217115	Cylinder - Feed Thrust Changeout on conditionBy	Breakdown		312 HR, 7262 LF
PD04	10/05/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	312 HR, 7262 LF
PD04	11/05/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	312 HR, 7267 LF
PD04	11/05/2016	217111	Set threading speed.	Breakdown		312 HR, 7267 LF
PD04	12/05/2016	217195	Adjust Orientation of Detent Catch.	Corrective Maintenance		313 HR, 7273 LF
PD04	12/05/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	313 HR, 7273 LF
PD04	12/05/2016	217199	levers kicking out, detents u/s	Breakdown		313 HR, 7273 LF
PD04	12/05/2016	217029	soft jaw not working properly	Breakdown		313 HR, 7273 LF
PD04	13/05/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	313 HR, 7275 LF
PD04	16/05/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	17/05/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	313 HR, 7288 LF
PD04	17/05/2016	217259	Drifter Oil Leak?	Breakdown		313 HR, 7288 LF
PD04	17/05/2016	217250	Lube faults-lube was run dry had to bleed system	Breakdown		313 HR, 7288 LF
PD04	18/05/2016	217318	clino fault, clean out x8 plug	Breakdown		314 HR, 7295 LF
PD04	18/05/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	314 HR, 7295 LF
PD04	18/05/2016	217317	stinger faults, repair u/s wiring sticking d.c.v	Breakdown		314 HR, 7295 LF
PD04	18/05/2016	217316	water/ air fault, c/o 2x check valves	Breakdown		314 HR, 7295 LF
PD04	19/05/2016	217164	2 Weekly Service - Atlas Simba - DayshiftMEMS P	Preventative Maintenance		
PD04	19/05/2016	217340	Check clino calibration.	Corrective Maintenance		
PD04	19/05/2016	217329	Hydraulic fault. Boom movements sticking.	Breakdown		
PD04	19/05/2016	217343	Intermitant faults with hydraulics.Suspect contam	Breakdown		
PD04	19/05/2016	217342	Traming fault. Loss of power when traming from	Breakdown		
PD04	20/05/2016	217345	C/O -12 hose.	Breakdown		315 HR, 7299 LF
PD04	20/05/2016	217346	Check stingers switches and wiring.Free up stinge	Breakdown		315 HR, 7299 LF
PD04	21/05/2016	217366	replace cracked drill relief block	Breakdown		
PD04	22/05/2016	217373	hyd oil leak repairs	Breakdown		
PD04	23/05/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	318 HR, 7311 LF
PD04	23/05/2016	217386	replace broken feed rope bolt	Breakdown		318 HR, 7311 LF
PD04	24/05/2016	217400	adjust rod alignment	Breakdown		318 HR, 7319 LF
PD04	24/05/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	318 HR, 7319 LF
PD04	24/05/2016	217390	Remove Dirt out of Goin Valve.	Breakdown		318 HR, 7319 LF
PD04	24/05/2016	217394	Replace Pito Jaw Bolt.	Breakdown		318 HR, 7319 LF
PD04	25/05/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	321 HR, 7324 LF
PD04	26/05/2016	217541	Remove rubber from carousel.	Breakdown		
PD04	31/05/2016	217588	Replace 2x missing front stinger bolts.	Breakdown		323 HR, 7338 LF
PD04	1/06/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	324 HR, 7344 LF
PD04	2/06/2016	217409	C/O drifter cradle	Corrective Maintenance		325 HR, 7351 LF
PD04	2/06/2016	217786	Cylinder - Rod Handler Arms Changeout on condit	Breakdown	Replaced Both Rod Handlers worn out !	325 HR, 7351 LF
PD04	2/06/2016	217359	Replace exhaust flexi pipe	Corrective Maintenance		325 HR, 7351 LF
PD04	3/06/2016	217816	C/O -8 fitting.	Corrective Maintenance		327 HR, 7352 LF
PD04	3/06/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	327 HR, 7352 LF
PD04	4/06/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	328 HR, 7365 LF
PD04	6/06/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	6/06/2016	217827	E-stop full of water (opp washed out cab).	Damage		
PD04	7/06/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	7/06/2016	217855	Retrofit Cat E-stop Switch (water problem).	Corrective Maintenance		
PD04	8/06/2016	217939	c/o -4 hose under dash	Breakdown		329 HR, 7374 LF
PD04	8/06/2016	217928	C/O LH bottom clip-on.	Breakdown		329 HR, 7374 LF
PD04	8/06/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	329 HR, 7374 LF
PD04	9/06/2016	217944	C/O 1x drifter shoe.	Corrective Maintenance		329 HR, 7379 LF

PD04	9/06/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	329 HR, 7379 LF
PD04	10/06/2016	217973	Called to PD04 in the 649 didnt have power at the	Breakdown		329 HR, 7386 LF
PD04	10/06/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	329 HR, 7386 LF
PD04	13/06/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	331 HR, 7395 LF
PD04	13/06/2016	218024	Lube and high hydro fault. C/O 10A fuse.Air flush	Breakdown		331 HR, 7395 LF
PD04	13/06/2016	218023	Replace high pressure switch on fire suppression.(Breakdown		331 HR, 7395 LF
PD04	13/06/2016	218016	tripped out on over temp, c/o 10a fuse	Breakdown		331 HR, 7395 LF
PD04	14/06/2016	218062	c/o grease drum pump	Breakdown		
PD04	14/06/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	15/06/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	331 HR, 7400 LF
PD04	16/06/2016	217934	2 Weekly Service - Atlas Simba - DayshiftMEMS P	Preventative Maintenance		332 HR, 7404 LF
PD04	17/06/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	333 HR, 7407 LF
PD04	17/06/2016	218168	Feed fault.Loosen off drifter shoes. 75 Bar free fe	Corrective Maintenance		333 HR, 7407 LF
PD04	17/06/2016	218170	Remove Burred Pito Jaw Bolt.	Breakdown		333 HR, 7407 LF
PD04	17/06/2016	218178	starting fault	Breakdown		333 HR, 7407 LF
PD04	20/06/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	21/06/2016	218222	Clino display fault;ty buttons	Breakdown		334 HR, 7416 LF
PD04	21/06/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	334 HR, 7416 LF
PD04	22/06/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	335 HR, 7416 LF
PD04	25/06/2016	218597	Elec fault. No power to muerhead.Wires squashed	Breakdown		
PD04	27/06/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	28/06/2016	218639	C/o loose pito mount bolts	Breakdown		335 HR, 7421 LF
PD04	28/06/2016	218637	clino fault	Breakdown		335 HR, 7421 LF
PD04	28/06/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	335 HR, 7421 LF
PD04	29/06/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	336 HR, 7425 LF
PD04	30/06/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	336 HR, 7428 LF
PD04	1/07/2016	218682	change out trailing cable old one dropped a phase	Breakdown		336 HR, 7428 LF
PD04	1/07/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	336 HR, 7428 LF
PD04	4/07/2016	218687	blown hose	Breakdown		338 HR, 7438 LF
PD04	4/07/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	338 HR, 7438 LF
PD04	5/07/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	340 HR, 7442 LF
PD04	6/07/2016	218721	bolt pito jaw assembly back together.	Breakdown		
PD04	6/07/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	7/07/2016	218725	change accumulator	Breakdown		340 HR, 7457 LF
PD04	7/07/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	340 HR, 7457 LF
PD04	8/07/2016	218756	blown hose	Breakdown		341 HR, 7466 LF
PD04	8/07/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	341 HR, 7466 LF
PD04	11/07/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	11/07/2016	218782	Replace leaking flushing head.	Corrective Maintenance		
PD04	12/07/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	341 HR, 7471 LF
PD04	13/07/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	342 HR, 7476 LF
PD04	15/07/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	342 HR, 7477 LF
PD04	15/07/2016	218842	mixed up hose in loom	Breakdown		342 HR, 7477 LF
PD04	18/07/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	343 HR, 7478 LF
PD04	19/07/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	344 HR, 7486 LF
PD04	20/07/2016	218886	Adjust percussion pressure.	Corrective Maintenance		345 HR, 7491 LF
PD04	20/07/2016	218888	c?o damaged pitto jaws hyd fittings	Damage		345 HR, 7491 LF
PD04	20/07/2016	218867	called to simba no power found damaged trailing	Breakdown		345 HR, 7491 LF
PD04	20/07/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	345 HR, 7491 LF
PD04	21/07/2016	224383	c/o blown carrier hose	Breakdown		346 HR, 7498 LF
PD04	21/07/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	346 HR, 7498 LF
PD04	21/07/2016	224375	Repair wiring to AFFF pressure switch.Amber alar	Corrective Maintenance		346 HR, 7498 LF
PD04	21/07/2016	218959	Replace MUX head seals.	Breakdown		346 HR, 7498 LF
PD04	21/07/2016	224376	Strip/Repair Hyd fill Pump.	Breakdown		346 HR, 7498 LF
PD04	21/07/2016	224377	Water Pressure fault.Inlet Screen blocked solid...	Breakdown		346 HR, 7498 LF
PD04	22/07/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	347 HR, 7503 LF
PD04	25/07/2016	224485	C/O blown -6 carrier hose.	Breakdown		
PD04	25/07/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	26/07/2016	224504	Clino fault. C/O X8 cable.	Breakdown		348 HR, 7505 LF
PD04	26/07/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	348 HR, 7505 LF
PD04	26/07/2016	224488	Replace mux head, C/O -6 hose & tighten fittings	Breakdown		348 HR, 7505 LF
PD04	27/07/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	348 HR, 7510 LF
PD04	27/07/2016	224533	X8 sensor fault.Found loose plug, water interferar	Breakdown		348 HR, 7510 LF
PD04	28/07/2016	224561	C/O 2x -6, 3m loom hosesC/o blown jack leg hose	Breakdown		349 HR, 7518 LF
PD04	28/07/2016	224392	X9 Sensor Plate needs remounting.#9111 4065 3	Corrective Maintenance		349 HR, 7518 LF
PD04	29/07/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	29/07/2016	224562	Shut down faultrepair bad wiring to hydraulic oil	Breakdown		
PD04	1/08/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	351 HR, 7518 LF
PD04	2/08/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	3/08/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	352 HR, 7524 LF
PD04	4/08/2016	224698	Broken manifold bolt on drifter. (oil leak)	Breakdown		
PD04	4/08/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	4/08/2016	224676	Tighten loose pito jaw.	Breakdown		
PD04	5/08/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	352 HR, 7534 LF

PD04	8/08/2016	224735	Clino fault.Faulty cable.	Breakdown	Faulty clino cable. Calibrate.	352 HR, 7534 LP
PD04	8/08/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	352 HR, 7534 LP
PD04	9/08/2016	224751	Air flush fault	Breakdown		352 HR, 7543 LP
PD04	9/08/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	352 HR, 7543 LP
PD04	9/08/2016	224752	remount pitto jaws	Breakdown		352 HR, 7543 LP
PD04	9/08/2016	224741	Repair hydro leak on drifter.(C/O U/S o-ring)	Breakdown	C/O o-ring on percussion 90 degree bolt on fitti	352 HR, 7543 LP
PD04	10/08/2016	224758	C/O pito jaw bolt.	Breakdown		353 HR, 7550 LP
PD04	10/08/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	353 HR, 7550 LP
PD04	10/08/2016	224821	PD04 Not starting after disconnecting 1000VFound	Breakdown		353 HR, 7550 LP
PD04	10/08/2016	224824	Shutdown fault.	Breakdown		353 HR, 7550 LP
PD04	11/08/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	354 HR, 7554 LP
PD04	11/08/2016	224836	Tighten loose fitting on cooler.	Corrective Maintenance		354 HR, 7554 LP
PD04	12/08/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	355 HR, 7556 LP
PD04	15/08/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	16/08/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	355 HR, 7559 LP
PD04	16/08/2016	224929	PD04 Power pack not Latching once startedFound	Breakdown		355 HR, 7559 LP
PD04	17/08/2016	224954	c/o -8 hose	Breakdown		355 HR, 7559 LP
PD04	17/08/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	355 HR, 7559 LP
PD04	17/08/2016	224952	remove broken fitng in hyd cooler and c/o with r	Breakdown		355 HR, 7559 LP
PD04	18/08/2016	224998	C/O feed rope ladder.	Breakdown		356 HR, 7561 LP
PD04	18/08/2016	224996	C/O top LH clip-on, adjust drifter slides.C/O U/S f	Breakdown	Get TRIAL clip on from surface.	356 HR, 7561 LP
PD04	18/08/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	356 HR, 7561 LP
PD04	19/08/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	356 HR, 7565 LP
PD04	22/08/2016	225035	c/o broken shank inside back hammer assy	Breakdown		356 HR, 7565 LP
PD04	22/08/2016	225046	C/O MUX head.Make up 2x spare MUX heads.	Corrective Maintenance		356 HR, 7565 LP
PD04	23/08/2016	225050	c/o x2 -6 hoseschange 2x -6 hoses	Breakdown		358 HR, 7572 LP
PD04	23/08/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	358 HR, 7572 LP
PD04	23/08/2016	225061	Drill fault.When feeding back, percussion comes c	Breakdown		358 HR, 7572 LP
PD04	23/08/2016	225052	remount pito cylinderremount cylinder	Breakdown		358 HR, 7572 LP
PD04	24/08/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	358 HR, 7580 LP
PD04	24/08/2016	225127	set pump OL for a 8Kw pump, was set for a 5kw	Breakdown		358 HR, 7580 LP
PD04	25/08/2016	224906	2 Weekly Service - Atlas Simba - DayshiftMEMS P	Preventative Maintenance		359 HR, 7585 LP
PD04	25/08/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	359 HR, 7585 LP
PD04	29/08/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	29/08/2016	225163	no power to clino screengreen death in wiring and	Breakdown		
PD04	30/08/2016	209331	C/o Blown Hose.	Breakdown		360 HR, 7586 LP
PD04	30/08/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	360 HR, 7586 LP
PD04	31/08/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	360 HR, 7590 LP
PD04	31/08/2016	225266	Oil leak in drifterResealed MUX still leaking, Repla	Breakdown		360 HR, 7590 LP
PD04	31/08/2016	225125	percussion fault when pulling drifter backneed to	Corrective Maintenance		360 HR, 7590 LP
PD04	31/08/2016	225177	Replaced blown hose	Breakdown		360 HR, 7590 LP
PD04	1/09/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	361 HR, 7594 LP
PD04	1/09/2016	225281	run up drifter and adjust air pressure.	Breakdown		361 HR, 7594 LP
PD04	2/09/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	361 HR
PD04	5/09/2016	225315	Replace blown hyd hose	Breakdown		
PD04	6/09/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	363 HR, 7596 LP
PD04	7/09/2016	225256	2 Weekly Service - Atlas Simba - DayshiftMEMS P	Preventative Maintenance		366 HR, 7603 LP
PD04	7/09/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	366 HR, 7603 LP
PD04	8/09/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	366 HR, 7603 LP
PD04	9/09/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	368 HR, 7605 LP
PD04	9/09/2016	225419	High Percussion Fluctuating?FPCI Activating (Feee	Corrective Maintenance		368 HR, 7605 LP
PD04	12/09/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	368 HR, 7606 LP
PD04	13/09/2016	225458	c/o broken feed ropetidy up mixed up hoses	Breakdown		
PD04	13/09/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	14/09/2016	225535	blown -12 hosec/o -12 hose	Breakdown		368 HR, 7609 LP
PD04	15/09/2016	225596	c/o blown hyd hose	Breakdown	c/o blown //6 loom hose c/o leaking hdy cooler	368 HR, 7614 LP
PD04	15/09/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	368 HR, 7614 LP
PD04	15/09/2016	225618	Replaced Snapped bolt in pito cylinders	Breakdown		368 HR, 7614 LP
PD04	16/09/2016	225624	C/Onapped pito bolt	Corrective Maintenance		369 HR, 7617 LP
PD04	16/09/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	369 HR, 7617 LP
PD04	19/09/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	21/09/2016	225733	clino faultrecalibrate clino sensors	Breakdown		
PD04	21/09/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	21/09/2016	225735	LH Lift Cyl Transfer Pipe Bent/Leaking.	Damage		
PD04	22/09/2016	225881	Cylinder - Stinger Changeout on condition	Component Change out		371 HR, 7624 LP
PD04	22/09/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	371 HR, 7624 LP
PD04	23/09/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	373 HR, 7627 LP
PD04	23/09/2016	225746	Replace Pito Jaw bolt	Breakdown		373 HR, 7627 LP
PD04	26/09/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	26/09/2016	225765	flushing seal leakingc/o flushing housing	Breakdown		
PD04	27/09/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	7638 LP
PD04	27/09/2016	225775	fix water leak on carrier.	Breakdown		7638 LP
PD04	28/09/2016	225780	c/o blown //10 hose	Breakdown		7642 LP
PD04	28/09/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	7642 LP

PD04	29/09/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	373 HR, 7646 LF
PD04	30/09/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	373 HR, 7646 LF
PD04	3/10/2016	225984	c/o 3m -12 hose	Breakdown		374 HR, 7651 LF
PD04	3/10/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	374 HR, 7651 LF
PD04	4/10/2016	226005	c/o 2x bottom clip ons	Breakdown		
PD04	4/10/2016	226001	c/o flushing seal	Breakdown		
PD04	4/10/2016	226013	Change out worn hyd hoses	Corrective Maintenance		
PD04	10/10/2016	226088	c/o blown hose	Breakdown		
PD04	10/10/2016	226090	called to pd 4 to help fitter he had no 24v on elec	Breakdown		
PD04	10/10/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	11/10/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	375 HR, 7651 LF
PD04	11/10/2016	226083	E-stop fault	Breakdown		375 HR, 7651 LF
PD04	12/10/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	376 HR, 7655 LF
PD04	13/10/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	376 HR, 7655 LF
PD04	14/10/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	376 HR, 7659 LF
PD04	14/10/2016	226136	no power fault to clino systemc/o blown fuse cha	Breakdown		376 HR, 7659 LF
PD04	17/10/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	18/10/2016	226171	blown outrigger hosetried to c/o couldnt get cylin	Breakdown		377 HR, 7665 LF
PD04	18/10/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	377 HR, 7665 LF
PD04	19/10/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	377 HR, 7667 LF
PD04	24/10/2016	226273	c/o -8 boom hose	Damage		
PD04	24/10/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	24/10/2016	226277	Drifter making oil excess oil from the lube circuit.	Breakdown		
PD04	24/10/2016	226272	no stinger movementsc/o contact and repair wirin	Breakdown		
PD04	25/10/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	379 HR, 7677 LF
PD04	25/10/2016	226281	Water staying on? Came Good	Corrective Maintenance		379 HR, 7677 LF
PD04	26/10/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	381 HR, 7683 LF
PD04	26/10/2016	226387	Rear stinger wouldnt retract replace faulty contac	Breakdown		381 HR, 7683 LF
PD04	27/10/2016	226401	clino screen not working	Breakdown		381 HR, 7691 LF
PD04	27/10/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	381 HR, 7691 LF
PD04	27/10/2016	226393	repair cable reel wiring no power at switch	Breakdown		381 HR, 7691 LF
PD04	27/10/2016	226339	Repair oil leak on Drifter and replace hose	Breakdown		381 HR, 7691 LF
PD04	28/10/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	382 HR, 7699 LF
PD04	31/10/2016	226418	c.o -12 hose	Breakdown		
PD04	31/10/2016	226420	Cylinder - Feed Thrust Changeout on condition	Component Change out		
PD04	31/10/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	31/10/2016	226415	no water faultsiezed valve	Breakdown		
PD04	31/10/2016	226423	Replace 1x -12 carrier hose.Replace 1x -4 carrier	Breakdown		
PD04	1/11/2016	226440	C/O 2x -12 hoses.	Breakdown		383 HR, 7707 LF
PD04	1/11/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	383 HR, 7707 LF
PD04	3/11/2016	226526	Boaring Lights not good enough!Make up swivel a	Corrective Maintenance		
PD04	4/11/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	386 HR, 7713 LF
PD04	6/11/2016	226544	Pump motor noisy.	Corrective Maintenance		
PD04	7/11/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	8/11/2016	226575	c/o -12 hose	Breakdown		386 HR, 7715 LF
PD04	8/11/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	386 HR, 7715 LF
PD04	9/11/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	386 HR, 7719 LF
PD04	10/11/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	386 HR, 7719 LF
PD04	14/11/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	15/11/2016	226746	Replace Freyed Return Rope.	Corrective Maintenance		387 HR, 7720 LF
PD04	17/11/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	387 HR, 7724 LF
PD04	20/11/2016	226902	change pump	Breakdown		
PD04	22/11/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	390 HR, 7728 LF
PD04	23/11/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	390 HR, 7728 LF
PD04	24/11/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	390 HR, 7729 LF
PD04	25/11/2016	226994	rotation faultsslow or no rotation after bogging ro	Breakdown		390 HR, 7729 LF
PD04	28/11/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	390 HR, 7729 LF
PD04	29/11/2016	227050	c/o blown carrier hose and outrigger hose	Breakdown		391 HR, 7734 LF
PD04	29/11/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	391 HR, 7734 LF
PD04	30/11/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	392 HR, 7742 LF
PD04	30/11/2016	227160	No reaming mode.Stripped block valves and reset	Corrective Maintenance		392 HR, 7742 LF
PD04	30/11/2016	227161	OIL leak on governor.Segment orings replaced.	Corrective Maintenance		392 HR, 7742 LF
PD04	2/12/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	392 HR, 7743 LF
PD04	5/12/2016	227196	Replace Return Rope.	Breakdown		
PD04	6/12/2016	227200	c/o feed rope and failed pully	Breakdown		392 HR, 7750 LF
PD04	6/12/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	392 HR, 7750 LF
PD04	6/12/2016	227210	Percussion Kicking Out?	Breakdown		392 HR, 7750 LF
PD04	6/12/2016	227224	Reseal Percussion Spool. Bypassing into Kick out.	Corrective Maintenance		392 HR, 7750 LF
PD04	6/12/2016	227233	starting faultbatteries are u/s	Breakdown		392 HR, 7750 LF
PD04	7/12/2016	227181	C/O battreys	Corrective Maintenance		392 HR, 7754 LF
PD04	7/12/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	392 HR, 7754 LF
PD04	8/12/2016	227330	drill out snapped bolt in pito cyl	Breakdown		
PD04	9/12/2016	227340	C/O blown carrier hose.	Breakdown		
PD04	9/12/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu

PD04	18/12/2016	227525	c/o failed pos 2 tyreold tyre s/n zz00056v1a new	Component Change out		7765 LP
PD04	19/12/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	19/12/2016	227536	Lost control front Stinger.Refit DIN Plug.	Breakdown		
PD04	20/12/2016	227566	C/O feed Rope.	Breakdown		392 HR, 7771 LP
PD04	20/12/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	392 HR, 7771 LP
PD04	21/12/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	22/12/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	392 HR, 7781 LP
PD04	23/12/2016	227702	C/O engine oil drain hose.Top up oil level.	Breakdown		392 HR, 7787 LP
PD04	23/12/2016	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	392 HR, 7787 LP
PD04	3/01/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	4/01/2018	234876	2 Weekly Service - Atlas Simba - DayshiftMEMS P	Preventative Maintenance		575 HR, 8495 LP
PD04	4/01/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	575 HR, 8495 LP
PD04	4/01/2018	235018	Replaced blown hose	Breakdown		575 HR, 8495 LP
PD04	9/01/2018	235077	Lost Power to PTO.	Breakdown		
PD04	12/01/2018	235245	c/o -6 hose	Breakdown		
PD04	12/01/2018	235238	C/O X9 clino sensor.	Breakdown		
PD04	12/01/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	12/01/2018	235246	no water, contacts sticking	Breakdown		
PD04	13/01/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	14/01/2018	235251	c/o clino cable and sensor	Breakdown		
PD04	14/01/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	15/01/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	582 HR, 8505 LP
PD04	16/01/2018	235291	c/o -6 hose	Breakdown		
PD04	16/01/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	16/01/2018	235292	mux head u/s c/o with new one	Breakdown		
PD04	16/01/2018	235294	tighten loose feed rope and fittings	Breakdown		
PD04	17/01/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	583 HR, 8514 LP
PD04	18/01/2018	235128	6 Monthly Service - Atlas Simba - DayshiftMEMS F	Preventative Maintenance		
PD04	19/01/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	585 HR, 8520 LP
PD04	20/01/2018	235525	Replace Feed rope and adjust slides	Breakdown		
PD04	21/01/2018	235428	c/o blown fuse for hydro switch	Breakdown		
PD04	21/01/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	21/01/2018	235411	No Water/Air Flush?Replace blocked Hose.	Breakdown		
PD04	23/01/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	589 HR, 8535 LP
PD04	23/01/2018	235453	Replace Shank.	Breakdown		589 HR, 8535 LP
PD04	25/01/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	589 HR, 8544 LP
PD04	25/01/2018	235533	repair water leaks hose reel bulk head area	Corrective Maintenance		589 HR, 8544 LP
PD04	26/01/2018	235546	c/o -6 hose	Breakdown		592 HR, 8549 LP
PD04	26/01/2018	235595	Cylinder - Rod Handler Arms Changeout on conditi	Component Change out	Replaced Both Rod Handlers worn out !	592 HR, 8549 LP
PD04	26/01/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	592 HR, 8549 LP
PD04	26/01/2018	235545	straight rod holder arm adjust alignment	Breakdown		592 HR, 8549 LP
PD04	27/01/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	592 HR, 8555 LP
PD04	27/01/2018	235562	water pressure fault, tighten loose water fitting	Breakdown		592 HR, 8555 LP
PD04	27/01/2018	235555	Weld on rear rod arm adjustment mount.Repair v	Breakdown		592 HR, 8555 LP
PD04	28/01/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	28/01/2018	235564	Tighten loose fittings on drifter, C/O -8 hose.Repl	Corrective Maintenance		
PD04	29/01/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	30/01/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	593 HR, 8561 LP
PD04	30/01/2018	237397	threading fault	Breakdown		593 HR, 8561 LP
PD04	31/01/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	1/02/2018	235674	c/o rear inner rod handler cylinderwiper seal fail	Breakdown		594 HR, 8569 LP
PD04	1/02/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	594 HR, 8569 LP
PD04	2/02/2018	235322	2 Weekly Service - Atlas Simba - DayshiftMEMS P	Preventative Maintenance		595 HR, 8571 LP
PD04	3/02/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	3/02/2018	235705	Percussion lever not holding in?Clean kick out orif	Breakdown		
PD04	4/02/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	5/02/2018	235730	Connect Tramming Lights	Breakdown		596 HR, 8576 LP
PD04	5/02/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	596 HR, 8576 LP
PD04	5/02/2018	235733	Loose Fitting.	Breakdown		596 HR, 8576 LP
PD04	5/02/2018	235796	water valve sticking	Breakdown		596 HR, 8576 LP
PD04	6/02/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	6/02/2018	235801	Replace rod handler retaining rod.	Damage		
PD04	7/02/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	8/02/2018	235834	Blown Hose, Broken Fitting.Repair Carosell and R	Damage		
PD04	8/02/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	9/02/2018	235848	c/o -8 hose	Breakdown		
PD04	9/02/2018	235849	c/o shank, and flushing head	Breakdown		
PD04	9/02/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	10/02/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	10/02/2018	235857	remove snapped grease nipple off pulley	Breakdown		
PD04	11/02/2018	235859	stripped thrwad in drifter cradle, fit bspt fitting in	Breakdown		
PD04	12/02/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	601 HR, 8597 LP
PD04	13/02/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	14/02/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu

PD04	15/02/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	15/02/2018	235949	Replace Blown hose	Breakdown		
PD04	16/02/2018	235651	2 Weekly Service - Atlas Simba - DayshiftMEMS P	Preventative Maintenance		
PD04	17/02/2018	235976	Blown Hose.	Breakdown		
PD04	17/02/2018	235980	c/o snapped return rope bolt	Breakdown		
PD04	17/02/2018	235977	Hose Reel Ripped off!Couldnt helicoil so had to m	Damage		
PD04	18/02/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	605 HR, 8612 LP
PD04	18/02/2018	235990	ramp up fault	Breakdown		605 HR, 8612 LP
PD04	19/02/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	21/02/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	21/02/2018	236100	No water Pressure?	Breakdown		
PD04	21/02/2018	236096	Rod fell out of rod arms, landed in boom, while ra	Breakdown		
PD04	22/02/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	22/02/2018	236112	Replace missing rod handler Jaw.	Breakdown		
PD04	23/02/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	612 HR, 8616 LP
PD04	23/02/2018	236114	Lost water Pressure at shank	Breakdown		612 HR, 8616 LP
PD04	24/02/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	25/02/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	26/02/2018	236152	c/o -6 hose	Breakdown		613 HR, 8625 LP
PD04	26/02/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	613 HR, 8625 LP
PD04	26/02/2018	236153	fit jaw in rod handlers	Breakdown		613 HR, 8625 LP
PD04	27/02/2018	236166	c/o mux head strapping bolt	Breakdown		
PD04	27/02/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	27/02/2018	236222	Drill out snapped shuttle cap bolt and Cradle bolt.	Breakdown		
PD04	28/02/2018	236035	2 Weekly Service - Atlas Simba - DayshiftMEMS P	Preventative Maintenance		
PD04	28/02/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	28/02/2018	236231	re fit hose reel cradle repair oil leak	Breakdown		
PD04	28/02/2018	236247	Repair pito jaws	Breakdown		
PD04	2/03/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	2/03/2018	236269	oil leak repairs	Breakdown		
PD04	2/03/2018	236254	Percussion lever not holding in full percussion pos	Breakdown		
PD04	2/03/2018	236253	Repair leaks in loom and on rollover.C/O shank.	Breakdown		
PD04	3/03/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	5/03/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	6/03/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	617 HR, 8646 LP
PD04	7/03/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	9/03/2018	236422	c/o -6 hose	Breakdown		
PD04	9/03/2018	236430	c/o blown hose	Breakdown		
PD04	9/03/2018	236429	clino fault repairs remount x9 sensor recal	Breakdown		
PD04	9/03/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	10/03/2018	236437	c/o hyd temp sender	Breakdown		
PD04	10/03/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	11/03/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	12/03/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	620 HR, 8658 LP
PD04	13/03/2018	236464	C/O feed rope.	Breakdown		
PD04	13/03/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	14/03/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	622 HR
PD04	15/03/2018	236333	2 Weekly Service - Atlas Simba - DayshiftMEMS P	Preventative Maintenance		
PD04	19/03/2018	236565	c/o rear stinger contact	Breakdown		
PD04	19/03/2018	236564	gear switch u/sremove switch and free up	Breakdown		
PD04	20/03/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	20/03/2018	236573	Feed/Percussion Levers kicking out.Hyd Return fil	Corrective Maintenance		
PD04	21/03/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	626 HR, 8668 LP
PD04	22/03/2018	236667	c/o blown pump hose add 5 drums of oil	Breakdown		
PD04	22/03/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	22/03/2018	236670	Rewire Isolator.Replace 15a Breaker.	Breakdown		
PD04	23/03/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	626 HR, 8679 LP
PD04	23/03/2018	236672	Replace Broken feed fitting.	Damage		626 HR, 8679 LP
PD04	24/03/2018	236680	No power fault, wiring melted on starter and alter	Breakdown		
PD04	25/03/2018	236695	Replace clino cable	Breakdown		
PD04	26/03/2018	236702	cable reel not working, free up dcv	Breakdown		627 HR, 8680 LP
PD04	26/03/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	627 HR, 8680 LP
PD04	27/03/2018	236721	c/o broken -8 nipple	Breakdown		
PD04	27/03/2018	236709	c/o damaged drifter hdy fittings	Breakdown		
PD04	27/03/2018	236720	cable reel not workingdvcv stuck	Breakdown		
PD04	27/03/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	28/03/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	629 HR, 8689 LP
PD04	28/03/2018	236772	Reseal Feed fittings.	Corrective Maintenance		629 HR, 8689 LP
PD04	29/03/2018	236602	2 Weekly Service - Atlas Simba - DayshiftMEMS P	Preventative Maintenance		8689 LP
PD04	31/03/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	1/04/2018	236819	Blown Hose	Breakdown		
PD04	1/04/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	2/04/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	2/04/2018	236824	rear stinger nort workingrepair wiring to switch	Breakdown		

PD04	2/04/2018	236827	Replace broken -8 Elbow	Damage		
PD04	2/04/2018	236825	Replace Carosell Drum.	Damage		
PD04	3/04/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	629 HR, 8690 LP
PD04	3/04/2018	236839	refit return rope jumped off tidy hoses	Breakdown		629 HR, 8690 LP
PD04	4/04/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	8690 LP
PD04	4/04/2018	236845	Damaged Hyd Hose.	Damage		8690 LP
PD04	4/04/2018	236963	percussion fault/c/o filters	Corrective Maintenance		8690 LP
PD04	5/04/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	6/04/2018	236975	c/o -8 hose	Breakdown		
PD04	6/04/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	8/04/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	9/04/2018	236993	c/o flushing jacket	Breakdown		8690 LP
PD04	9/04/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	8690 LP
PD04	10/04/2018	237006	c/o -6 hose	Breakdown		8690 LP
PD04	10/04/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	8690 LP
PD04	10/04/2018	237008	tighten loose rod handlers	Breakdown		8690 LP
PD04	11/04/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	12/04/2018	236886	3 Monthly Service - ATLAS Simba - DayshiftMEMS	Preventative Maintenance		
PD04	12/04/2018	237070	c/o leaking hyd cooler water fitting	Breakdown		
PD04	13/04/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	14/04/2018	237100	c/o blown hose	Breakdown		
PD04	14/04/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	15/04/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	16/04/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	16/04/2018	237132	starter motor u/s	Breakdown		
PD04	17/04/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	18/04/2018	237216	C/O -6 hose.	Breakdown		
PD04	18/04/2018	237222	C/O flushing head.	Breakdown		
PD04	18/04/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	18/04/2018	237221	Threading fault	Breakdown		
PD04	19/04/2018	237225	C/O -6 2.2m hose.	Breakdown		
PD04	19/04/2018	237235	C/O flushing head. (front seal blew out)	Corrective Maintenance		
PD04	19/04/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	20/04/2018	237237	C/O -6 90 degree fitting.	Breakdown		
PD04	20/04/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	21/04/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	21/04/2018	237255	Replace u/s fitting, calibrate clino, swop rotation	Breakdown		
PD04	22/04/2018	237248	c/o feed rope c/o pitto jaw bolts	Component Change out		
PD04	23/04/2018	237265	C/O Fitting Leaking	Breakdown		
PD04	23/04/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	24/04/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	25/04/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	25/04/2018	237336	pitto jaws not holding tighten loose loom hose	Breakdown		
PD04	25/04/2018	237335	rock damage c/o hyd fitting	Damage		
PD04	26/04/2018	237159	2 Weekly Service - Atlas Simba - DayshiftMEMS P	Preventative Maintenance		
PD04	28/04/2018	237376	c/o blown hose	Breakdown		
PD04	28/04/2018	237377	c/o blown hose	Breakdown		
PD04	28/04/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	29/04/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	30/04/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	630 HR, 6.5 LP
PD04	2/05/2018	237579	Cylinder - Feed Thrust Changeout on condition	Component Change out		
PD04	2/05/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	3/05/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	4/05/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	5/05/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	6/05/2018	237601	adjust dampening pressure to 40 bar	Breakdown		
PD04	6/05/2018	237598	c.o broken t fitting	Breakdown		
PD04	6/05/2018	237602	c/o jackleg hose	Breakdown		
PD04	6/05/2018	237600	c/o pito jaws	Breakdown		
PD04	6/05/2018	237603	c/o shank and flushing head'	Breakdown		
PD04	6/05/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	low water pressu
PD04	8/05/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	632 HR, 18 LP
PD04	8/05/2018	237631	remount rod handlers	Breakdown		632 HR, 18 LP
PD04	8/05/2018	237632	tighten loose feed rope and tighten loose hose	Breakdown		632 HR, 18 LP
PD04	9/05/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	633 HR, 25 LP
PD04	10/05/2018	237438	2 Weekly Service - Atlas Simba - DayshiftMEMS P	Preventative Maintenance		633 HR, 28 LP
PD04	10/05/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	633 HR, 28 LP
PD04	11/05/2018	237719	c/o pitto jaw bolt tighten loose hyd fittings	Breakdown		
PD04	11/05/2018	237739	Cylinder - Stinger Changeout on condition	Component Change out		
PD04	14/05/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	636 HR, 36 LP
PD04	15/05/2018	237855	Blown hose.	Breakdown		637 HR, 38 LP
PD04	15/05/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	637 HR, 38 LP
PD04	15/05/2018	237854	oil leak tighten loom hose hose	Breakdown		637 HR, 38 LP
PD04	16/05/2018	237856	Cylinder - Stinger Changeout on condition	Component Change out		

PD04	16/05/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	17/05/2018	237876	Blown Pump hose.Remopunt 2x Pito cyl pads.	Breakdown		
PD04	17/05/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	18/05/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	19/05/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	19/05/2018	237887	tighten loose pito jaw bolt	Breakdown		
PD04	20/05/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	20/05/2018	237888	oil leak on carrier, tighten loose hose	Breakdown		
PD04	20/05/2018	237889	replace pito jaw bolt	Breakdown		
PD04	21/05/2018	237897	clino fault, c/o cable and sensor	Breakdown		640 HR, 63 LP
PD04	21/05/2018	237902	clino faultbellow u/s	Breakdown		640 HR, 63 LP
PD04	21/05/2018	237903	Cylinder - Feed Thrust Changeout on condition	Component Change out		640 HR, 63 LP
PD04	21/05/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	640 HR, 63 LP
PD04	21/05/2018	237901	remount pito jaw box	Breakdown		640 HR, 63 LP
PD04	22/05/2018	237914	c/o -6 hose	Breakdown		
PD04	22/05/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	23/05/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check	640 HR, 70 LP
PD04	24/05/2018	237509	2 Weekly Service - Atlas Simba - DayshiftMEMS P	Preventative Maintenance		
PD04	25/05/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	26/05/2018	237956	Feed regulator	Breakdown		
PD04	29/05/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	
PD04	30/05/2018	X0000024	Daily Service - PD04***PLEASE DO NOT CLOSE T	Preventative Maintenance	15/4/15 Changed out 2 x hoses. 23/4/15 Check low water pressu	