

Volvo L180G Wheel Loader IT009 - Dis Assembled



Make	Volvo		Model	L180G Dis Assembled		
Year		Hours	8838		As at	01/12/2019
Mileage				km	As at	
Serial/VIN	VCEL180GE16040			Engine Serial		
Details	<p>Volvo L180G Wheel Loader / Tool Carrier Asset no IT009. Please note - This loader is currently Dis Assembled and is sold "As Is" - AS PER PHOTOS. This IT is sold as a machine only with no tools included. Offered for sale via online auction ex Site Nifty Copper Mine via Telfer Western Australia, running to drive on to buyers transport. See Google Maps link: https://goo.gl/maps/Xvaa3uBAFso9MP7A8</p>					
Asking price	AUD	Under review - call for pricing				
Ex site	Australia, Western Australia, Telfer					

Service history	This IT is sold as machine only with no tools included.
------------------------	---

For further details, to make an offer or book an inspection, contact

Global Equipment Solutions on Office: 08 9201 1142













4.0 UG ANCILLARY

4.1.1 IT009 VOLVO L180G

- Currently has failed transmission – long lead time
- Hard to source parts
- Used for fan lifts
- Used for loading crusher

Asset Number	Make	Model	Current SMU reading (hrs)	All-time SMU
IT009	Volvo	L180G	8838	8838

4.1.2 IT009 SUMMARY

Low usage UG due to size. CJD option for transmission \$63K plus \$35K core