

2012 Caterpillar 980H NON Running Asset ME12



Make	Caterpillar		Model	980H NON Running	
Year	2012	Hours		As at	
Mileage			km	As at	
Serial/VIN	CAT0980HCKZL00559		Engine Serial		
Details	<p>Un Reserved 2012 Caterpillar 980H NON Running Asset ME12. Fitted with Loadrite scale system including L Series 2180 and LP950 printer. This loader is non running and maintenance feedback shows the unit is next due for a 1,000 hours service at 15,000 hours and has a possible cracked head that needs to eb sent out for testing.. Offered for sale via Online auction in "As Is" condition, lifted on to buyers transport. Located at Savannah Nickel Mine, via Kununurra Western Australia.</p>				
Asking price	AUD	Under review - call for pricing			
Ex site	Australia, Western Australia, Kununurra				

Service history	This loader is non running and maintenance feedback shows the unit is next due for a 1,000 hours service at 15,000 hours and has a possible cracked head that needs to eb sent out for				
------------------------	--	--	--	--	--

testing.

**For further details, to make an offer or book an inspection, contact
Global Equipment Solutions on Office: 08 9201 1142**











Work Order	Description	Start Date	Status	Cost Centre	Key/Section	PM Task	Branch
097993	ME12, Yearly WORK ORDER	7-Dec-14	F	4400210	WHOLE		UG
098614	Carry out 500 HR service as per attached sheet	30-Dec-14	F	4400210	500HR	10031	CAP
099171	Carry out 250HR service as per attached sheet	12-Jan-15	F	4400210	250HR	10030	CAP
099320	Replace full set of tyres	19-Jan-15	F	4400210	TYRE		CAP
099280	Carry out 125 HR inspection as per attached sheet	20-Jan-15	F	4400210	125HR	2237	CAP
099640	ME09, REPLACE BUCKET	27-Jan-15	F	4400210	BUCKET	2648	CAP
099547	Carry out 1000HR service as per attached sheet	29-Jan-15	F	4400210	1000HR	10032	CAP
099811	ME12, FIT FAST FILL SYSTEM	4-Feb-15	F	4400210	FRAME		CAP
099851	ME12, REPLACE BUCKET LIP	4-Feb-15	F	4400210	BUCKET		CAP
099832	Carry out 125 HR inspection as per attached sheet	7-Feb-15	F	4400210	125HR	2237	CAP
100227	Carry out 250HR service as per attached sheet	16-Feb-15	F	4400210	250HR	10030	CAP
100540	Carry out 125 HR inspection as per attached sheet	22-Feb-15	F	4400210	125HR	2237	CAP
100235	Carry out 125 HR inspection as per attached sheet	23-Feb-15	F	4400210	125HR	2237	CAP
100442	ME12, REPLACE STEERING ORBITAL VALVE	23-Feb-15	F	4400210	STEER		CAP
100544	Carry out 500 HR service as per attached sheet	2-Mar-15	F	4400210	500HR	10031	CAP
100793	Carry out 125 HR inspection as per attached sheet	9-Mar-15	F	4400210	125HR	2237	CAP
100807	Carry out 250HR service as per attached sheet	17-Mar-15	F	4400210	250HR	10030	CAP
101373	Carry out 125 HR inspection as per attached sheet	27-Mar-15	F	4400210	125HR	2237	CAP
101607	Carry out 2000Hr service as per attached sheet	3-Apr-15	F	4400210	2000HR	10033	CAP
101925	Carry out 250HR service as per attached sheet	20-Apr-15	F	4400210	250HR	10030	CAP
102405	Carry out 125 HR inspection as per attached sheet	27-Apr-15	F	4400210	125HR	2237	CAP
102635	ME12, REPLACE HYDRAULIC FAN HOSES	27-Apr-15	F	4400210	HYD		CAP
102646	Carry out 500 HR service as per attached sheet	6-May-15	F	4400210	500HR	10031	CAP
103294	Carry out 250HR service as per attached sheet	22-May-15	F	4400210	250HR	10030	CAP
103634	Carry out 1000HR service as per attached sheet	5-Jun-15	F	4400210	1000HR	10032	CAP
104338	Carry out 250HR service as per attached sheet	21-Jun-15	F	4400210	250HR	10030	CAP
105685	DIESEL FUEL ONLY - Work Orders Created for Stores Issue of	1-Jul-15	F	4400210	ADMIN	600	CAP
104939	Carry out 500 HR service as per attached sheet	10-Jul-15	F	4400210	500HR	10031	CAP
105345	CRANE REQUIRED TO MOVE BUCKET AT UG MAINTENANCE	15-Jul-15	F	4400210	BUCKET		CAP
105370	CRANE REQUIRED TO MOVE BUCKET	16-Jul-15	F	4400210	BUCKET		CAP
105494	ME12, Repair battery/ bonnet electric motor boxes from	18-Jul-15	F	4400210	WHOLE		CAP
105558	ME12, Supply belly plate guard	20-Jul-15	F	4400210	WHOLE		CAP
105579	ME12, Fit reverse camera and monitor	20-Jul-15	F	4400210	ELECTL		CAP
105521	Carry out 250HR service as per attached sheet	26-Jul-15	F	4400210	250HR	10030	CAP
106064	Carry out 2000Hr service as per attached sheet	11-Aug-15	F	4400210	2000HR	10033	CAP
106581	REQUIRED TO LIFT BUCKETS AT UG WORKSHOP	14-Aug-15	F	4400210	BUCKET		CAP
106588	ME12, REPLACE TRANS TEMP SENSOR	14-Aug-15	F	4400210	TRANS		CAP
102511	REPLACE BUCKET and rebuild bucket # 2	20-Aug-15	F	4400210	BUCKET	2648	CAP
106716	Use mobile crane to move ME12 bucket out of boily	20-Aug-15	F	4400210	BUCKET		CAP
106792	Carry out 250HR service as per attached sheet	28-Aug-15	F	4400210	250HR	10030	CAP
107322	Repair aircon fault- blocked orifice on drier	31-Aug-15	F	4400210	ACON		CAP
107326	ME12, replace Z link pins and bushes	31-Aug-15	F	4400210	FRAME		CAP
107471	Carry out 500 HR service as per attached sheet	13-Sep-15	F	4400210	500HR	10031	CAP
107810	Carry out 250HR service as per attached sheet	28-Sep-15	F	4400210	250HR	10030	CAP
108633	AFFF SYSTEM TEST	1-Oct-15	F	4400210	AFFF	2254	CAP
108489	REPLACE WORN STEERING PINS AND BEARINGS	2-Oct-15	F	4400210	STEER		CAP
108712	Replace broken wear plate on bottom of bucket	10-Oct-15	F	4400210	GET		CAP
108750	Carry out 1000HR service as per attached sheet	14-Oct-15	F	4400210	1000HR	10032	CAP
109381	Carry out 250HR service as per attached sheet	31-Oct-15	F	4400210	250HR	10030	CAP
109519	ME12, MOVE BUCKET IN BOILY BAY	31-Oct-15	F	4400210	BUCKET		CAP
109808	Carry out fire suppression service	1-Nov-15	F	4400210	AFFF	2227	CAP
109696	980H, REPLACE BUCKET	7-Nov-15	F	4400210	BUCKET	2648	CAP
109728	Carry out 500 HR service as per attached sheet	15-Nov-15	F	4400210	500HR	10031	CAP
110781	Carry out 250HR service as per attached sheet	2-Dec-15	F	4400210	250HR	10030	CAP
110894	ME12, CHARGING FAULT WITH REGULATOR	4-Dec-15	F	4400210	ENGINE		CAP
110902	ME12, REPLACE FAN TENSIONER	5-Dec-15	F	4400210	ENGINE		CAP
110904	ME12, REPLACE FAILED FUEL FILTER SENSOR	6-Dec-15	F	4400210	ELECTL		CAP
110905	Change out number 5 injector	6-Dec-15	F	4400210	ENGINE		CAP
111133	ME12 Boily work, Cut lip off new (second hand) bucket -BTP	12-Dec-15	F	4400210	BUCKET		CAP
111691	Carry out 2000Hr service as per attached sheet	24-Dec-15	F	4400210	2000HR	10033	CAP
112099	Commpresser clutch U/S	2-Jan-16	F	4400210	ACON		CAP
112112	Carry out 250HR service as per attached sheet	7-Jan-16	F	4400210	250HR	10030	CAP

112198	ME12,980H, REPLACE BUCKET	9-Jan-16	F	4400210	BUCKET	2648	CAP
112715	ME12, repair Acon. Leak at the accumulator	18-Jan-16	F	4400210	ACON		CAP
112896	Carry out 500 HR service as per attached sheet	28-Jan-16	F	4400210	500HR	10031	CAP
113128	Carry out 250HR service as per attached sheet	14-Feb-16	F	4400210	250HR	10030	CAP
113864	Carry out 1000HR service as per attached sheet	29-Feb-16	F	4400210	1000HR	10032	CAP
114113	c/o starter motor and batteries	6-Mar-16	F	4400210	ELECTL		CAP
114324	Carry out 250HR service as per attached sheet	16-Mar-16	F	4400210	250HR	10030	CAP
114546	CHANGE OUT BUCKET	19-Mar-16	F	4400210	BUCKET		CAP
114581	PARK BRAKE U/S	21-Mar-16	F	4400210	BRAKE		CAP
114821	Carry out 500 HR service as per attached sheet	2-Apr-16	F	4400210	500HR	10031	CAP
115213	Move ME12 bucket into boily shop so we can have	9-Apr-16	F	4400210	BUCKET		CAP
115229	Carry out 250HR service as per attached sheet	15-Apr-16	F	4400210	250HR	10030	CAP
115649	Carry out 2000Hr service as per attached sheet	30-Apr-16	F	4400210	2000HR	10033	CAP
115983	Carry out 250HR service as per attached sheet	14-May-16	F	4400210	250HR	10030	CAP
115991	Carry out fire suppression service	17-May-16	F	4400210	AFFF	2227	CAP
117876	BRAKE ACCUMULATOR CHARGE VALVE REQUIRES REBUILDING	11-Jul-18	F	4400210	BRAKE		CAP
117908	Carry out 500 HR service as per attached sheet	31-Aug-18	F	4400210	500HR	10031	CAP
117959	3 Monthly work order for daily services & minor repairs	1-Oct-18	F	4400210	WHOLE	2108	CAP
118087	Carry out fire suppression service	11-Oct-18	F	4400210	AFFF	2227	CAP
118409	Replace Implement valve wiring harness	9-Dec-18	F	4400210	ELECTL		CAP
118534	REPLACE WELD ON CUTTING EDGES ONTO THE BUCKET	12-Dec-18	F	4400210	GET		CAP
121644	REPLACE LEAKING CORE IN COOLER PACK	16-Dec-18	F	4400210	ENGINE		CAP
123197	Replace Orbital Valve	20-Dec-18	F	4400210	STEER		CAP
121632	Carry out 250HR service as per attached sheet	25-Dec-18	F	4400210	250HR	10030	CAP
123323	REPLACE HYDRAULIC PRESSURE SWITCH	26-Dec-18	F	4400210	ELECTL		CAP
123338	Replace park brake linings	28-Dec-18	F	4400210	BRAKE		CAP
123263	3 Monthly work order for daily services & minor repairs	1-Jan-19	F	4400210	WHOLE	2108	CAP
123516	REPLACE LEAKING RADIATOR LEAKING COOLER CORE	4-Jan-19	F	4400210	ENGINE		CAP
123532	REPLACE AIR-CONDITIONING PRESSURE SWITCH	6-Jan-19	F	4400210	ACON		CAP
123563	Replace all four tyres	10-Jan-19	F	4400210	TYRE		CAP
125654	C/O Alternator, Over changing	19-Jan-19	F	4400210	ELECTL		CAP
125697	Replace faulty tilt lever in cab	22-Jan-19	F	4400210	CABIN		CAP
125764	Repair coolant leak on engine cooler	3-Feb-19	F	4400210	ENGINE		CAP
125768	Replace transmission filter hoses and bypass switch	8-Feb-19	F	4400210	TRANS		CAP
127309	Refeb aircon system due to hose failure and contamination	16-Feb-19	F	4400210	ACON		CAP
130013	Carry out 1000HR service as per attached sheet	4-Mar-19	F	4400210	1000HR	10032	CAP
127834	Replace all chassis harnesses due to being rotten	10-Mar-19	F	4400210	ELECTL		CAP
129337	replace radiator cores	10-Mar-19	F	4400210	ENGINE		CAP
130095	diagnose hyd fault with brake release and loss of implements	21-Mar-19	F	4400210	HYD		CAP
131786	REPAIR FRONT AXLE HOUSING	30-Mar-19	F	4400210	AXLE		CAP
130307	3 Monthly work order for daily services & minor repairs	1-Apr-19	F	4400210	WHOLE	2108	CAP
130444	Replace brittle fuel harness	4-Apr-19	F	4400210	ELECTL		CAP
131857	Carry out 250HR service as per attached sheet	4-Apr-19	F	4400210	250HR	10030	CAP
131724	Carry out fire suppression service	13-Apr-19	F	4400210	AFFF	2227	CAP
132077	CHANGE OUT LEAKING HOOD TILT CYLINDERS	19-Apr-19	F	4400210	HYDCYL		CAP
132253	Carry out 500 HR service as per attached sheet	22-Apr-19	F	4400210	500HR	10031	CAP
132609	Low Engine Power C/O Turbo	22-Apr-19	F	4400210	ENGINE		CAP
133832	Replace batteries.	22-May-19	F	4400210	ELECTL		CAP
134157	TWO-WAY NOT TRANSMITTING	29-May-19	F	4400210	ELECTL		CAP
134161	Carry out 250HR service as per attached sheet	29-May-19	F	4400210	250HR	10030	CAP
133882	REPAIR BROKEN STEP LEFT HAND SIDE	30-May-19	F	4400210	FRAME		CAP
133881	REPLACE CRACKED FRONT WINDSCREEN - Not Required	4-Jun-19	F	4400210	CABIN		CAP
134602	GET Needs Replacing	7-Jun-19	F	4400210	GET		CAP
134336	REPAIR CRACKS AT THE BACK OF BUCKET	12-Jun-19	F	4400210	GET		CAP
134909	Carry out 2000Hr service as per attached sheet	14-Jun-19	F	4400210	2000HR	10033	CAP
135256	Repair mounting steps.	16-Jun-19	F	4400210	FRAME		CAP
135800	Yearly work order for daily services & minor repairs	1-Jul-19	F	4400210	WHOLE	2108	CAP
138666	SOLE PLATES ON BUCKET COMPLETELY WORN	5-Jul-19	F	4400210	BUCKET		CAP
136361	REPLACE BOOM BUCKET PINS AND BUSHES	6-Jul-19	F	4400210	FRAME		CAP
137786	Carry out 250HR service as per attached sheet	9-Jul-19	F	4400210	250HR	10030	CAP
137865	weld GET on bucket	9-Jul-19	F	4400210	BUCKET		CAP
138057	Repair bent rear steps	16-Jul-19	F	4400210	FRAME		CAP
138194	REPLACE LEAKING LIFT CYLINDER HOSES	19-Jul-19	F	4400210	HOSES		CAP

138274	change out leaking L/H steering hose	22-Jul-19	F	4400210	HOSES		CAP
138443	Carry out 500 HR service as per attached sheet	3-Aug-19	F	4400210	500HR	10031	CAP
139457	Check front diff/ axle housing crack - supervisor	16-Aug-19	F	4400210	AXLE		CAP
140001	Replace R/H steering hose.	20-Aug-19	F	4400210	HOSES		CAP
140263	Alternator Over Charging	24-Aug-19	F	4400210	ELECTL		CAP
139927	Carry out 1000HR service as per attached sheet	29-Aug-19	F	4400210	1000HR	10032	CAP
134156	Repair FUEL GAUGE NOT WORKING - Sender	7-Sep-19	F	4400210	ELECTL		CAP
141788	Replace radiator cores.	10-Sep-19	F	4400210	ENGINE		CAP
141736	Carry out 250HR service as per attached sheet	16-Sep-19	F	4400210	250HR	10030	CAP
141873	Replace wiper blade	17-Sep-19	F	4400210	CABIN		CAP
141874	Replace front right light	17-Sep-19	F	4400210	ELECTL		CAP
142150	Check for signs of fuel dilution	17-Sep-19	F	4400210	ENGINE		CAP
142496	Replace Cracked Auto Grease Tank	22-Sep-19	F	4400210	WHOLE		CAP
142519	fit trans filler cap to transmission	23-Sep-19	F	4400210	HYD		CAP
142537	Transmission gauge fluctuating	24-Sep-19	F	4400210	TRANS		CAP
142604	AFFF Gone Off	25-Sep-19	F	4400210	AFFF		CAP
142861	C/out Bucket	28-Sep-19	F	4400210	BUCKET		CAP
140455	Install Digital Radio	30-Sep-19	F	4400210	ELECTL		UG
142804	Carry out 500 HR service as per attached sheet	3-Oct-19	F	4400210	500HR	10031	CAP
142805	Carry out fire suppression service	4-Oct-19	F	4400210	AFFF	2227	CAP
143295	C/coil for implement lock out	6-Oct-19	F	4400210	ELECTL		CAP
143467	Repair seat.	10-Oct-19	F	4400210	CABIN		CAP
143499	Top radiator hose failed.	10-Oct-19	F	4400210	ENGINE		CAP
143526	C/out exhaust muffler	11-Oct-19	F	4400210	ENGINE		CAP
143756	Fuel gauge not working.	14-Oct-19	F	4400210	CABIN		CAP
143757	Replace R/H cutting edge.	14-Oct-19	F	4400210	BUCKET		CAP
143758	Inspect and repair hyd leaks.	14-Oct-19	F	4400210	HYD		CAP
143761	Front windscreen cracked.	14-Oct-19	I	4400210	CABIN		CAP
143808	Replace Pilot Valve.	15-Oct-19	F	4400210	HYD		CAP
143334	Attach bucket pins to autolube	17-Oct-19	F	4400210	FRAME		CAP
143503	Replace operator's seat incl suspension	20-Oct-19	F	4400210	CABIN		CAP
144675	C/out blown steer hose	25-Oct-19	F	4400210	HOSES		CAP
144852	Install and calibrate tilt and boom lift kick outs	29-Oct-19	F	4400210	ELECTL		CAP
145191	Flush Cooling system	30-Oct-19	F	4400210	ENGINE		CAP
145580	Replace air con blower motor - Hi current	9-Nov-19	F	4400210	ACON		CAP
143664	Carry out 250HR service as per attached sheet	10-Nov-19	F	4400210	250HR	10030	CAP
145422	Replace missing lamps	11-Nov-19	F	4400210	ELECTL		CAP
145809	Replace tilt cylinder hoses and grease lines.	11-Nov-19	F	4400210	HOSES		CAP
145814	Bucket repairs	11-Nov-19	F	4400210	BUCKET		CAP
146497	Air Con Not Cold.	18-Nov-19	F	4400210	ACON		CAP
146823	Re-locate fire extinguishers from rear to front guard	24-Nov-19	L	4400210	AFFF		CAP
146446	Carry out 2000Hr service as per attached sheet	27-Nov-19	F	4400210	2000HR	10033	CAP
146636	Found Starter Motor Bolts Loose On Daily Service	27-Nov-19	F	4400210	ELECTL		CAP
146639	Steering Frame Lock Missing Pin.	28-Nov-19	F	4400210	FRAME		CAP
147602	C/out transmission filter canister	30-Nov-19	F	4400210	TRANS		CAP
147688	Replace transmission filter outer housing (and filter)	2-Dec-19	F	4400210	TRANS		CAP
147913	RH dog bone pin in bucket, clevis on bucket bent	5-Dec-19	F	4400210	BUCKET		CAP
148115	Carry out 250HR service as per attached sheet	13-Dec-19	F	4400210	250HR	10030	CAP
148708	RIGHT HAND SIDE INDICATOR NOT WORKING	15-Dec-19	F	4400210	ELECTL		CAP
148875	Aircon repairs	17-Dec-19	F	4400210	ACON		CAP
149152	Investigate and repair fuel bleed back issue	20-Dec-19	F	4400210	ENGINE		CAP
148859	HYDRAULIC LEAK ON HYDRAULIC PUMP ON RIGHT HAND SIDE	20-Dec-19	I	4400210	HYD		CAP
149214	Repair auto greaser fault	22-Dec-19	F	4400210	ELECTL		CAP
147861	Replace steering pins and bushes	24-Dec-19	I	4400210	STEER		CAP
148750	Carry out 500 HR service as per attached sheet	26-Dec-19	F	4400210	500HR	10031	CAP
149916	Repair right ladder and fit new rubber step	28-Dec-19	F	4400210	FRAME		CAP
149917	Replace air con hose	28-Dec-19	F	4400210	ACON		CAP
ME1220	Daily Consumables Only	1-Jan-20	S	4400210	WHOLE		CAP
150372	Inspect and repair engine oil leak at rear of engine	3-Jan-20	F	4400210	ENGINE		CAP
150582	Damage to bottom of fuel tank - leaking drain tank & repair	4-Jan-20	F	4400210	FRAME		CAP
149657	Replace the oRing in the trans filter housing	10-Jan-20	I	4400210	TRANS		CAP
151111	FUEL IN COOLANT	15-Jan-20	I	4400210	ENGINE		CAP
151365	C/out cutting edges	19-Jan-20	F	4400210	BUCKET		CAP

151504	Replace lift hoses	30-Jan-20	F	4400210	HOSES		CAP
154018	Replace boost hoses	5-Feb-20	I	4400210	ENGINE		CAP
152136	Carry out 250HR service as per attached sheet	12-Feb-20	I	4400210	250HR	10030	CAP
153713	Small oil leak from engine	26-Feb-20	L	4400210	ENGINE		CAP
153714	Trans Gauge not working	26-Feb-20	I	4400210	ELECTL		CAP
153744	Engine over heating - Replace cooler pack segments	26-Feb-20	L	4400210	ENGINE		CAP
153779	Front wiper motor siezed	27-Feb-20	I	4400210	ELECTL		CAP
153801	Replace battery's, tighten cooler pack bolts	28-Feb-20	F	4400210	WHOLE		CAP
153930	Repair coolant leak from cooler pack, replace top and bottom	29-Feb-20	F	4400210	WHOLE		CAP
154222	Cat to review injector cup seals. Identify which pot has a	1-Mar-20	F	4400210	WHOLE		CAP
153777	CARRY OUT WEEKLY "A" SERVICE ON U/G VEHICLES Not done	3-Mar-20	F	4400210	WHOLE	10000	CAP
153778	Replace cooling system hoses	3-Mar-20	I	4400210	ENGINE		CAP
153969	Carry out Weekly Mechanical Inspection of HV Gear. not done	11-Mar-20	L	4400210	WHOLE	10008	CAP
153764	Replace hyd suction hose - weeping	12-Mar-20	F	4400210	HYD		CAP
153985	Carry out Weekly Mechanical Inspection of HV Gear.18/3/20not	18-Mar-20	L	4400210	WHOLE	10008	CAP
154002	Carry out Weekly Mechanical Inspection of HV Gear.	25-Mar-20	L	4400210	WHOLE	10008	CAP
154490	Carry out Weekly Mechanical Inspection of Cat 980H.	1-Apr-20	L	4400210	WEEK	10034	CAP
154544	Carry out Weekly Mechanical Inspection of Cat 980H.	8-Apr-20	L	4400210	WEEK	10034	CAP
154545	Carry out fire suppression service	12-Apr-20	I	4400210	AFFF	2227	CAP
154590	Carry out Weekly Mechanical Inspection of Cat 980H.	15-Apr-20	L	4400210	WEEK	10034	CAP
156299	Take off Head and send away for testing.	17-Apr-20	I	4400210	WHOLE		CAP
154634	Carry out Weekly Mechanical Inspection of Cat 980H.	22-Apr-20	L	4400210	WEEK	10034	CAP
154664	Carry out Weekly Mechanical Inspection of Cat 980H.	29-Apr-20	L	4400210	WEEK	10034	CAP